



MORRISON HERSHFIELD

REPORT

**Rehabilitation of the Portage Avenue
Twin Bridges over Sturgeon Creek**

Preliminary Engineering Study

Presented to:

**Matt Chislett, P.Eng.
Public Works Department
City of Winnipeg
106-1155 Pacific Avenue
Winnipeg, MB R3E 3P1**



Report No. 1 07 1234.AB

April 2013

\\WIN01FP\DATA1\SHARED\PROJ\W12401300\4 DESIGN\STRUCTURE\REPORT\PORTAGEAVE
REPORT_FINAL_APRIL 8-2013.DOCX

TABLE OF CONTENTS

	Page
1. INTRODUCTION	1
2. DESCRIPTION OF THE STRUCTURE	2
3. CONDITION ASSESSMENT	4
3.1 VISUAL INSPECTION	4
3.2 DECK CONDITION SURVEY	5
4. STRUCTURAL EVALUATION	7
4.1 MATERIAL PROPERTIES	7
4.2 LOADS CONSIDERED	7
4.2.1 Live Load	7
4.2.2 Dead Load	8
4.3 EVALUATION PARAMETER	8
4.3.1 Target Reliability Index	8
4.3.2 Dynamic Load Allowance	9
4.4 ANALYSIS	9
5. RECOMMENDED REHABILITATIVE WORKS	11
5.1 Scope of Work	11
5.2 Regulatory Requirements	12
5.3 Traffic Management Plan	13
5.4 Stakeholder Analysis	15
5.5 Risk Assessment	15
5.6 Utilities	16
5.7 Schedule	16
5.8 Cost Estimate	17

APPENDIX A: CONDITION ASSESSMENT REPORT

APPENDIX B: LIVE LOAD VEHICLES

APPENDIX C: COST ESTIMATE

APPENDIX D: DRAWING



1. INTRODUCTION

The City of Winnipeg retained Morrison Hershfield Limited (MH) to undertake a preliminary engineering study for the rehabilitation of the Portage Avenue Twin Bridges over Sturgeon Creek. The preliminary engineering services include a detailed bridge deck condition survey, detailed visual inspection, structural evaluation and pre-design for rehabilitation of the bridge.

The Portage Avenue Twin Bridges built in 1981 and 1982 provides an important crossing of Sturgeon Creek for the Trans-Canada Highway. It consists of a three-span semi-continuous precast pre-stressed concrete box girder structure over two pedestrian under-bridge walkways and Sturgeon Creek. The existing twin bridge carrying four lanes of traffic in each direction, eastbound and westbound, is separated by a median. The traffic in each direction has a left turning lane beyond the bridge. The bridge has sidewalks on each of the structures.

Corrosion potential measurements and extraction of cores for the detailed bridge deck condition survey were performed by Eng-Tech Consulting Limited between July 16 and 20, 2012. The detailed visual inspection was performed by MH on July 11, 2012 in conformance with the Ontario Structures Inspection Manual.

The bridge currently exhibits evidence of deterioration at the girder ends, ballast wall, traffic barriers and approach slabs. The expansion joints have corroded, lost expansion capacity, the seal is suspected to be leaking and cannot be replaced with the currently reduced expansion gap.

Based on the bridge deck condition survey, detailed visual inspection and structural evaluation findings, this Preliminary Engineering Report includes details to rehabilitate the structure, in order for the structure to have a minimum remaining useful service life of 50 years with a second bridge rehabilitation required in approximately 25 years identified as serving the City's needs.

2. DESCRIPTION OF THE STRUCTURE

The existing bridge is a twin structure carrying four lanes of traffic in each direction, eastbound and westbound, on Portage Avenue over Sturgeon Creek. The structure consists of a three-span (9m – 18m – 9m) semi-continuous precast pre-stressed concrete box cell structure. The bridge is post-tensioned transversely at mid-span in end spans and at two locations in center span. The bridge has a 29° 45' right hand forward skew.

All the existing information is obtained from As Built drawings B178-80-01 to B178-80-65. The existing structure, built in 1980, was designed as per AASHTO 1977 Standard Specifications for Highway Bridges for HS 30-44 (MS 27) Truck.

The total out to out width of the twin-structure is 38.694 m. A variable width median having a maximum width of 3.658 m separates the traffic in opposite directions. The median has a longitudinal joint separating the two structures. The bridge has a 2.438 m wide sidewalk on each structure. The sidewalk has a pedestrian rail at the outside edge and an epoxy-coated reinforced concrete barrier with a top rail on the traffic side. The sidewalk slopes transversely at 1% towards the outside edge and drains into the creek. The sidewalk and median has several embedded utility ducts.

The bridge deck consists of a 100 mm thick epoxy-coated reinforced concrete slab with a 50 mm thick high density concrete overlay.

The substructure consists of concrete abutments and piers on 305 dia. precast concrete piles. The abutment slope protection consists of 300 mm thick grouted rock riprap. There are pedestrian walkways under the bridge on each side of the creek.

The neoprene bearing pads are fixed at the west pier and expansion at the east pier and abutments. The expansion joints are Wabo Maurer strip seal joints.

Since original construction in 1980, there has been several small bridge maintenance contracts executed on the bridge structure involving:

- sidewalk surface concrete repairs on the south sidewalk near midspan,
- abutment seat concrete repairs at the north side of the east and west abutment,
- application of silane sealer to the roadway surface and roadway side and top of traffic barriers,

- installation of a flexible epoxy wearing surface at the curb lanes and shoulders of the bridge deck.

3. CONDITION ASSESSMENT

A detailed visual inspection and bridge deck condition survey was performed to assess the condition of the existing structure. The detailed visual inspection was carried out in conformance with the Ontario Structures Inspection Manual and the bridge deck condition survey consisted of corrosion potential survey and chloride ion testing. The condition assessment report is included in Appendix A.

3.1 VISUAL INSPECTION

This section summarizes the findings of the detailed visual inspection performed by MH on July 11, 2012 in conformance with the Ontario Structures Inspection Manual and follows below in sections that relate to the main structural components.

Approaches: The approach slabs have settled at the ends and have cracks and delaminations at the ballast wall ends. The approach slabs have wheel line rutting and pot holes. The south structure east approach sidewalk has settled and is a tripping hazard. The concrete in west approach sidewalk has delaminated at the expansion joint.

Superstructure: The cells in the box cell girders are inaccessible; therefore, the visible exteriors of the girders were inspected. The concrete in the bottom of a few girders in the north structure at abutment ends have delaminated. The spalled concrete on west abutment seat may be from the deteriorated cast-in-place concrete at girder end caps. Girder 15 from north has rotated south. The median soffit which carries encased conduits has spalled at west pier and has a wide crack at the midspan.

The high density concrete deck overlay has medium cracks over the piers in both structures. There are other minor longitudinal cracks in the overlay. The corrosion potential survey consisted of exposing the top layer of re-bar along the bridge deck by concrete coring. A visual inspection of the condition of the epoxy-coating and re-bar was made at each core hole location. The epoxy-coating and re-bar were all found to be in excellent condition with no sign of coating deterioration or corrosion.

The deck expansion joint at west abutment, north structure, has settled by 15 mm on the bridge deck side. This relative settlement is likely a result of the abutment repairs undertaken in 2008. The strip seal also appears to be leaking.

The sidewalk concrete has hairline cracks and delaminations. The sidewalk expansion joint at west abutment, north structure, has settled. The median has spalled concrete at expansion and construction joints. The traffic side face of concrete barrier in north structure has spalled and exposed re-bars at a few locations.

The existing galvanized handrail is in good condition, however, it does not meet current standards inasmuch as, the picket opening exceeds the current maximum size permitted by 40% and the handrail is not protected from potential snow clearing equipment damage by a concrete curb.

Substructure: The abutment and wingwalls are in good condition. The abutment ballast walls are inaccessible for inspection. However, based on the presence of gravel and soil on the seat of west abutment, north structure, it is suspected that the concrete in the ballast wall and/or girder ends have spalled and deteriorated. The pier shafts are in good condition.

The abutment bearings are in good condition except for a few bearings in the north structure. Bearing 15 from north on the west abutment has rotated in north-south direction and four bearings from north on east abutment have cracks and rust stains. The pier bearings are in good condition with a few hairline cracks.

The architectural end posts are in good condition except for some discoloration and staining on the surfaces.

The service box and wiring servicing the under-bridge pedestrian lighting has deteriorated.

A relatively small section of grouted rip rap on the east creek bank is missing.

3.2 DECK CONDITION SURVEY

The corrosion potential survey consisted of localized half-cell measurements and AC resistance measurements as per the Ontario Structural Rehabilitation Manual (OSRM) for bridges containing epoxy rebars. Calculated AC resistance at individual test locations along the bridge decks were found to be in the range of 0 ohm to 3500 ohms. According to the Ministry of Transportation of Ontario, a calculated AC resistance of less than 1000 ohm is considered to have a high probability of corrosion. Based on the calculated AC resistance results, the south bridge deck has greater resistance than the north bridge deck. This indicates that the resistance to an anodic and cathodic reaction, necessary for corrosion to occur, in the steel is less in the north bridge deck than the south bridge deck. In addition to

the AC resistance measurements, a visual inspection of the condition of the epoxy coating and re-bar was made at each test location. Based on the visual inspection, the epoxy coating and re-bar at the test locations that had resistance less than 1000 ohms appeared to be in similar (excellent) condition to the test locations that had resistance greater than 1000 ohms. Hence, the calculated AC resistance should be interpreted as the likelihood of an anodic and cathodic reaction to occur, however the results bear no weight on the presence and degree of corrosion.

Ground penetrating radar survey results were to be incorporated into the deck condition assessment. The radar testing results of EBA Engineering Consultants Ltd. Report dated May 2012 provided by the City was reviewed for incorporation into this bridge deck condition survey. Regrettably, this could not be done as the radar cover to rebar findings could not be correlated to the actual cover observed in the field by coring and exposing the rebar. Radar results indicated a rebar cover range of 80mm to 200mm with an average of 140mm, whereas the field observed cover range is 75mm to 110mm with an average of 85mm.

The chloride ion test was conducted in accordance with the Canadian Standards Association A23.2-4B – Test Method for Sampling and Determination of Water-Soluble Chloride Ion Content in Hardened Grout or Concrete. Water-soluble chloride ion contents along bridge deck and fascia at the depth of rebar were found to be lower than the critical chloride ion threshold to initiate electrochemical corrosion in steel. The chloride ion content in traffic barriers, sidewalk, median and approach slabs were above or within the threshold limit.

4. STRUCTURAL EVALUATION

The evaluation of the bridge superstructure was carried out in accordance with CAN/ CSA S6-06, Section 14, Evaluation.

4.1 MATERIAL PROPERTIES

The following material properties from As Built drawing B178-80-02 were used in the evaluation of the structure,

Precast pre-stressed concrete box cell girder:

Concrete, f'_c :	35 MPa (5,075 psi)
Black Reinforcing Steel, f_y :	300 MPa (43,000 psi)
Prestressing Steel, f_{pu} :	1860 MPa (270,000 psi)

Structural concrete for deck slab, barrier, sidewalk, and median:

Concrete, f'_c :	30 MPa (4,350 psi)
Epoxy-coated Reinforcing Steel, f_y :	400 MPa (58,000 psi)

4.2 LOADS CONSIDERED

4.2.1 Live Load

The structural capacity of the pre-stressed box cell structure was evaluated for the normal traffic load, i.e., CL-625 truck and lane load for all the three evaluation levels. The structure was also evaluated for alternative loading, AASHTO HSS-25 Truck and other legal truck loads with gross vehicle weights of 36,500 kg, 56,500 kg and 62,500 kg, 81 090 kg Liebherr mobile crane, and overload vehicles with gross vehicle weights of 124,057 kg and 166,080 kg. See Appendix B for vehicle load and axle configuration provided by the City of Winnipeg.

The structure was also analyzed for the design truck load, HS 30 – 44, for the purpose of comparison. The axle loads for HS 30 – 44 were obtained by multiplying the axle loads of a HS-20 truck by 1.5.

The structure was evaluated for four lanes of traffic loads. The sidewalk load is not considered to occur coincident with the maximum traffic loading as per Clause 14.9.5.1.

As the clearance envelope required for the mobile crane and overload vehicles is greater than the normal traffic vehicles, it is assumed that these vehicles will travel in the middle lanes and will be escorted on the bridge one at a time with no other traffic on the bridge. The analysis of these vehicle loads was carried by applying live load factors for Permit Annual (PA) traffic at a speed of less than or equal to 10km/ hr.

4.2.2 Dead Load

The dead load consists of the precast pre-stressed box cell girder, cast-in-place concrete deck, and the superimposed dead loads from high density concrete overlay, sidewalks, median, pedestrian rails, and concrete barrier. The superimposed dead loads were distributed equally to all the girders.

4.3 EVALUATION PARAMETER

4.3.1 Target Reliability Index

The load factors applied to live and dead loads are based on reliability index, β , which is a measure of the level of safety of the structure. The bridge code requires that the new structures be designed for an annual reliability index, $\beta = 3.75$, which corresponds to a 75 year design life $\beta = 3.5$. The new structures are designed for system behavior S2, element behavior E2 and non-inspection level INSP0. However, the existing structures are evaluated using a lower reliability index, as the cost of rehabilitation is much higher than the additional cost incurred in new construction based on higher reliability index.

The existing structure is evaluated for,

System behavior:	S2
Element behavior:	E2
Inspection level:	INSP1
Target reliability index, β :	3.50

The live and dead load factors are as follows;

Traffic	Span	Load Factors		
		Dead Load, α_D		Live Load, α_L
		D1	D2	LL
Normal Traffic or Alternative Loading	Short	1.09	1.18	2.20
	Other	1.09	1.18	1.63
Permit Annual (PA)	Short	1.09	1.18	1.78
	Other	1.09	1.18	1.53

D1 Factory produced concrete

D2 Cast-in-place concrete and other non-structural concrete

Short span load factors are used for moment effects in spans up to 10 m and for shear effects in spans up to 6 m.

4.3.2 Dynamic Load Allowance

A dynamic load of 0.30 was used for normal traffic and alternative loading and 0.09 (30% x 0.30) for permit annual traffic.

4.4 ANALYSIS

The structure was analyzed as a semi-continuous structure with girder and wet deck loads acting on simple spans and superimposed dead loads and live loads acting on continuous spans.

The structural analysis was based on CSA S6-06 Section 5 with the ULS load combination applied per meter width of the girder. The flexural and shear capacity of the box cell girders were calculated along the mid spans and ends in accordance with Section 8 and compared with the load effects. The girders were considered to be composite with bridge deck at the piers. The structure is adequate in flexure and shear for normal traffic and alternative loading and overload vehicles travelling under controlled supervision and speed. The results of the structural evaluation are included in Appendix C.

Location	Moment			Shear		
	Mf kN-m	Mr kN-m	Mr / Mf	Vf kN	Vr kN	Vr / Vf
Mid Span – Short Span	472	798	1.69	--	--	--
Mid Span – Long Span	1085	1314	1.21	--	--	--
Supports	-820	-914	1.12	499	1013	2.032

5. RECOMMENDED REHABILITATIVE WORKS

5.1 Scope of Work

Considering the findings of the detailed visual inspection, structural evaluation and bridge deck condition survey the following rehabilitative work is recommended, in order for the structure to have a minimum remaining useful service life of 50 years with a second bridge rehabilitation required in approximately 25 years as has been identified as serving the City's needs:

- Demolish and remove approach slabs, pavement slabs, approach sidewalk, ballast wall, handrail, expansion joints, traffic barriers and deteriorated girder ends.
- Construct new girder ends, ballast wall, approach slabs, pavement slabs, expansion joints, and approach sidewalk.
- Construct new traffic barrier, aluminum handrail and handrail curb.
- Prepare sidewalk surface and pour concrete topping to reverse the transverse slope with 1% cross-fall towards the barrier.
- Prepare median surface and construct safety curb median.
- Remove remaining epoxy overlay, prepare surface and treat concrete bridge deck surface/cracks using Methacrylate (MMA) Technology.
- Construct roadway expansion joint.
- Modify utility conduit as required.
- Apply silane sealer to surface of traffic barriers, median, bridge sidewalk, end-posts and approach slabs.
- Miscellaneous works including, but not limited to; under-bridge lighting repair, rip rap repair, under-bridge sidewalk repair, etc.

Preliminary design drawings for the rehabilitative works can be found in Appendix D.

The long-term durability of the bridge is considered to be enhanced by not using expansion joints at the abutment ends, by converting the abutment into a semi-integral abutment. Changing the abutments to function as semi-integral was investigated. The investigation indicated that due to the presence of utility ducts in the median and sidewalk areas it was deemed impractical to convert the abutments to function as semi-integral. Therefore, it is recommended that the expansion joints be replaced at the current location in combination

with a roadway expansion joint leading to both approaches to restore the bridge's expansion capacity and waterproofness.

The possibility of widening the bridge sidewalk utilizing the existing structure was investigated and determined to be feasible. However, the decorative bridge end posts attached to the abutment wingwalls would need to be removed in order to widen the sidewalk over the abutments. There is no desire to remove the bridge end posts and thus no advantage to only widen the sidewalk on the bridge so the notion of sidewalk widening was not pursued any further. Moreover, the bridge end-posts are in good condition, and not requiring any repair work.

No property acquisition or temporary construction easements are required to facilitate the recommended rehabilitative works. All work and construction access will take place on City owned property.

The recommended bridge rehabilitative design complies with the City of Winnipeg Universal Design Policy and Standards.

5.2 Regulatory Requirements

Regulatory body approvals are required for the proposed bridge rehabilitative works.

Approval by the Department of Fisheries and Oceans (DFO) consists of a submission of a Notification Form as the proposed rehabilitative works is considered "Bridge Maintenance" and therefore work can be performed under an Operational Statement and formal application is not required. The Notification Form should be submitted once the detailed design is completed. When the Notification Form has been completed, submitted to DFO and DFO has acknowledged receipt of the form, approval has been obtained.

A City of Winnipeg Waterways Bylaw Permit is required prior to commencing work on-site. The Application Form for the Waterways Bylaw Permit should be submitted once the detailed design is completed.

Detail design drawings should be submitted to Underground Structures allowing six (6) weeks for comments.

5.3 Traffic Management Plan

Portage Avenue at the Sturgeon Creek Bridge handles approximately 53,000 vehicles per day. The peak period occurs for westbound traffic from 4:00 to 5:00 p.m. with almost 2,900 vehicles crossing the bridge.

Pedestrian traffic will be maintained on at least one side at all times and the under-bridge sidewalks will be also be maintained at all times.

The following considerations will be analyzed for each of the vehicular traffic management options described below:

- 1) Traffic Service- How will traffic be impacted by the closure?
- 2) Cost- What will the cost implication be?
- 3) Safety- How is safety impacted?
- 4) Quality of Construction- How will the final product be affected?
- 5) Duration of Construction- How long will construction take?
- 6) Potential for Schedule Acceleration- Can the contract be accelerated to minimize disruption?
- 7) Risk- Is any additional risk added?

The following options will be discussed for staging the construction and accommodating traffic:

- 1) Half at-a-time Construction - This option involves closing four lanes of traffic and constructing one half of the bridge at a time. All traffic would use the 4 lanes on the opposite half of the bridge. Two sub-options include:
 - a. Traffic using 2 lanes per direction 24 hours a day;
 - b. Reversing one lane during peak periods (ie. 3 lanes in peak direction, 1 lane in the opposite direction);
- 2) Lane at-a-time Construction - This option involves closing two lanes of traffic in one direction and constructing the bridge one lane at a time. On the same half as construction is taking place, traffic would have 2 lanes while on the opposite half, traffic would still have 4 lanes. Two sub-options include:
 - a. Two lanes in one direction, 4 lanes in the opposite direction 24 hours a day;
 - b. Reversing one lane during peak periods (3 lanes in each direction).
- 3) Another option looked at is to construct a temporary widening to allow 5 lanes of traffic. This option has been deemed not possible for two reasons. One is because of the need to maintain pedestrian traffic on the open side. The other is for constructability reasons; the existing shoulder and median barriers on the bridge contain steel dowels that cannot be practically removed and replaced.

Temporary median crossovers would be constructed either side of the bridge wherever traffic is required to cross the median. Traffic in both directions would be returned to 4 lanes per direction prior to the next signalized intersection.

After analyzing the pros and cons of each option as shown in Table 1, the best method of staging construction will be to close one half at a time and accommodate 2 lanes in each direction on the other half. While traffic will be disrupted, this option provides for the shortest duration of disruption and also provides for the greatest opportunity for an accelerated completion schedule. Similar traffic management plans have been used successfully on Portage Avenue and Disraeli Freeway, for example, in the past.

TABLE 1- Evaluation of Traffic Management Plans
(0=Worst ; 3=Best)

OPTIONS		A. Traffic Service	Score	B. Cost	Score	C. Safety	Score	D. Quality of Construction	Score
1a.	Half at-a-time Construction 2 lanes per direction	- Poor level of service during peak hours	1	- Least cost	3	- Safest; workers completely separated from traffic	3	- best potential for high quality finished product	3
1b.	Half at-a-time Construction Reversing one lane	- Improves peak direction - Traffic in opposite direction fails with only 1 lane UNACCEPTABLE OPTION DUE TO FAILING LEVEL OF SERVICE	2	/		/		/	
2a.	Lane at-a-time Construction 2 lanes in one direction, 4 lanes in opposite direction	- Poor level of service in peak direction for side under construction - Traffic unaffected in opposite direction	2	- As much as a 50% increase in cost	1	- Less safe; workers crossing and working around traffic	1	- potential for poor quality increased due to many construction stages and resulting construction	1
2b.	Lane at-a-time Construction Reversing one lane	- Improves peak direction - Traffic on both sides of bridge now affected	3	- Over 50% increase in cost	0	- Less safe; workers crossing and working around traffic	1	- potential for poor quality increased due to many construction stages and	1

OPTIONS		E. Duration of Construction	Score	F. Potential for Schedule Acceleration	Score	G. Risk	Score	Total Score
1a.	Half at-a-time Construction 2 lanes per direction	- shortest construction period (one construction season)	3	- provides for good potential to accelerate construction	3	- lowest overall project risk	3	19
1b.	Half at-a-time Construction Reversing one lane	/		/		/		UNACCEPTABLE
2a.	Lane at-a-time Construction 2 lanes in one direction, 4 lanes in opposite direction	- construction period increased to two construction seasons	1	- unlikely to accelerate schedule due to concrete curing time between the many construction stages being the critical path	1	- increased risks due to multi-stage	1	8
2b.	Lane at-a-time Construction Reversing one lane	- construction period increased to two construction seasons	1	- unlikely to accelerate schedule due to concrete curing time between the many construction stages being the critical path	1	- increased risks due to multi-stage	1	8

Steps to reduce the impact on traffic flow during construction shall be further developed and investigated during Detailed Design. These steps should include, but not be limited to:

- modification to signal timings;
- ensuring that no construction occurs along alternate routes at the same time (i.e. Ness Avenue);
- implementation of a communication plan to notify drivers of anticipated delays and alternate routes;



- incorporate into the construction contract documents incentives for the Contractor to lessen the impact to traffic by completing early or by other means.

5.4 Stakeholder Analysis

A number of stakeholders have been identified as having a role and/or being affected by/interested in the Project. The following table summarizes the stakeholders, level of involvement, and how they are interested/affected.

Stakeholder Analysis Table		
Stakeholder	Role in Decision Making	How Stakeholder is Affected By/Interested in the Project
Public Works	I, C, PD, A, R, S	Project success; cost/quality/time; project deliverable accountability
DFO	R	Regulatory accountability
Manitoba Hydro	I, C, PD, S	Protection/Safety of electrical cable in bridge sidewalk
MTS	I, C, PD, S	Protection of communication cables in bridge sidewalk
Transit	I, C	Maintenance of Transit stops during lane closures
General Public	G	Pedestrian and vehicular traffic diversions
Local City Councilor	G	Project information
City Parks	G	Project information
City Waterways	C, S	Regulatory accountability
Legend:		
NI:	No Involvement	A: Accountable
G:	General Communication	R: Review Required
I:	Input Required	S: Sign-off/Approval Required
C:	Consulted	
PD:	Participant in Planning & Decision Making	

5.5 Risk Assessment

For this Project, a risk response strategy for identified high probability/high impact risks is presented as follows:

<u>Key Risk</u>	<u>Potential Impact</u>	<u>Risk Response Strategy</u>
1. Existing conditions are not as expected	Schedule delay Cost increase	Include flexibility into design details and develop a contingency plan to mitigate.
2. Estimated cost of work too low	Schedule delay Budget increase	Review estimates with experienced contractors and include appropriate contingencies.
3. Working around MTS/ Hydro ducts proves to be not feasible	Schedule delay Cost increase Reduced quality	Communicate with utilities early in the design and develop contingency plan to leave ducts in place.
4. Permitting not received or late	Schedule delay Cost increase	Communicate with regulatory agencies early and maximize float time in schedule for permitting.
5. Weather impacts construction	Schedule delay Cost increase Reduced quality	Commence construction early in spring and provide incentives for contractor to finish early.

5.6 Utilities

Located within both sidewalks and the median on the bridge are conduits for use by MTS and Manitoba Hydro. Based on current discussions with MTS and MB Hydro, it is anticipated that during demolition and replacement of the sidewalk approach slab, complete with ducts, all cables contained within the ducts will be taken out of service. Following completion of construction the utilities will replace the cables on the bridge from the closest manholes and re-energize the system. Presently, MTS and MB Hydro are investigating options for facilitating construction around the sidewalk approach slabs. The strategy for dealing with the conduits will be finalized during detailed design.

Contact information is as follows:

MB Hydro: Terry McCarthy – Phone: 204-360-4127

MTS: Michael Janz – Phone: 204-941-4672

5.7 Schedule

We estimate the following time schedule for the project.

Activity	Time Frame
Complete Detailed Design	November 2013
Council Approval of Capital	December 2013
Tender and Award	December 2013-January 2014
Construction first structure	April 2014-July 2014
Construction second structure	August 2014-October 2014

We anticipate the award of one Bid Opportunity package however, delivery of expansion joint materials could have an impact on the schedule if the period between award and start of construction is shortened.

5.8 Cost Estimate

The Class 3 estimated total project cost for the proposed bridge rehabilitative works is \$4,000,000.00 as given in the following table. The cost estimate does not include GST, and has an allowance for contingencies, City overheads, engineering and testing and other project expenses.

Item No.	Bid Item	Estimated Cost
1	Mobilization/Demob	\$ 300,000.00
2	Traffic Control	\$ 50,000.00
3	Structural Removals	\$ 310,000.00
4	Excavation	\$ 30,000.00
5	Backfill - granular	\$ 60,000.00
6	Structural Concrete	
	a) approach slabs	\$ 200,000.00
	b) traffic barriers	\$ 75,000.00
	c) median/sidewalk	\$ 100,000.00
	d) ballast wall	\$ 100,000.00
	e) girder ends	\$ 50,000.00
	f) approach sidewalk	\$ 25,000.00
	g) roadway pavement	\$ 300,000.00
7	Expansion Joints	\$ 400,000.00
8	Bridge Deck Sealing	\$ 70,000.00
9	Reinforcing - Black	\$ 75,000.00
10	Reinforcing - S/S	\$ 200,000.00
11	Galvanic Protection	\$ 50,000.00
12	Aluminum Pedestrian Handrail	\$ 50,000.00
13	Electrical	\$ 25,000.00
14	Rip Rap	\$ 25,000.00
15	Misc. Work	\$ 200,000.00
16	Repair Underbridge Sidewalk	\$ 50,000.00
17	Guardrail	\$ 20,000.00
	Sub-Total	\$ 2,765,000.00
	CONTINGENCY (15%)	\$ 414,750.00
	TOTAL CONSTRUCTION	\$ 3,179,750.00
	City overheads, engineering, testing and other project expenses	\$ 820,250.00
	TOTAL ESTIMATED PROJECT COST	\$ 4,000,000.00

It is estimated that the cash flow forecast for the total project cost would be \$250,000 in 2013 and 3,750,000 in 2014.

APPENDIX A: CONDITION ASSESSMENT REPORT



MORRISON HERSHFIELD

August 29, 2012

Project No.: W12401300

Matt Chislett, P.Eng
City of Winnipeg
Public Works Department
106-1155 Pacific Avenue
Winnipeg, MB R3E 3P1

Dear Mr. Chislett:

**Re: PORTAGE AVENUE TWIN BRIDGES OVER STURGEON CREEK
BRIDGE DECK CONDITION SURVEY AND DETAILED VISUAL INSPECTION**

We are pleased to present the following enclosed documents in relation to the bridge deck condition survey and detailed visual inspection conducted on the Portage Avenue Twin Bridges over Sturgeon Creek:

- ENG-TECH Consulting Limited report on the corrosion potential survey and chloride ion testing program.
- Ontario Bridge Management System Bridge Inspection Forms.

Bridge Deck Condition Survey

To summarize, the corrosion potential survey results bear no weight on the presence and degree of corrosion, based on the visual inspection of epoxy rebar at the test locations. Measured chloride ion content at the depth of rebar along the bridge deck and fascia are lower than the critical chloride ion threshold, while the traffic barriers, sidewalk, median and approach slabs are above the critical chloride ion threshold.

Detailed Visual Inspection

The detailed visual inspection was performed by Mr. Bill Ebenspanger and Mr. Hao Zhang on July 11, 2012 in conformance with the Ontario Structures Inspection Manual.

Performance deficiencies noted for the following elements include:

- Abutments, Ballast Walls – Suspected disintegration of concrete.
- Approaches, Approach Slabs – Rough riding surface, wheel rutting, potholes, wide cracks and surface delaminations.
- Barriers, Railing Systems – Inadequate gap to accommodate expansion.
- Girders, Ends – Suspected loss of concrete.
- Decks, Deck top – Loss of protection due to presence of medium cracks.

- Joints, Armouring – Loss of expansion capacity and seal replacement capability.
- Joints, Seals – suspected leaking seals.

Recommended Bridge Rehabilitation Works

Considering the results of the Bridge Deck Condition Survey and Detailed Visual Inspection and in order to achieve a 25 year service life before further rehabilitation can be expected, it is recommended that a preliminary design for rehabilitative works be developed to address deficiencies noted for the following bridge elements:

- Ballast walls
- Approach slabs
- Barriers
- Girder ends
- Deck top
- Median
- Joints
- Sidewalk

Please contact me at 204.977.8370 if you have any questions or require further information.

Yours truly,
Morrison Hershfield Limited



Bill Ebenspanger, P.Eng.

Element Data

Element Group:	Abutments				Length:	--
Element Name:	Abutment Walls				Width:	43.54m
Location:	East & West Abutments				Height:	1.75m
Description:	Abutment Seats				Count:	2
Material:	Concrete Finned Surface				Total Quantity:	152 sq.m.
Element type:	Cast-in-Place Reinforced				Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/>	Moderate <input checked="" type="checkbox"/>	Severe <input type="checkbox"/>		Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor	
	Sq.m.		152			
Comments:	<ul style="list-style-type: none"> Refer to Photo 1 					
Performance Deficiencies:						
<ul style="list-style-type: none"> None 						
Recommended Work:						
<p style="text-align: right;">None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/></p>						

Element Group:	Abutments				Length:	--
Element Name:	Ballast Walls				Width:	43.54m
Location:	East & West Abutments				Height:	.9m
Description:	Backwall				Count:	2
Material:	Concrete				Total Quantity:	80 sq.m.
Element type:	Cast-in-Place Reinforced				Not Inspected:	<input checked="" type="checkbox"/>
Environment:	Benign <input type="checkbox"/>	Moderate <input checked="" type="checkbox"/>	Severe <input type="checkbox"/>		Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor	
	Sq.m.					
Comments:	<ul style="list-style-type: none"> Limited access – gravelly material noted on West abutment seat North structure. Refer to Photo 2. 					
Performance Deficiencies:						
<ul style="list-style-type: none"> Suspected disintegration of concrete back wall and/or girder ends due to leaking expansion joints. 						
Recommended Work:						
<ul style="list-style-type: none"> Further investigation required. <p style="text-align: right;">None > 10 Yrs <input type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input checked="" type="checkbox"/> Urgent <input type="checkbox"/></p>						

Element Data

Element Group:	Abutments					Length:	--
Element Name:	Bearings					Width:	--
Location:	East & West Abutments					Height:	--
Description:	Expansion Bearing Pad					Count:	60
Material:	Neoprene					Total Quantity:	60
Element type:	Expansion Bearing Pad					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/> Moderate <input checked="" type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Each		51	6	3		
Comments:	<ul style="list-style-type: none"> Bearings 1 to 4 from North at East Abutment cracked and rusted. Refer to Photo 3. West Abutment - bearing 15 from North rotated N-S. Refer to Photo 4. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> None-uniform contact of bearing with bearing seat. Excessive inclination of bearing. 							
Recommended Work:							
<ul style="list-style-type: none"> Regular monitoring of bearings. 							
None>10 Yrs <input type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input checked="" type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Abutments					Length:	6m
Element Name:	Wingwalls					Width:	--
Location:	East & West Abutments					Height:	1.5m
Description:	Four Wingwalls					Count:	4
Material:	Concrete					Total Quantity:	18 sq.m.
Element type:	Cast-in-Place Reinforced					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/> Moderate <input checked="" type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		18				
Comments:	<ul style="list-style-type: none"> Refer to Photo 5. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> None 							
Recommended Work:							
None>10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Data

Element Group:	Approaches					Length:	8.66m
Element Name:	Approach Slabs					Width:	14.63m
Location:	East & West Abutments					Height:	.25m
Description:	Cantilever Slab					Count:	4
Material:	Concrete					Total Quantity:	500 sq.m.
Element type:	Cast-in-Place Reinforced					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		484	8	8		
Comments:	<ul style="list-style-type: none"> • Wheel Line Rutting - 4 routed cracks in all slabs. • Westbound Slabs – asphalt filled potholes. • Refer to Photo 6. • Settlement at ends of all slabs and cracking and delamination observed at back wall ends. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> • Rough riding surface, wheel line rutting, potholes, wide cracks and surface delaminations. 							
Recommended Work:							
<ul style="list-style-type: none"> • Replace approach slabs. 							
None > 10 Yrs <input type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input checked="" type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Approaches					Length:	8.66m
Element Name:	Curb / Gutters					Width:	--
Location:	East & West Approaches					Height:	--
Description:	Traffic Barrier / Median Curb					Count:	8
Material:	Concrete					Total Quantity:	70m
Element type:	Cast-in-Place Reinforced					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	M		68	1	1		
Comments:	<ul style="list-style-type: none"> • West Approach Slab – Eastbound curb spalled. • Refer to Photo 7. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> • None 							
Recommended Work:							
None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Data

Element Group:	Approaches					Length:	6.4m
Element Name:	Sidewalk					Width:	1.98m
Location:	East & West Abutments					Height:	0
Description:	Pedestrian Sidewalk					Count:	4
Material:	Concrete					Total Quantity:	50 sq.m.
Element type:	Cast-in-Place Reinforced					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		48	1	1		
Comments:	<ul style="list-style-type: none"> • South Structure – West Slab delaminated near expansion joint. • South Structure – East corner settled, tripping concern. • Refer to Photos 8 & 9. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> • Excessive settlement and delaminations. 							
Recommended Work:							
<ul style="list-style-type: none"> • Replace sidewalk approach slab. • Urgently repair tripping concern. 							
<p style="text-align: right;">None > 10 Yrs <input type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input checked="" type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/></p>							

Element Group:	Barriers					Length:	51.5m
Element Name:	Interior Barrier / Parapet Walls					Width:	--
Location:	Shoulders					Height:	.813m
Description:	Traffic Barrier					Count:	2
Material:	Concrete					Total Quantity:	84 sq.m.
Element type:	Cast-in-Place Reinforced					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		78	4	2		
Comments:	<ul style="list-style-type: none"> • North Structure – Concrete spalling and exposed rebar. • Refer to Photo 10. 						
Performance Deficiencies:							
None							
Recommended Work:							
<p style="text-align: right;">None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/></p>							

Element Data

Element Group:	Barriers				Length:	51.5m
Element Name:	Barrier Exterior				Width:	--
Location:	Shoulders				Height:	.676m
Description:	Back of Barrier				Count:	2
Material:	Concrete				Total Quantity:	70 sq.m.
Element type:	Cast-in-Place Reinforced				Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/>	Moderate <input checked="" type="checkbox"/>	Severe <input type="checkbox"/>		Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor	
	Sq.m.		70			
Comments:	<ul style="list-style-type: none"> Refer to Photo 11. 					
Performance Deficiencies:						
<ul style="list-style-type: none"> None 						
Recommended Work:						
None>10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>						

Element Group:	Barriers				Length:	51.5m
Element Name:	Medlan Barrier				Width:	4
Location:	Median				Height:	--
Description:	Median Curb				Count:	1
Material:	Concrete				Total Quantity:	200 sq.m.
Element type:	Cast-in-Place Reinforced				Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/>	Moderate <input type="checkbox"/>	Severe <input checked="" type="checkbox"/>		Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor	
	Sq.m.		198	1	1	
Comments:	<ul style="list-style-type: none"> Concrete spalls at Construction Joints and Expansion Joints. Refer to Photo 12. 					
Performance Deficiencies:						
<ul style="list-style-type: none"> None 						
Recommended Work:						
None>10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>						

Element Data

Element Group:	Barriers				Length:	51.5m
Element Name:	Handrailing				Width:	--
Location:	North & South Edges of Bridge				Height:	--
Description:	Pedestrian Handrail				Count:	2
Material:	Galvanized Steel				Total Quantity:	103m
Element type:	Picket & Post Railing				Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/>	Moderate <input checked="" type="checkbox"/>	Severe <input type="checkbox"/>		Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor	
	M		103			
Comments:	<ul style="list-style-type: none"> Refer to Photo 11. 					
Performance Deficiencies:						
<ul style="list-style-type: none"> None 						
Recommended Work:						
None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>						

Element Group:	Barriers				Length:	51.5m
Element Name:	Railing Systems				Width:	--
Location:	Top of Shoulder Barriers				Height:	--
Description:	Traffic Barrier Rail				Count:	2
Material:	Aluminum				Total Quantity:	103m
Element type:	Barrier Rail				Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/>	Moderate <input type="checkbox"/>	Severe <input checked="" type="checkbox"/>		Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor	
	M		101	1	1	
Comments:	<ul style="list-style-type: none"> Expansion capacity exceeded at comers (typical). Refer to Photo 13. 					
Performance Deficiencies:						
<ul style="list-style-type: none"> Inadequate gap to accommodate expansion in railing. 						
Recommended Work:						
<ul style="list-style-type: none"> Restore expansion gap. 						
None > 10 Yrs <input type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input checked="" type="checkbox"/> Urgent <input type="checkbox"/>						

Element Data

Element Group:	Girders					Length:	2m
Element Name:	Ends					Width:	1.219m
Location:	One Metre off Back Wall					Height:	.610m
Description:	Precast Box Girders					Count:	30
Material:	Precast Concrete					Total Quantity:	146 sq.m.
Element type:	Pre-stressed Concrete					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/> Moderate <input checked="" type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		136	6	4		
Comments:	<ul style="list-style-type: none"> • End spalling and bottom delaminations – North Girders East & West Abutments. • Refer to Photos 14 & 15. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> • Suspected loss of concrete at girder ends. 							
Recommended Work:							
<ul style="list-style-type: none"> • Regular monitoring required. 							
<p style="text-align: right;">None>10 Yrs <input type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input checked="" type="checkbox"/> Urgent <input type="checkbox"/></p>							

Element Group:	Girders					Length:	33.8m
Element Name:	Middle					Width:	1.219m
Location:	Over Sturgeon Creek					Height:	.610
Description:	Precast Box Girders					Count:	30
Material:	Precast Concrete					Total Quantity:	2,473 sq.m.
Element type:	Pre-stressed Concrete					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		2,473				
Comments:	<ul style="list-style-type: none"> • Girder 15 from North - rotated South by 15 mm. • Refer to Photo 16. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> • Rotated girder. 							
Recommended Work:							
<ul style="list-style-type: none"> • Regular monitoring required. 							
<p style="text-align: right;">None>10 Yrs <input type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input checked="" type="checkbox"/> Urgent <input type="checkbox"/></p>							

Element Data

Element Group:	Decks					Length:	35.8m
Element Name:	Deck Top					Width:	38.7m
Location:	Over Sturgeon Creek					Height:	.10m
Description:	Exposed Bridge Deck					Count:	--
Material:	Concrete					Total Quantity:	1,385 sq.m.
Element type:	Cast-in-Place Reinforced					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		1,355	30	0		
Comments:	<ul style="list-style-type: none"> • Medium cracks over piers westbound. Minor longitudinal cracks. • Cannot inspect deck under barriers and sidewalk. • Concrete scaling in gutter westbound. • Refer to Photos 17 & 18. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> • Loss of protection due to medium cracks. 							
Recommended Work:							
<ul style="list-style-type: none"> • Crack sealing. 							
None > 10 Yrs <input type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input checked="" type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Decks					Length:	35.8m
Element Name:	Soffit Exterior					Width:	1.71m
Location:	Cantilevered Overhang & Fascia					Height:	--
Description:						Count:	--
Material:						Total Quantity:	60 sq.m.
Element type:						Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/> Moderate <input checked="" type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		57	2	1		
Comments:	<ul style="list-style-type: none"> • South Structure – West-span wide crack, East-span spall, Mid-span abandoned electrical box rusted. • North Structure – Mid-span 2 wide cracks. Hairline to narrow longitudinal cracks. • Refer to Photo 19. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> • None 							
Recommended Work:							
None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Data

Element Group:	Embankment & Streams					Length:	
Element Name:	Embankments					Width:	
Location:	East & West Embankments					Height:	
Description:	Grassed Slopes					Count:	
Material:	Sod					Total Quantity:	4
Element type:	Grassed Slopes					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	End		4				
Comments:	<ul style="list-style-type: none"> Refer to Photo 20. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> None 							
Recommended Work:							
None>10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Embankments & Streams					Length:	
Element Name:	Slope Protection					Width:	
Location:	East & West Banks					Height:	
Description:	Rip Rap					Count:	
Material:	Grouted Rock					Total Quantity:	2
Element type:	Grouted Rip Rap					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Each		2				
Comments:	<ul style="list-style-type: none"> Refer to Photo 21. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> None 							
Recommended Work:							
None>10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Data

Element Group:	Embankments & Streams					Length:	
Element Name:	Streams & Waterways					Width:	
Location:	Sturgeon Creek					Height:	
Description:	Creek Bottom					Count:	
Material:	Random Rip Rap					Total Quantity:	1
Element type:	Rock Rip Rap					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Each		1				
Comments:	<ul style="list-style-type: none"> Refer to Photo 22. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> None 							
Recommended Work:							
<p style="text-align: right;">None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/></p>							

Element Group:	Foundations					Length:	
Element Name:	Below Ground					Width:	
Location:	Piers & Abutments					Height:	
Description:	Footing & Precast Piles					Count:	
Material:	Concrete					Total Quantity:	
Element type:	Cast-in-Place Reinforced & Precast					Not Inspected:	<input checked="" type="checkbox"/>
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	--						
Comments:	Limited inspection – unremarkable.						
Performance Deficiencies:							
<ul style="list-style-type: none"> None 							
Recommended Work:							
<p style="text-align: right;">None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/></p>							

Element Data

Element Group:	Joints				Length:	40m
Element Name:	Armouring				Width:	--
Location:	Median & East & West Abutments				Height:	--
Description:	Single Strip Seal Joint				Count:	6
Material:	Steel				Total Quantity:	240m
Element type:	Extrusion				Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/>	Moderate <input type="checkbox"/>	Severe <input checked="" type="checkbox"/>		Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor	
	M		240			
Comments:	<ul style="list-style-type: none"> North Structure – Expansion Joint settled 15 mm on Bridge’s side, West Abutment. Refer to Photos 23, 24, & 25. 					
Performance Deficiencies:						
<ul style="list-style-type: none"> Loss of expansion capacity and seal replacement capability. 						
Recommended Work:						
<ul style="list-style-type: none"> Restore expansion capacity. 						
None > 10 Yrs <input type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input checked="" type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>						

Element Group:	Joints				Length:	Each
Element Name:	Seals				Width:	--
Location:	Median & East & West Abutments				Height:	--
Description:	Single Strip Seal				Count:	3
Material:	Neoprene Rubber				Total Quantity:	
Element type:	Strip Seal				Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/>	Moderate <input type="checkbox"/>	Severe <input checked="" type="checkbox"/>		Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor	
	Each		3			
Comments:	<ul style="list-style-type: none"> Appears to be leaking at West Abutment, North Side. Refer to Photos 23, 24, & 25. 					
Performance Deficiencies:						
<ul style="list-style-type: none"> Suspected leaking seal. 						
Recommended Work:						
<ul style="list-style-type: none"> Regular monitoring. 						
None > 10 Yrs <input type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input checked="" type="checkbox"/> Urgent <input type="checkbox"/>						

Element Data

Element Group:	Piers					Length:	--
Element Name:	Bearings					Width:	--
Location:	Pier 2 and Pier 3					Height:	--
Description:	Bearing Pads					Count:	120
Material:	Neoprene Rubber					Total Quantity:	
Element type:	Bearing Pad					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Each		120				
Comments:	<ul style="list-style-type: none"> Hairline cracks observed. Refer to Photo 26. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> None 							
Recommended Work:							
<p style="text-align: right;">None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/></p>							

Element Group:	Piers					Length:	--
Element Name:	Shafts					Width:	--
Location:	No. 2 and No. 3					Height:	--
Description:	Pier Shaft					Count:	2
Material:	Concrete					Total Quantity:	130 sq.m.
Element type:	Cast-in-Place Reinforced					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		128	1	1		
Comments:	<ul style="list-style-type: none"> Delamination on East Pier Cap, South End. Refer to Photo 27. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> None 							
Recommended Work:							
<p style="text-align: right;">None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/></p>							

Element Data

Element Group:	Sidewalks / Curbs					Length:	35.8m
Element Name:	Sidewalks and Medians					Width:	2.438m
Location:	North & South Side of Bridge					Height:	0
Description:	Pedestrian Sidewalk					Count:	2
Material:	Concrete					Total Quantity:	175 sq.m.
Element type:	Cast-in-Place Reinforced					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/> Moderate <input type="checkbox"/> Severe <input checked="" type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		171	2	2		
Comments:	<ul style="list-style-type: none"> • South Structure – Delamination / hairline cracks / failed trial crack repairs. • North Structure – Hairline cracks / Expansion Joint settled West Abutment. • Refer to Photos 28 & 29. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> • None 							
Recommended Work:							
None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Sidewalks / Curbs					Length:	45m
Element Name:	Sidewalks and Medians					Width:	2.4m
Location:	East and West Banks					Height:	--
Description:	Under-Bridge Sidewalk					Count:	2
Material:	Concrete					Total Quantity:	108 sq.m.
Element type:	Cast-in-Place Reinforced					Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Severe <input type="checkbox"/>					Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	Sq.m.		90	12	6		
Comments:	<ul style="list-style-type: none"> • Areas of delamination and spalling. • Refer to Photos 30 & 31. 						
Performance Deficiencies:							
<ul style="list-style-type: none"> • None 							
Recommended Work:							
None > 10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Barriers				Length:	6m
Element Name:	Posts				Width:	.25m
Location:	Four Corners of Bridge				Height:	4.22m
Description:	Monument Wall End Post Extensions				Count:	2
Material:	Concrete				Total Quantity:	150 sq.m.
Element type:	Cast-in-Place Reinforced				Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/>	Moderate <input checked="" type="checkbox"/>	Severe <input type="checkbox"/>		Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor	
			150			
Comments:	<ul style="list-style-type: none"> Refer to Photo 32. 					
Performance Deficiencies:						
<ul style="list-style-type: none"> None 						
Recommended Work:						
<p style="text-align: right;">None>10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/></p>						

Element Group:	Decks				Length:	35.8m
Element Name:	Soffit – Inside Boxes				Width:	1.25m
Location:	Median				Height:	--
Description:	Encased Conduit / Med. Expansion Joint				Count:	--
Material:	Concrete				Total Quantity:	45 sq.m.
Element type:	Cast-in-Place Reinforced				Not Inspected:	<input type="checkbox"/>
Environment:	Benign <input type="checkbox"/>	Moderate <input checked="" type="checkbox"/>	Severe <input type="checkbox"/>		Perform. Deficiencies	Maint. Needs
Condition Data:	Units	Exc.	Good	Fair	Poor	
	Sq.m.		42	2	1	
Comments:	<ul style="list-style-type: none"> Spall at West Pier and wide crack at Midspan. Refer to Photos 33 & 34. 					
Performance Deficiencies:						
<ul style="list-style-type: none"> None 						
Recommended Work:						
<p style="text-align: right;">None>10 Yrs <input checked="" type="checkbox"/> 6-10 Yrs <input type="checkbox"/> 1-5 Yrs <input type="checkbox"/> Now < 1 Year <input type="checkbox"/> Urgent <input type="checkbox"/></p>						



Photo 1 – west abutment



Photo 2 – west abutment gravelly material on seat



Photo 3 – east abutment bearing 4 from north



Photo 4 – west span girder 15 from north rotated




Photo 5 – wingwall



Photo 6 – east approach looking south



Photo 7 – west approach looking south



Photo 8 – south sidewalk west end



Photo 9 – south sidewalk east end trip hazard



Photo 10 – north barrier



Photo 11 – south sidewalk looking east



Photo 12- deck looking east



Photo 13 – north traffic back wall at west expansion joint



Photo 14 – NW bearing and delamination at bottom of girder



Photo 15 – NW bearing and delamination at bottom of girder



Photo 16 – middle span girders



Photo 17 – deck cracking



Photo 18 – deck scaling



Photo 19 – middle span south extension soffit



Photo 20 – north elevation from NW corner




Photo 21- slope protection



Photo 22 – creek riprap



Photo 23 – west expansion joint looking south



Photo 24 – east expansion joint looking south



Photo 25 – median expansion joint



Photo 26 – east pier, east bearing 16 from north crack




Photo 27 – piers



Photo 28 – north sidewalk west end minor settlement



Photo 29 – north sidewalk west end minor settlement



Photo 30 – under-bridge sidewalk



Photo 31 – under-bridge sidewalk delamination



Photo 32 - endpost



Photo 33 – middle soffit above west pier



Photo 34 – midspan crack



#6 - Marion Street, Winnipeg, Manitoba, R3J 0K4
Phone: (204) 233-1694 Fax: (204) 235-1579
E-mail: eng_tech@mts.net
www.eng-tech.ca

August 16, 2012

File No.: 11-087-01

Morrison Hershfield
Unit 1 – 25 Scurfield Blvd.
Winnipeg, MB
R3Y 1G4

ATTENTION: Bill Ebinspanger, P.Eng.

RE: Portage Avenue Twin Bridges Over Sturgeon Creek - Final Report

Dear Mr. Ebinspanger,

1.0 Introduction

ENG-TECH Consulting Limited (ENG-TECH) was retained by Morrison Hershfield to conduct localised half-cell, AC resistance and chloride ion testing on the Portage Avenue twin bridge structure passing over Sturgeon Creek. The information and data presented in this final report forms part of the condition survey to be reported in a structural rehabilitation recommendation to be presented to the City of Winnipeg by Morrison Hershfield.

2.0 Scope of Work

The work presented in this report consists of a corrosion potential survey and laboratory chloride ion testing program conducted on the Sturgeon Creek Bridge.

The corrosion potential survey consisted of exposing the top layer of reinforcing bars (re-bar) along, the bridge deck, traffic barriers, sidewalk, fascia, and approach slabs in order to conduct localized half-cell and AC resistance measurements.

The chloride ion testing program consisted of extracting concrete cores from the bridge deck, traffic barriers, sidewalk, fascia and approach slabs in order to determine the water-soluble chloride ion profile throughout the depth of the concrete.

Corrosion potential measurements and extraction of cores were conducted between July 16 and 20, 2012, along the north and south structures. The test locations are presented in Drawings 1 and 2 of Appendix A. Location and depth of cover at each test location was determined by Morrison Hershfield.

3.0 Methodology

3.1 Corrosion Potential Survey

Localized half-cell and AC resistance measurements, on the bridge structure, were carried out according to the *Ontario Structural Rehabilitation Manual (OSRM)* for bridges containing epoxy coated re-bar. Initially, the re-bar location and depth of cover was determined by the use of a cover meter instrument. Once located, the re-bar was exposed by cutting the concrete, with a coring machine, down to the depth of re-bar and then jackhammering the concrete within the cut area. After, a self-tapping screw was inserted into the re-bar in order to provide a connection for localized half-cell and AC resistance measurements.

3.1.1 Localized Half-Cell Measurements

Localized half-cell measurements were done using a half-cell instrument consisting of a copper sulphate reference electrode and portable voltmeter. The measurements were conducted at each test locations by connecting the voltmeter to the self-tapping screw and reference electrode. As such, localised half-cell measurements were done along the same re-bar segment.

3.1.2 AC Resistance Measurements

AC resistance measurements were done using a null balancing ohmmeter capable of measuring resistance from 0.01 ohm to 1.0 megaohm. The measurements were carried out by connecting the ohmmeter to two test locations. The complete set of AC resistance measurements were made between all possible combinations of test locations.

Due to the ability of only closing 2 lanes of traffic at a time, the AC resistance measurements covering all possible combinations was limited to the lane closure area.

3.2 Chloride Ion Testing Program

The chloride ion content of the bridge structure was conducted according to the Canadian Standards Association A23.2-4B: *Test Method for Sampling and Determination of Water-Soluble Chloride Ion Content in Hardened Grout or Concrete*. Drilled concrete cores of 100 mm in length or greater were extracted at selected test locations. Once extracted, the cores were brought to ENG-TECH's laboratory and slices were cut at depths of 10-20 mm, 30-40 mm, 50-60 mm, 70-80 mm and 90-100 mm from the top of core. The first 4 top slices were tested for chloride ion while the 5th bottom slice, of selected cores, was tested in order to provide background readings.

4.0 Results and Discussion

Localized half-cell measurements at the test locations revealed that the localised voltage drops had a range of -0.100 V to -0.600 V. Due to the presence of epoxy coating, the qualification of the potential for corrosion in the steel is not established by conventional practices. Notwithstanding, general observations can be made that provide insight into the potential for corrosion in the steel reinforcement.

Localized half-cell measurements were found to be higher long the south bridge deck than the north bridge deck. The average localized voltage drop along lanes 1, 2, 3 and 4 of the south bridge deck were -0.454 V, -0.400 V, -0.400 V and -0.401 V, respectively. The average localized voltage drop along lanes 1, 2, 3 and 4 of the north bridge deck were -0.196 V, -0.228V, -0.249 V and -0.260 V,

respectively. Based on the localized voltage drop measurements, there is a higher potential for corrosion in the top re-bar of the south deck than the north deck.

Results of averaged localized voltage drop measurements along the approach slabs, sidewalk, fascia and traffic barriers are summarized in Table 1.

Structural Element	South Structure	North Structure
Traffic barrier	-0.439	-0.466
Sidewalk	-	-0.395
Fascia	-	-0.331
West approach slab	-0.467	-0.412
East approach slab	-0.391	-0.375

Calculated AC resistance at individual test locations along the bridge decks were found to be in the range of 0 ohm to 3500 ohms. According to the Ministry of Transportation of Ontario, a calculated AC resistance of less than 1000 ohm is considered to have a high probability of corrosion. Based on the calculated AC resistance, presented in Table 2, the south bridge deck has greater resistance than the north bridge deck. This indicates that the resistance to an anodic and cathodic reaction, necessary for corrosion to occur, in the steel is less in the north bridge deck than the south bridge deck. In addition to the AC resistance measurements, a visual inspection of the condition of the epoxy coating and re-bar was made at each test location. Based on the visual inspection, the epoxy coating and re-bar at the test locations that had resistance less than 1000 ohms appeared to be in similar condition to the test locations that had resistance greater than 1000 ohms. Hence, the calculated AC resistance should be interpreted as the likelihood of an anodic and cathodic reaction to occur, however the results bear no weight on the presence and degree of corrosion.

A summary of AC resistance measurements between all possible test location combinations were calculated according to the OSRM and the individual readings are presented in Appendix D.

It is noted that test locations 15, 16, 17, 19 and 21 were provided for in the original corrosion potential survey proposal but not included in the final survey due to the presence of high voltage conduits inside the sidewalk.

Bridge Deck	Lane	Test Location	Calculated AC Resistance (ohm)
South	1	2	0
	2	4	3495
		5	115
	3	7	624
		8	273
	4	11	1573
		12	1123
13		1223	
North	1	24	1193
	2	26	3
		27	503
	3	29	0
		30	1
	4	33	82
		34	2
35		1	

Water-soluble chloride ion contents were found to be lower along the bridge deck and fascia than the traffic barriers, sidewalk, approach slabs and median. A summary of averaged water-soluble chloride ion contents are presented in Table 3. A literature review indicated that the onset of electrochemical corrosion of steel occurs when the water-soluble chloride ion content by mass of portland cement is in the range of 0.40% to 0.15%. This critical chloride ion threshold is dictated by the pH of the cement and carbonation of the concrete which makes a fixed threshold value not possible. By assuming that the concrete has a portland cement content of 300 kg/m³ and density of 2350 kg/m³, the critical chloride ion threshold to cause corrosion is between 0.050% and 0.019%.

Based on the water-soluble chloride ion test results, the bridge deck and fascia on average contain concentrations that are below the critical chloride ion threshold while all other structural elements are above or within the critical chloride ion threshold. This indicates that the concrete on the bridge deck and fascia have low prevalence on the electrochemical process required for corrosion while all other structural elements do.

The corrosion potential survey and chloride ion test results are summarized in Appendix B.

Table 3: Averaged Water-Soluble Chloride Ion Profile						
Structural Element		Sample Depth (mm)	South Structure		North Structure	
			Avg. Re-Bar Depth (mm)	Chloride Ion Content (%)	Avg. Re-Bar Depth (mm)	Chloride Ion Content (%)
Bridge deck	Lane 1	10-20	75	0.312	80	0.342
		30-40		0.115		0.114
		50-60		0.021		0.023
		70-80		0.017		0.020
		90-100		0.015		0.017
	Lane 3	10-20	85	0.483	85	0.352
		30-40		0.271		0.168
		50-60		0.075		0.043
		70-80		0.042		0.015
	Lane 4	10-20	95	0.211	85	0.214
		30-40		0.089		0.101
		50-60		0.034		0.023
70-80		0.023		0.020		
90-100		0.019		0.019		
Traffic barrier		10-20	50	0.321	40	0.477
		30-40		0.216		0.374
		50-60		0.139		0.228
		70-80		0.105		0.237
Sidewalk		10-20	-	-	50	0.321
		30-40				0.253
		50-60				0.162
		70-80				0.086
Facia		10-20	-	-	60	0.184
		30-40				0.110
		50-60				0.051
		70-80				0.023
West approach slab		10-20	50	0.503	70	0.445
		30-40		0.293		0.315
		50-60		0.181		0.226
		70-80		0.094		0.206
East approach slab		10-20	50	0.487	75	0.562
		30-40		0.335		0.429
		50-60		0.239		0.282
		70-80		0.177		0.230
Median		10-20	-	-	50	0.516
		30-40				0.349
		50-60				0.258
		70-80				0.215

5.0 Conclusion


A corrosion potential survey and laboratory chloride ion testing program was conducted on the Portage Avenue twin bridge structure passing over Sturgeon Creek.

The corrosion potential survey consisted of measuring localized voltage drops and AC resistance along the bridge deck, traffic barriers, sidewalk, fascia, and approach slabs. Based on the localized voltage drop and AC resistance measurements it was observed that: 1) higher voltage drops are present along the south bridge deck than the north bridge deck, and 2) lower calculated AC resistances are present along the north bridge deck than the south bridge deck.

The chloride ion testing program consisted of measuring the water-soluble chloride ion profile on concrete cores extracted from the bridge deck, traffic barriers, sidewalk, fascia and approach slabs. Based on the results, the water-soluble chloride ion content at the depth of re-bar along the bridge deck and fascia are lower than the critical chloride ion threshold, while the traffic barriers, sidewalk, median and approach slabs are above or within the critical chloride ion threshold.

If there are any questions or comments, please contact the undersigned.

Sincerely,
ENG-TECH Consulting Limited



Jean-Luc Lambert, EIT
Materials Engineer

Reviewed by,
ENG-TECH Consulting Limited



Danny Holfeld, Principal
Manager of Operations

DH/jl

CC: Email: BEbenspanger@morrisonhershfield.com

Attachments: Appendix A - Test Location Drawings
 Appendix B - Corrosion Potential Survey and Laboratory Test Results
 Appendix C - Concrete Core Pictures
 Appendix D - Individual AC Resistance Measurements


APPENDIX A

Test Location Drawings



TEST LOCATION

EXPANSION JOINT



NO.	DATE	ISSUE / REVISION

ENG-TECH
CONSULTING LIMITED

#6 - 854 Marion Street
Winnipeg, MB R2J 0K4
Phone: (204) 233-1694
Fax: (204) 233-1679




CLIENT:	MORRISON HERSHFIELD
PROJECT:	PORTAGE AVENUE TWIN BRIDGES OVER STURGEON CREEK
DWG DESCRIPTION:	TEST LOCATIONS ALONG SOUTH STRUCTURE
SCALE:	N.T.S.
DRAWN BY:	JL
DATE:	AUGUST 10, 2012
FILE NO.:	12-087-01
CLIENT DWG/FIG. NO.:	
ENG-TECH DWG/FIG. NO.:	1



TEST LOCATION

EXPANSION JOINT



NO.	DATE	ISSUE / REVISION

ENG-TECH
Consulting Limited

#6 - 854 Marion Street
Winnipeg, MB R2J 0K4
Phone: (204) 233-1694
Fax: (204) 235-1579



CLIENT:	MORRISON HERSHFIELD
PROJECT:	PORTAGE AVENUE TWIN BRIDGES OVER STURGEON CREEK
DWG DESCRIPTION:	TEST LOCATIONS ALONG NORTH STRUCTURE
SCALE:	N.T.S.
DRAWN BY:	JL
DATE:	AUGUST 10, 2012
FILE NO.:	12-087-01
CLIENT DWG/FIG. NO.:	
ENG-TECH DWG/FIG. NO.:	
NO.:	2

APPENDIX B

Corrosion Potential Survey and Laboratory Test Results

Table 1: Corrosion Potential Survey and Laboratory Test Results for South Structure

Test Location	Location	Depth to Top Layer of Re-bar [mm]	Localized Half Cell Measurement [V]	Calculated AC Resistance [ohm]	Thickness of High Density Concrete [mm]	Core Length [mm]	Sample Depth [mm]	Water-Soluble Chloride Ion Content [%]	Notes
1	Eastbound lane 1 along west approach. 4.3 m west of west expansion joint and 2.0 m south of median curb.	55	-0.454	-	-	-	-	-	
2	Eastbound lane 1 along bridge deck. 18.0 m west of east expansion joint and 2.0 m south of lane 1 curb.	75	-0.432	0	65	120	10-20 30-40 50-60 70-80 90-100	0.312 0.115 0.021 0.017 0.015	
3	Eastbound lane 1 along east approach. 5.0 m east of east approach and 2.1 m south of median curb.	95	-0.397	-	-	-	-	-	
4	Eastbound lane 2 along bridge deck. 6.0 m east of west expansion joint and 5.4 m south of median curb.	80	-0.333	3495	-	-	-	-	
5	Eastbound lane 2 along bridge deck. 6.2 m west of east expansion joint and 5.4 m south of median curb.	95	-0.466	115	-	-	-	-	
6	Eastbound lane 3 along west approach. 6.0 m west of west expansion joint and 7.5 m north of traffic barrier toe.	60	-0.391	-	-	140	10-20 30-40 50-60 70-80	0.527 0.289 0.188 0.086	
7	Eastbound lane 3 along bridge deck. 13.0 m east of west expansion joint and 6.5 m north of traffic barrier toe.	85	-0.457	624	55	155	10-20 30-40 50-60 70-80	0.472 0.276 0.070 0.030	

Table 1: Corrosion Potential Survey and Laboratory Test Results for South Structure (Continued)

Test Location	Location	Depth to Top Layer of Re-bar [mm]	Localized Half Cell Measurement [V]	Calculated AC Resistance [ohm]	Thickness of High Density Concrete [mm]	Core Length [mm]	Sample Depth [mm]	Water-Soluble Chloride Ion Content [%]	Notes
8	Eastbound lane 3 along bridge deck. 13.0 m west of east expansion joint and 6.5 m north of traffic barrier toe.	90	-0.342	273	55	140	10-20 30-40 50-60 70-80	0.493 0.266 0.083 0.053	
9	Eastbound lane 3 along east approach. 5.0 m east of east expansion joint and 6.5 m north of lane 4 curb.	-	-0.299	-	-	145	10-20 30-40 50-60 70-80	0.582 0.421 0.285 0.230	
10	Eastbound lane 4 along west approach. 4.9 m west of west expansion joint and 1.0 m north of traffic barrier toe.	50	-0.556	-	-	150	10-20 30-40 50-60 70-80	0.478 0.296 0.173 0.101	
11	Eastbound lane 4 along bridge deck. 3.0 m east of west expansion joint and 1.0 m north of traffic barrier toe.	85	-0.501	1573	50	120	10-20 30-40 50-60 70-80 90-100	0.189 0.065 0.032 0.032 0.026	
12	Eastbound lane 4 along bridge deck. 19.0 m east of west expansion joint and 1.0 m north of traffic barrier toe.	110	-0.355	1123	55	145	10-20 30-40 50-60 70-80 90-100	0.230 0.115 0.046 0.018 0.017	
13	Eastbound lane 4 along bridge deck. 3.0 m west of east expansion joint and 1.0 m north of traffic barrier toe.	90	-0.346	1723	50	135	10-20 30-40 50-60 70-80 90-100	0.214 0.086 0.024 0.020 0.015	

Table 1: Corrosion Potential Survey and Laboratory Test Results for South Structure (Continued)

Test Location	Location	Depth to Top Layer of Re-bar [mm]	Localized Half Cell Measurement [V]	Calculated AC Resistance [ohm]	Thickness of High Density Concrete [mm]	Core Length [mm]	Sample Depth [mm]	Water-Soluble Chloride Ion Content [%]	Notes
14	Eastbound lane 4 along east approach. 3.8 m east of east expansion joint and 1.0 m north of traffic barrier toe.	50	-0.476	-	-	150	10-20 30-40 50-60 70-80	0.391 0.249 0.192 0.123	
15	South structure along west side of sidewalk.	-	-	-	-	-	-	-	No testing done due to high voltage conduits.
16	South structure along center of sidewalk.	-	-	-	-	-	-	-	No testing done due to high voltage conduits.
17	South structure along east side of sidewalk.	-	-	-	-	-	-	-	No testing done due to high voltage conduits.
18	South structure along north face of traffic barrier. 5.5 m east of west expansion joint and 0.6 m vertically up from traffic barrier toe.	50	-0.500	-	-	145	10-20 30-40 50-60 70-80	0.416 0.285 0.197 0.152	Polymer with fiber topping approximately 1 mm thick
19	South structure along west facia.	-	-	-	-	-	-	-	No testing done due to high voltage conduits.

Table 1: Corrosion Potential Survey and Laboratory Test Results for South Structure (Continued)

Test Location	Location	Depth to Top Layer of Re-bar [mm]	Localized Half Cell Measurement [V]	Calculated AC Resistance [ohm]	Thickness of High Density Concrete [mm]	Core Length [mm]	Sample Depth [mm]	Water-Soluble Chloride Ion Content [%]	Notes
20	South structure along north face of traffic barrier. 19.0 m east of west expansion joint and 0.6 m vertically up from traffic barrier toe.	50	-0.270	-	-	-	-	-	
21	South structure along east fascia.	-	-	-	-	-	-	-	No testing done due to high voltage conduits.
22	South structure along north face of traffic barrier. 31.0 m east of west expansion joint and 0.6 m vertically up from traffic barrier toe.	50	-0.548	-	150	-	10-20 30-40 50-60 70-80	0.226 0.147 0.080 0.059	Polymer with fiber topping approximately 1 mm thick

Table 2: Corrosion Potential Survey and Laboratory Test Results for North Structure

Test Location	Location	Depth to Top Layer of Re-bar [mm]	Localized Half Cell Measurement [V]	Calculated AC Resistance [ohm]	Thickness of High Density Concrete [mm]	Core Length [mm]	Sample Depth [mm]	Water-Soluble Chloride Ion Content [%]	Notes
23	Westbound lane 1 along east approach. 4.1 m east of east expansion joint and 2.3 m north of median curb.	95	-0.173	-	-	-	-	-	
24	Westbound lane 1 along bridge deck. 18.7 m east of west expansion joint and 1.9 m north of median curb.	80	-0.196	1193	45	120	10-20 30-40 50-60 70-80 90-100	0.342 0.114 0.023 0.020 0.017	
25	Westbound lane 1 along west approach. 4.6 m west of west expansion joint and 1.4 m north of median curb.	80	-0.368	-	-	-	-	-	
26	Westbound lane 2 along bridge deck. 14.6 m west of east expansion joint and 4.9 m north of median curb.	80	-0.214	3	-	-	-	-	
27	Westbound lane 2 along bridge deck. 15.6 m east of west expansion joint and 5.2 m north of median curb.	95	-0.242	503	-	-	-	-	
28	Westbound lane 3 along east approach. 4.2 m east of east expansion joint and 6.2 m south of traffic barrier toe.	80	-0.337	-	-	135	10-20 30-40 50-60 70-80	0.593 0.484 0.298 0.238	

Table 2: Corrosion Potential Survey and Laboratory Test Results for North Structure (Continued)

Test Location	Location	Depth to Top Layer of Re-bar [mm]	Localized Half Cell Measurement [V]	Calculated AC Resistance [ohm]	Thickness of High Density Concrete [mm]	Core Length [mm]	Sample Depth [mm]	Water-Soluble Chloride Ion Content [%]	Notes
29	Westbound lane 3 along bridge deck, 13.1 m west of east expansion joint and 6.0 m south of traffic barrier toe.	85	-0.253	0	55	140	10-20 30-40 50-60 70-80	0.326 0.144 0.032 0.012	
30	Westbound lane 3 along bridge deck, 12.7 m east of west expansion joint and 6.2 m south of traffic barrier toe.	85	-0.244	1	70	140	10-20 30-40 50-60 70-80	0.377 0.192 0.053 0.017	
31	Westbound lane 3 along west approach, 4.9 m west of west expansion joint and 7.0 m south of traffic barrier toe.	70	-0.459	-	-	125	10-20 30-40 50-60 70-80	0.375 0.274 0.235 0.232	Concrete delaminated at 20 mm from surface.
32	Westbound lane 4 along east approach, 4.5 m east of east expansion joint and 1.5 m south of traffic barrier toe.	75	-0.616	-	-	140	10-20 30-40 50-60 70-80	0.531 0.374 0.266 0.222	Concrete delaminated at 40 mm from surface
33	Westbound lane 4 along bridge deck, 7.3 m west of east expansion joint and 1.2 m south of traffic barrier toe.	95	-0.422	82	60	100	10-20 30-40 50-60 70-80 90-100	0.232 0.108 0.024 0.020 0.018	
34	Westbound lane 4 along bridge deck, 19.5 m west of east expansion joint and 1.1 m south of traffic barrier toe.	80	-0.172	2	50	135	10-20 30-40 50-60 70-80 90-100	0.224 0.085 0.020 0.020 0.020	

Table 2: Corrosion Potential Survey and Laboratory Test Results for North Structure (Continued)


Test Location	Location	Depth to Top Layer of Re-bar [mm]	Localized Half Cell Measurement [V]	Calculated AC Resistance [ohm]	Thickness of High Density Concrete [mm]	Core Length [mm]	Sample Depth [mm]	Water-Soluble Chloride Ion Content [%]	Notes
35	Westbound lane 4 along bridge deck. 4.4 m east of west expansion joint and 1.0 m south of traffic barrier toe.	90	-0.185	1	60	130	10-20 30-40 50-60 70-80 90-100	0.187 0.111 0.026 0.020 0.020	
36	Westbound lane 4 along west approach. 5.1 m west of west expansion joint and 1.2 m south of traffic barrier toe.	75	-0.409	-	-	140	10-20 30-40 50-60 70-80	0.516 0.355 0.217 0.180	
37	North structure along sidewalk. 7.0 m west of east expansion joint and 0.4 m from face of fascia.	60	-0.394	234	-	-	-	-	
38	North structure along sidewalk. 19.0 m west of east expansion joint and 0.4 m from face of fascia.	30	-0.595	2913	-	100	10-20 30-40 50-60 70-80	0.321 0.253 0.162 0.086	
39	North structure along sidewalk. 7.0 m east of west expansion joint and 0.4 m from face of fascia.	60	-0.196	1763	-	-	-	-	
40	North structure along south face of traffic barrier. 6.8 m west of east expansion joint and 0.6 m vertically up from traffic barrier toe..	50	-0.436	-	-	140	10-20 30-40 50-60 70-80	0.572 0.449 0.232 0.226	Concrete delaminated at 50 mm from surface. Polymer with fiber topping approximately 1 mm thick.


Table 2: Corrosion Potential Survey and Laboratory Test Results for North Structure (Continued)

Test Location	Location	Depth to Top Layer of Re-bar [mm]	Localized Half Cell Measurement [V]	Calculated AC Resistance [ohm]	Thickness of High Density Concrete [mm]	Core Length [mm]	Sample Depth [mm]	Water-Soluble Chloride Ion Content [%]	Notes
41	North structure along south face of traffic barrier. 19.5 m west of east expansion joint and 0.4 m vertically up from traffic barrier toe.	40	-0.399	-	-	-	-	-	
42	North structure along south face of traffic barrier. 31.0 m west of east expansion joint and 0.6 m vertically up from traffic barrier toe.	45	-0.563	-	-	160	10-20 30-40 50-60 70-80	0.381 0.299 0.223 0.247	Concrete delaminated at 40 mm from surface. Polymer with fiber topping approximately 1 mm thick. Slice 50-60 had some chunks with rust like colouration.
43	North structure along fascia. 5.3 m west of east expansion joint and 0.2 m vertically down from surface of sidewalk.	75	-0.377	-	-	135	10-20 30-40 50-60 70-80	0.265 0.196 0.084 0.029	Polymer with fiber topping approximately 1 mm thick.
44	North structure along fascia. 4.8 m east of west expansion joint and 0.2 m vertically down from surface of sidewalk.	60	-0.285	-	-	150	10-20 30-40 50-60 70-80	0.103 0.023 0.018 0.017	Polymer with fiber topping approximately 1 mm thick.
45	North structure along median. 18.1 m east of west expansion joint and 0.3 m south of median curb.	50	-	-	-	145	10-20 30-40 50-60 70-80	0.516 0.349 0.258 0.215	Polymer with fiber topping approximately 1 mm thick.


APPENDIX C

Concrete Core Pictures





Concrete Cores at Test Locations



Concrete Cores at Test Locations





Concrete Cores at Test Locations

APPENDIX D


Individual AC Resistance Measurements

Measured AC Resistance (ohm) Between Connection 1 and 2: South Structure															
Connection 1	Connection 2													Calculated AC Resistance	
	2	4	5	6	10	9	14	7	8	11	12	13			
2	-	3495	115											0	
4	4145	-	4045											3495	
5	125	3695	-											115	
6				-	203									n.a.	
10				199	-									n.a.	
9										657				n.a.	
14									657	-				n.a.	
7										-	897	2197	1747	2347	624
8										947	-	1847	1297	1747	273
11										2147	1647	-	2547	3147	1573
12										1747	1197	2547	-	2697	1123
13										2447	1847	3347	2747	-	1723

APPENDIX B: LIVE LOAD VEHICLES



 THE CITY OF WINNIPEG PUBLIC WORKS DEPARTMENT	LIVE LOAD VEHICLES	 MORRISON HERSHFIELD
Portage Avenue Twin Bridges over Sturgeon Creek	CSA S6-06 DESIGN LOADING CL-625 TRUCK / LANE	PROJ. NO. 07-8164 SCALE: N.T.S. DATE: MAY 2011
		PLATE NO. 1



HSS - 25 TRUCK


THE CITY OF WINNIPEG
 PUBLIC WORKS DEPARTMENT

LIVE LOAD VEHICLES



MORRISON HERSHFIELD

Portage Avenue
 Twin Bridges
 over
 Sturgeon Creek

AASHTO HSS DESIGN TRUCK

PROJ. NO. 07-8164
 SCALE: N.T.S.
 DATE: MAY 2011

PLATE NO. 2



36 500 kg G.V.W. SEMI - TRAILER TRUCK


THE CITY OF WINNIPEG
 PUBLIC WORKS DEPARTMENT

LIVE LOAD VEHICLES



MORRISON HERSHFIELD

Portage Avenue
 Twin Bridges
 over
 Sturgeon Creek

LEGAL TRUCK
36 500 kg G.V.W.

PROJ. NO. 07-8164
 SCALE: N.T.S.
 DATE: MAY 2011

PLATE NO.3



**56 500 kg G.V.W. SEMI - TRAILER COMBINATION
(B - TRAIN LEGAL TAC)**


THE CITY OF WINNIPEG
 PUBLIC WORKS DEPARTMENT

LIVE LOAD VEHICLES



MORRISON HERSHFIELD

Portage Avenue
 Twin Bridges
 over
 Sturgeon Creek


LEGAL TRUCK
 56 500 kg G.V.W.

PROJ. NO. 07-8164
 SCALE: N.T.S.
 DATE: MAY 2011


PLATE NO. 4



 THE CITY OF WINNIPEG PUBLIC WORKS DEPARTMENT	LIVE LOAD VEHICLES	 MORRISON HERSHFIELD
Portage Avenue Twin Bridges over Sturgeon Creek	124 057 kg OVERLOAD VEHICLE	PROJ. NO. 07-8164 SCALE: N.T.S. DATE: MAY 2011
		PLATE NO. 6



 THE CITY OF WINNIPEG PUBLIC WORKS DEPARTMENT	LIVE LOAD VEHICLES	 MORRISON HERSHFIELD
Portage Avenue Twin Bridges over Sturgeon Creek	166 080 kg OVERLOAD VEHICLE SCHEUERLE CONFIGURATION	PROJ. NO 07-8164 SCALE: N.T.S. DATE: MAY 2011
		PLATE NO. 7



81 090 kg MOBILE CRANE LIEBHERR 1160


THE CITY OF WINNIPEG
 PUBLIC WORKS DEPARTMENT

LIVE LOAD VEHICLES


MORRISON HERSHFIELD

Portage Avenue
 Twin Bridges
 over
 Sturgeon Creek

MOBILE CRANE
 81 090 kg LIEBHERR 1160

PROJ. NO. 07-8164
 SCALE: N.T.S.
 DATE: MAY 2011

PLATE NO. 8

APPENDIX C: STRUCTURAL EVALUATION CALCULATIONS

1. Design Criteria

Canadian Highway Bridge Design Code

S6-06

2. Load Type

Dead Load (DL): precast pre-stressed concrete box cell girder, cast-in-place concrete deck
 Superimposed Dead Load (SDL): high density concrete overlay, sidewalk and median, concrete barrier
 Live Load (LL): See Appendix B for normal and alternative live load vehicles, mobile crane and overload vehicles

3. Material Properties

Contract Drawings B178-80-02 & 19

Structural Concrete	f_c	12 MPa
	f_c	30 MPa
Reinforcing Steel (hard grade)	f_y	400 MPa
Precast Prestressed Concrete Concrete	f_{ci}	30 MPa
	f_c	35 MPa
Reinforcing Steel	f_y	300 MPa
Prestressing Steel	f_s	1860 MPa
Dia of prestressing strand		13 mm
Initial force in prestressing strand	P_i	128.6 kN

4. Evaluation Parameter

System Behaviour:	S2	
Element Behaviour:	E2	
Inspection Level:	INSP1	
Target Reliability Index:	β	3.5

Load Factors:

Dead Load:				Table 14.7
Factory produced concrete	D1	1.09		
Cast-in-place concrete and non-structural products	D2	1.18		
Live Load:				
Normal Traffic or alternative loading				Table 14.9
Short Span	α_{LS}	2.2		
Other Span	α_{LI}	1.63		
Permit - Annual or project (PA)				Table 14.10
Short Span	α_{LS}	1.78		
Other Span	α_{LI}	1.53		
Short Span: Moment L < 10m, Shear L < 6m				
Dynamic Load Factor				
Normal traffic and alternative loading	DLA	0.3		3.8.4.5 & 14.9.3 (d)
Permit vehicle (Overload vehicles)	0.3 * DLA = DLA _P	0.09		14.9.3 (a)

5. Load Distribution Factor

Description		Span 1 & 3 (L1)		Pier 1 & 2		Span 2 (L2)		
		Exterior	Interior	Exterior	Interior	Exterior	Interior	
Total width of bridge (m)	B	18.29	18.29	18.29	18.29	18.29	18.29	
Total width of design lanes (m)	W _c	14.02	14.02	14.02	14.02	14.02	14.02	
Number of design lane	n	4	4	4	4	4	4	
Design lane width (m)	W _e = W _c / n	3.505	3.505	3.505	3.505	3.505	3.505	
Multi-lane modification factor - normal traffic	R _L	0.7	0.7	0.7	0.7	0.7	0.7	Table 3.5
Lane width modification factor	$\mu = (W_e - 3.3) / 0.6 \leq 1.0$	0.34	0.34	0.34	0.34	0.34	0.34	
Span length (m)	L1 or L2	9.966	9.966			18.000	18.000	
Effective span length (m)	L	7.97	7.97	6.99	6.99	10.80	10.80	Fig A5.1.1
Factors for longitudinal moments								
Load distribution for width dimension	F	12.17	11.86	11.92	11.32	12.82	13.37	Table 5.3
Correction factor to adjust F	C _r	12.24	12.24	11.71	11.71	13.22	13.22	Table 5.3
Moment Amplification Factor	$F_m = B / [F * (1 + \mu C_r / 100)] \geq 1.05$	1.44	1.48	1.48	1.55	1.37	1.31	
Factors for longitudinal shear								
Voided slab - c/c spacing of long web lines (S < 2.0m)	S	1.219	1.219	1.219	1.219	1.219	1.219	
Load distribution for width dimension (n <= 4)	F * (S/2) ^{0.25}	8.66	8.66	8.66	8.66	8.66	8.66	5.7.1.4.1.2(b)
Shear Amplification Factor	$F_v = B / F \geq 1.05$	2.11	2.11	2.11	2.11	2.11	2.11	
USL and SLS-1								
Normal Traffic								
Truck Load / m width of voided slab for moment	F _m * n * R _L / B	0.22	0.23	0.23	0.24	0.21	0.20	
Truck Load / m width of voided slab for shear	F _v * n * R _L / B	0.32	0.32	0.32	0.32	0.32	0.32	

6. Loads and Analysis Summary

Unit weight of concrete	24	kN / m ³
Unit weight of prestressed concrete	24.5	kN / m ³
Dead Loads		
Box Cell Girder	10.4	kN / m
CIP Concrete Deck	1.95	kN / m
Superimposed Dead Loads		
Concrete Overlay	0.98	kN / m
Sidewalk	1.45	kN / m
Median	1.02	kN / m
Barrier	0.47	kN / m
	<u>3.91</u>	kN / m

The spans are considered as semi-continuous with girders and wet deck loads acting as loads on simple spans and superimposed dead loads and live loads acting as loads on continuous span.

Span 1 & 3

L1 = 9.966 m

Dead Load	Load Factor	UDL kN / m	Unfactored / m width			Factored / m width		
			M kN-m	- M kN-m	V kN	M _{ULS} kN-m	- M _{ULS} kN-m	V _{ULS} kN
Box Cell Girder	1.09	10.4	129	0	74	140.7	0.0	80.7
CIP Concrete Deck	1.18	1.95	24	0	12	26.4	0.0	13.1
Overlay, barrier, median, sidewalk	1.18	3.91	11	-91	24	13.0	-107.4	28.3

Live Load	Load Factor		Unfactored per lane (SAP2000 Analysis)			Factored per lane		
	Short Span α_{LS}	Other Span α_{LI}	M kN-m	- M kN-m	V kN	M _{ULS} = $\alpha_{LS} * M$ kN-m	- M _{ULS} = $\alpha_{LS} * (-M)$ kN-m	V _{ULS} = $\alpha_{LI} * V$ kN
Design Truck								
HS - 30 Truck (AASHTO)	2.2	1.63	486	-761	360	1069	-1674	587
Normal Traffic and alternative loading								
CL1-625	2.2	1.63	231	-727	314	508	-1599	512
CL2-625	2.2	1.63	358	-635	299	788	-1397	487
CL3-625	2.2	1.63	457	-513	266	1005	-1129	434
CL1-625 Lane Load	2.2	1.63	216	-785	314	475	-1727	512
CL2-625 Lane Load	2.2	1.63	364	-704	293	801	-1549	478
CL3-625 Lane Load	2.2	1.63	423	-543	259	931	-1195	422
HSS - 25 Truck (AASHTO)	2.2	1.63	393	-801	333	865	-1762	543
36 500 kg G.V.W. Legal Truck	2.2	1.63	283	-512	224	623	-1126	365
56 500 kg G.V.W. Legal Truck	2.2	1.63	213	-664	279	469	-1461	455
62 500 kg G.V.W. Legal Truck	2.2	1.63	179	-696	307	394	-1531	500
Overload Vehicle								
124 057 kg Overload vehicle	1.78	1.53	360	-668	315	641	-1189	482
166 080 kg Overload vehicle	1.78	1.53	69	-1080	334	123	-1922	511
81 090 kg Liebherr 1160	1.78	1.53	172	-938	427	306	-1670	653

Live Load	DLA α_{LI}	Distribution Factors / m width			Factored Truck Load / m width		
		M	- M	V	M _{ULS} kN-m	- M _{ULS} kN-m	V _{ULS} kN
Design Truck							
HSS - 30 Truck (AASHTO)	0.3	0.21	0.24	0.32	292	-522	244
Normal Traffic and alternative loading							
CL1-625	0.3	0.21	0.24	0.32	139	-499	213
CL2-625	0.3	0.21	0.24	0.32	215	-436	203
CL3-625	0.3	0.21	0.24	0.32	274	-352	180
CL1-625 Lane Load	0	0.21	0.24	0.32	100	-414	164
CL2-625 Lane Load	0	0.21	0.24	0.32	168	-372	153
CL3-625 Lane Load	0	0.21	0.24	0.32	195	-287	135
HSS - 25 Truck (AASHTO)	0.3	0.21	0.24	0.32	236	-550	226
36 500 kg G.V.W. Legal Truck	0.3	0.21	0.24	0.32	170	-351	152
56 500 kg G.V.W. Legal Truck	0.3	0.21	0.24	0.32	128	-456	189
62 500 kg G.V.W. Legal Truck	0.3	0.21	0.24	0.32	108	-478	208
Overload Vehicle							
124 057 kg Overload vehicle	0.09	0.32	0.34	0.46	226	-441	243
166 080 kg Overload vehicle	0.09	0.32	0.34	0.46	43	-712	257
81 090 kg Liebherr 1160	0.09	0.32	0.34	0.46	108	-619	329
Max Live Load					292	-712	329

Total DL1 + DL2 + LL (1+DLA)

472 -820 451

Span 2

L1 = 18 m

Dead Load	Load Factor	UDL kN / m	Unfactored / m width			Factored / m width		
			M kN-m	- M kN-m	V kN	M _{ULS} kN-m	- M _{ULS} kN-m	V _{ULS} kN
Box Cell Girder	1.09	10.4	421	0	94	459.1	0.0	102.5
CIP Concrete Deck	1.18	1.95	79	0	18	86.1	0.0	19.6
Overlay, barrier, median, sidewalk	1.18	3.91	70	-91	36	82.6	-107.4	42.5

Live Load	Load Factor		Unfactored per lane			Factored per lane		
	Short Span α_{LS}	Other Span α_{LI}	M kN-m	- M kN-m	V kN	M _{ULS} = $\alpha_{LS} * M$ kN-m	- M _{ULS} = $\alpha_{LS} * (- M)$ kN-m	V _{ULS} = $\alpha_{LI} * V$ kN
Design Truck								
HS - 30 Truck (AASHTO)	2.2	1.63	921	-761	422	1501	-1240	688
Normal Traffic and alternative loading								
CL1-625	2.2	1.63	737	-727	371	1201	-1185	605
CL2-625	2.2	1.63	770	-635	348	1255	-1035	567
CL3-625	2.2	1.63	709	-513	283	1156	-836	461
CL1-625 Lane Load	2.2	1.63	761	-758	378	1240	-1236	616
CL2-625 Lane Load	2.2	1.63	789	-704	356	1286	-1148	580
CL3-625 Lane Load	2.2	1.63	678	-543	304	1105	-885	496
HSS - 25 Truck (AASHTO)	2.2	1.63	924	-801	435	1506	-1306	709
36 500 kg G.V.W. Legal Truck	2.2	1.63	594	-512	286	968	-835	466
56 500 kg G.V.W. Legal Truck	2.2	1.63	660	-664	338	1076	-1082	551
62 500 kg G.V.W. Legal Truck	2.2	1.63	732	-696	354	1193	-1134	577
Overload Vehicle								
124 057 kg Overload vehicle	1.78	1.53	564	-668	384	863	-1022	588
166 080 kg Overload vehicle	1.78	1.53	918	-1080	430	1405	-1652	658
81 090 kg Liebherr 1160	1.78	1.53	1007	-938	459	1541	-1435	702

Live Load	DLA α_{LI}	Distribution Factors / m width			Factored Truck Load / m width		
		M	- M	V	M _{ULS} kN-m	- M _{ULS} kN-m	V _{ULS} kN
Design Truck							
HSS - 30 Truck (AASHTO)	0.3	0.23	0.24	0.32	449	-387	286
Normal Traffic and alternative loading							
CL1-625	0.3	0.23	0.24	0.32	359	-370	252
CL2-625	0.3	0.23	0.24	0.32	375	-323	236
CL3-625	0.3	0.23	0.24	0.32	346	-261	192
CL1-625 Lane Load	0	0.23	0.24	0.32	285	-297	197
CL2-625 Lane Load	0	0.23	0.24	0.32	296	-275	186
CL3-625 Lane Load	0	0.23	0.24	0.32	254	-212	159
HSS - 25 Truck (AASHTO)	0.3	0.23	0.24	0.32	450	-407	295
36 500 kg G.V.W. Legal Truck	0.3	0.23	0.24	0.32	289	-260	194
56 500 kg G.V.W. Legal Truck	0.3	0.23	0.24	0.32	322	-338	229
62 500 kg G.V.W. Legal Truck	0.3	0.23	0.24	0.32	357	-354	240
Overload Vehicle							
124 057 kg Overload vehicle	0.09	0.32	0.34	0.46	304	-379	296
166 080 kg Overload vehicle	0.09	0.32	0.34	0.46	495	-612	331
81 090 kg Liebherr 1160	0.09	0.32	0.34	0.46	543	-532	354
Max Live Load					543	-612	354

Total DL1 + DL2 + LL (1+DLA)

1171 -720 518

7. Summary

Location		Flexure			Shear		
		M _f kN-m	M _r kN-m	M _r / M _f	V _f kN	V _r kN	V _r / V _f
At Mid Span	Span 1 & 3	472	798	1.691			
	Span 2	1171	1314	1.122			
At Supports		-820	-914	1.115	518	1013	1.955

Material Properties

Precast box cell concrete girder

Concrete	f'_c	35 MPa
Prestressed steel	f_{pu}	1860 MPa
Reinforcing steel	f_y	300 MPa
Type of prestressing steel		low relaxation
Structural concrete (deck, barrier, etc.)		
Concrete	f'_c	30 MPa
Reinforcing steel	f_y	400 MPa

Resistance factors

Concrete	ϕ_c	0.75
Prestress steel	ϕ_p	0.95
Reinforcing steel	ϕ_s	0.9

Table 8.1

Dimensions

Top flange width	b_t	1219 mm
Top flange thickness	h_t	153 mm
Web thickness	b_w	306 mm
Bottom flange width	b_b	1219 mm
Bottom flange thickness	h_b	153 mm
Total depth	d	610 mm
Prestressing strand	13 mm dia	A_{ps}
Total number of strands		98 mm ²
Reinforcing steel		16
	10M	A_{s10}
	25M	100 mm ²
		A_{s25}
		500 mm ²

Distance from top of concrete

Bottom prestress steel		
layer 1	d_{p1}	559 mm
layer 2	d_{p2}	508 mm
layer 3	d_{p3}	457 mm
Top prestressing steel	d'_p	101 mm
Bottom reinforcing steel	d_s	565 mm
Top reinforcing steel		
layer 1	d'_{s1}	45 mm
layer 2	d'_{s2}	108 mm

Area of steel

Bottom prestress steel				
layer 1	6 strands	A_{ps1}	588 mm ²	
layer 2	6 strands	A_{ps2}	588 mm ²	
layer 3	2 strands	A_{ps3}	196 mm ²	
Top prestressing steel	2 strands	A'_{ps}	196 mm ²	
Bottom reinforcing steel	3 10M	A_s	300 mm ²	
Top reinforcing steel				
layer 1	5 10M	A'_{s1}	500 mm ²	
layer 2	4 10M	A'_{s2}	400 mm ²	

Calculations

α_1	$= 0.85 - 0.0015 * f'_c$	0.798	
β_1	$= 0.97 - 0.0025 * f'_c$	0.883	
c / d_p	≤ 0.5		8.8.4.2
f_{ps}	$= f_{pu} * (1 - k_p * c / d_p)$	1,704 MPa	
k_p	$= 0.3$ for low-relaxation strand $= 0.4$ for smooth high-strength bars $= 0.5$ for deformed high strength bars	0.3	
c / d_p	$= \{ \phi_p * A_{ps} * f_{pu} + \phi_s * A_s * f_y - \phi_p * A'_{ps} * f_{pu} - \phi_s * A'_s * f_y - \alpha_1 * \phi_c * f'_c * ht * (b - bw) \} /$ $\{ \alpha_1 * \phi_c * \beta_1 * f'_c * bw * d_p + \phi_p * k_p * A_{ps} * f_{pu} \}$	-0.280	OK
f_{ps}	$= f_{pu} [1 - 0.5 * (\mu_p * f_{pu} / f'_c)]$	1,581 MPa	14.14.1.2.4
μ_p	$= A_{sp} / A_c$	0.006	
a	$= \{ \phi_p * A_{ps} * f_{ps} + \phi_s * A_s * f_y - \phi_p * A'_{ps} * f_{ps} - \phi_s * A'_s * f_y - \alpha_1 * \phi_c * f'_c * ht * (b - bw) \} /$ $\{ \alpha_1 * \phi_c * f'_c * bw \}$	-185 mm 185 mm	
M_r	$= \phi_p * A_{ps} * f_{ps} * (d_p - a/2) + \phi_s * A_s * f_y * (d_s - a/2) - \phi_p * A'_{ps} * f_{ps} * (d'_p - a/2) - \phi_s * A'_s * f_y * (d - d'_s) -$ $\alpha_1 * \phi_c * f'_c * ht * (b - bw) * (ht - a/2)$		
	$f_{ps} =$	1,704 MPa	1,042 kN-m 855 kN-m / m width
	$f_{ps} =$	1,581 MPa	973 kN-m 798 kN-m / m width Use

Material Properties

Precast box cell concrete girder

Concrete		f'_c	35 MPa
Prestressed steel		f_{pu}	1860 MPa
Reinforcing steel		f_y	300 MPa
Type of prestressing steel			low relaxation
Structural concrete (deck, barrier, etc.)			
Concrete		f'_c	30 MPa
Reinforcing steel		f_y	400 MPa

Resistance factors

Concrete		ϕ_c	0.75
Prestress steel		ϕ_p	0.95
Reinforcing steel		ϕ_s	0.9

Table 8.1

Dimensions

Top flange width		b_t	1219 mm
Top flange thickness		h_t	153 mm
Web thickness		b_w	306 mm
Bottom flange width		b_b	1219 mm
Bottom flange thickness		h_b	153 mm
Total depth		d	610 mm
Prestressing strand	13 mm dia	A_{ps}	98 mm ²
Total number of strands			28
Reinforcing steel	10M	A_{s10}	100 mm ²
	25M	A_{s25}	500 mm ²

Distance from top of concrete

Bottom prestress steel			
layer 1		d_{p1}	559 mm
layer 2		d_{p2}	508 mm
layer 3		d_{p3}	457 mm
layer 4		d_{p4}	406 mm
Bottom reinforcing steel		d_s	565 mm
Top reinforcing steel			
layer 1		d'_{s1}	45 mm
layer 2		d'_{s2}	108 mm

Area of steel

Bottom prestress steel			
layer 1	12 strands	A_{ps1}	1176 mm ²
layer 2	10 strands	A_{ps2}	980 mm ²
layer 3	4 strands	A_{ps3}	392 mm ²
layer 4	2	A_{ps4}	196 mm ²
Bottom reinforcing steel	3 10M	A_s	300 mm ²
Top reinforcing steel			
layer 1	5 10M	A'_{s1}	500 mm ²
layer 2	4 10M	A'_{s2}	400 mm ²

Calculations

α_1	$= 0.85 - 0.0015 * f'_c$	0.798	
β_1	$= 0.97 - 0.0025 * f'_c$	0.883	
c / d_p	≤ 0.5		8.8.4.2
f_{ps}	$= f_{pu} * (1 - k_p * c / d_p)$	1,633 MPa	
k_p	$= 0.3$ for low-relaxation strand $= 0.4$ for smooth high-strength bars $= 0.5$ for deformed high strength bars	0.3	
c / d_p	$= \{ \varphi_p * A_{ps} * f_{pu} + \varphi_s * A_s * f_y - \varphi_s * A'_s * f_y - \alpha_1 * \varphi_c * f'_c * ht * (b - bw) \} / \{ \alpha_1 * \varphi_c * \beta_1 * f'_c * bw * d_p + \varphi_p * k_p * A_{ps} * f_{pu} \}$	0.407	OK
f_{ps}	$= f_{pu} [1 - 0.5 * (\mu_p * f_{pu} / f'_c)]$	1,371 MPa	14.14.1.2.4
μ_p	$= A_{sp} / A_c$	0.010	
a	$= \{ \varphi_p * A_{ps} * f_{ps} + \varphi_s * A_s * f_y - \varphi_s * A'_s * f_y - \alpha_1 * \varphi_c * f'_c * ht * (b - bw) \} / \{ \alpha_1 * \varphi_c * f'_c * bw \}$	183 mm 183 mm	
M_r	$= \varphi_p * A_{ps} * f_{ps} * (d_p - a/2) + \varphi_s * A_s * f_y * (d_s - a/2) - \varphi_s * A'_s * f_y * (d - d's) - \alpha_1 * \varphi_c * f'_c * ht * (b - bw) * (ht - a/2)$		
	$f_{ps} = 1,633 \text{ MPa}$	1,891 kN-m 1551 kN-m / m width	
	$f_{ps} = 1,371 \text{ MPa}$	1,602 kN-m 1314 kN-m / m width	Use

Material Properties

Prestressed concrete	f'_c	35 MPa
Prestressed steel	f_{pu}	1860 MPa
Reinforcing steel	f_y	300 MPa
Type of prestressing steel		low relaxation
Structural concrete (deck, barrier, etc.)		
Concrete	f'_c	30 MPa
Reinforcing steel	f_y	400 MPa

Resistance factors

Concrete	ϕ_c	0.75
Prestress steel	ϕ_p	0.95
Reinforcing steel	ϕ_s	0.9

Table 8.1

Dimensions

Width	b	1219 mm	
Total depth	h	710 mm	incl 100 mm thk deck
Prestressing strand		13 mm dia	
Total number of strands	A_{ps}	98 mm ²	
Reinforcing steel		16	
precast box cell girder	A_{s10}	100 mm ²	
cast-in-place concrete deck	A_{s25}	500 mm ²	

Distance from top of concrete

Bottom prestress steel			
layer 1	d_{p1}	509 mm	
layer 2	d_{p2}	458 mm	
layer 3	d_{p3}	407 mm	
Top prestressing steel			
layer 1	d'_{p1}	102 mm	
layer 2	d'_{p2}	51 mm	
Bottom reinforcing steel			
layer 1 (deck concrete)	d_{s1}	686 mm	
layer 2	d_{s2}	640 mm	
layer 3	d_{s3}	487 mm	
Top reinforcing steel			
layer 1	d'_{s1}	45 mm	

Area of steel

Bottom prestress steel			
layer 1	2 strands	A_{ps1}	196 mm ²
layer 2	2 strands	A_{ps2}	196 mm ²
layer 3	4 strands	A_{ps3}	392 mm ²
Top prestressing steel			
layer 1	4 strands	A'_{ps1}	392 mm ²
layer 2	4 strands	A'_{ps2}	392 mm ²
Bottom reinforcing steel			
layer 1	5 25M	A_{s1}	2500 mm ²
layer 2	5 10M	A_{s2}	500 mm ²
layer 3	4 10M	A_{s3}	400 mm ²
Top reinforcing steel			
layer 1	3 10M	A'_{s1}	300 mm ²

Calculations

	α_1	$= 0.85 - 0.0015 * f'_c$	0.798	
	β_1	$= 0.97 - 0.0025 * f'_c$	0.883	
	c / d_p	≤ 0.5		8.8.4.2
	f_{ps}	$= f_{pu} * (1 - k_p * c / d_p)$	1,822 MPa	
	k_p	$= 0.3$ for low-relaxation strand $= 0.4$ for smooth high-strength bars $= 0.5$ for deformed high strength bars	0.3	
	c / d_p	$= \{ \phi_p * A_{ps} * f_{pu} + \phi_s * A_s * f_y - \phi_p * A'_{ps} * f_{pu} \} / \{ \alpha_1 * \phi_c * \beta_1 * f'_c * b * d_p + \phi_p * k_p * A_{ps} * f_{pu} \}$	0.068	OK
OR	f_{ps}	$= f_{pu} [1 - 0.5 * (\mu_p * f_{pu} / f'_c)]$	1,770 MPa	14.14.1.2.4
	μ_p	$= A_{sp} / A_c$	0.002	
	a	$= \{ \phi_p * A_{ps} * f_{ps} + \phi_s * A_s * f_y - \phi_p * A'_{ps} * f_{ps} \} / \{ \alpha_1 * \phi_c * f'_c * b \}$	29 mm 29 mm	
	M_r	$= \phi_p * A_{ps} * f_{ps} * (d_p - a/2) + \phi_s * A_s * f_y * (d_s - a/2) - \phi_p * A'_{ps} * f_{ps} * (d'_p - a/2) - \phi_s * A'_s * f_y * (d - d'_s)$		
		$f_{ps} = 1,822 \text{ MPa}$	1,087 kN-m 891 kN-m / m width	
		$f_{ps} = 1,770 \text{ MPa}$	1,154 kN-m 947 kN-m / m width	Use

Shear Capacity of Box Cell Girder at h/2 from support

V_c	$= 2.5 * \beta * \phi_c * f_{cr} * b_v * d_v$		8.9.3.4
f_{cr}	$= 0.4 * \text{sqrt}(f'_c) \leq 3.2 \text{ MPa}$	2.4 MPa	
β		0.18	
V_c		245.3 kN	
V_s	$= \phi_s * f_y * A_v * d_v * \cot(\theta) / s$		8.9.3.5
θ		42 degrees = 0.733 rad	
s		300 mm	
A_v	6 15 M A_{s15}	1200 mm ²	
V_s	200 mm ²	767.7 kN	
V_p			
V_{total}	$= V_c + V_s + V_p$	1013.0 kN	$> V_f$

Material Properties

Prestressed concrete	f'_c	35 MPa
Prestressed steel	f_{pu}	1860 MPa
Reinforcing steel	f_y	300 MPa
Type of prestressing steel		low relaxation
Structural concrete (deck, barrier, etc.)		
Concrete	f'_c	30 MPa
Reinforcing steel	f_y	400 MPa

Resistance factors

Concrete	ϕ_c	0.75
Prestress steel	ϕ_p	0.95
Reinforcing steel	ϕ_s	0.9

Table 8.1

Dimensions

Width	b	1219 mm
Total depth	h	710 mm
Prestressing strand		13 mm dia
Total number of strands	A_{ps}	98 mm ²
Reinforcing steel		
precast box cell girder		10M
cast-in-place concrete deck		25M
	A_{s10}	100 mm ²
	A_{s25}	500 mm ²

Distance from top of concrete

Bottom prestress steel		
layer 1	d_{p1}	509 mm
layer 2	d_{p2}	458 mm
layer 3	d_{p3}	407 mm
layer 4	d_{p4}	356 mm
Top prestressing steel		
layer 1	d'_{p1}	102 mm
layer 2	d'_{p2}	51 mm
Bottom reinforcing steel		
layer 1 (deck concrete)	d_{s1}	686 mm
layer 2	d_{s2}	640 mm
layer 3	d_{s3}	487 mm
Top reinforcing steel		
layer 1	d'_{s1}	45 mm


Area of steel


Bottom prestress steel			
layer 1	2 strands	A_{ps1}	196 mm ²
layer 2	2 strands	A_{ps2}	196 mm ²
layer 3	2 strands	A_{ps3}	196 mm ²
layer 4	4 strands	A_{ps3}	392 mm ²
Top prestressing steel			
layer 1	6 strands	A'_{ps1}	588 mm ²
layer 2	6 strands	A'_{ps2}	588 mm ²
Bottom reinforcing steel			
layer 1	5 25M	A_{s1}	2500 mm ²
layer 2	5 10M	A_{s2}	500 mm ²
layer 3	4 10M	A_{s3}	400 mm ²
Top reinforcing steel			
layer 1	3 10M	A'_{s1}	300 mm ²


4 debonded strands
2 debonded stands


Calculations


	α_1	$= 0.85 - 0.0015 * f_c$	0.798	
	β_1	$= 0.97 - 0.0025 * f_c$	0.883	
	c / d_p	≤ 0.5		8.8.4.2
	f_{ps}	$= f_{pu} * (1 - k_p * c / d_p)$	1,858 MPa	
	k_p	$= 0.3$ for low-relaxation strand $= 0.4$ for smooth high-strength bars $= 0.5$ for deformed high strength bars	0.3	
	c / d_p	$= \{ \phi_p * A_{ps} * f_{pu} + \phi_s * A_s * f_y - \phi_p * A'_{ps} * f_{pu} \} /$ $\{ \alpha_1 * \phi_c * \beta_1 * f_c * b * d_p + \phi_p * k_p * A_{ps} * f_{pu} \}$		
			0.003	OK
OR	f_{ps}	$= f_{pu} [1 - 0.5 * (\mu_p * f_{pu} / f_c)]$	1,703 MPa	14.14.1.2.4
	μ_p	$= A_{sp} / A_c$	0.003	
	a	$= \{ \phi_p * A_{ps} * f_{ps} + \phi_s * A_s * f_y - \phi_p * A'_{ps} * f_{ps} \} / \{ \alpha_1 * \phi_c * f_c * b \}$		
			1 mm	
			1 mm	
M_r		$= \phi_p * A_{ps} * f_{ps} * (d_p - a/2) + \phi_s * A_s * f_y * (d_s - a/2) - \phi_p * A'_{ps} * f_{ps} * (d'_p - a/2) - \phi_s * A'_{s1} * f_y * (d - d'_{s1}) -$ $\phi_s * A'_{s2} * f_y * (d - d'_{s2})$		
	$f_{ps} =$	1,858 MPa	1,161 kN-m	
			952 kN-m / m width	
	$f_{ps} =$	1,703 MPa	1,114 kN-m	
			914 kN-m / m width	Use
























































































APPENDIX D: DRAWINGS

A1 SIZE 894mm x 841mm
PLOT: 3/28/2013 1:06:10 PM
FILE NAME: W12401300-T-001_RX.dwg Saved By: dlane




REMOVALS PLAN
SCALE: 1:250
0 5 10 15m

REMOVAL LEGEND
 - FULL DEPTH REMOVAL
 - PARTIAL DEPTH REMOVAL




SECTION "A" NORTH STRUCTURE
SIMILAR @ SOUTH STRUCTURE
SCALE: 1:25
0 0.5 1.0 1.5m

REMOVAL LEGEND
 - REMOVAL




SECTION "B" @ SU-4 EXP
SIMILAR @ SU-1 EXP
SCALE: 1:25
0 0.5 1.0 1.5m

REMOVAL LEGEND
 - REMOVAL



SECTION "C" @ SU-4 EXP
SIMILAR @ SU-1, SU-5 & SU-8 EXP
SCALE: 1:25
0 0.5 1.0 1.5m

REMOVAL LEGEND
 - REMOVAL



SECTION "D" @ SU-4 EXP
SIMILAR @ SU-1, SU-5 & SU-8 EXP
SCALE: 1:25
0 0.5 1.0 1.5m

REMOVAL LEGEND
 - REMOVAL

METRIC
WHOLE NUMBERS INDICATE MILLIMETRES
DECIMALIZED NUMBERS INDICATE METRES

DRAWING INDEX

1	DRAWING INDEX, REMOVALS PLAN & SECTIONS
2	GENERAL ARRANGEMENT & SECTIONS
3	EXPANSION JOINT DETAILS

SURVEY BAR - HORIZONTAL CONTROL POINTS - PROJECT COORDINATES

CONTROL POINT	LOCATION	NORTHING	EASTING	ELEVATION	NAD 83 DATUM
#1	SURVEY BAR @ S/W CRN PORTAGE AVE. & HARRIS BLVD.	N9961.972	E9926.527	234.512	N5526586.997 E623766.098
#2	SURVEY BAR @ N/W CRN PORTAGE AVE & BOOTH DR.	N10002.288	E10158.351	233.912	N5526550.165 E623998.527

GEODETIC BENCHMARK - VERTICAL CONTROL POINTS

GBM	LOCATION	ELEVATION
39-044 (GSCM 83R498)	N side Portage Ave @ Harris Blvd, Tbt on top of 0.05m dia x 2.4m iron pipe, 6.5m N of N curb line of Portage Ave & 2.2m E of CL of Conc Pvmnt of Harris Blvd produced from the South	233.848

EXISTING	LEGEND - PLAN	NEW	EXISTING	LEGEND - PLAN	NEW	EXISTING	LEGEND - PLAN	NEW	
	GAS		MANHOLE		CONCRETE PAVEMENT		LOCATION APPROVED		BM
	MTS		CATCH BASIN / CATCH PIT		CONC SIDEWALK / MEDIAN		SUPR. U/G STRUCTURES		ELEV
	HYDRO		CURB INLET WITH BOX		ASPHALT PAVEMENT		DATE		DATE
	CATV / FIBRE OPTIC		TREE		PAVING STONE		NOTE:		DATE
	TRAFFIC SIGNALS / PIT		TEST HOLE		GRAVEL		LOCATION OF UNDERGROUND STRUCTURES		DATE
	LAND DRAINAGE SEWER		PROPERTY LINE		RAMP CURB		EXISTENCE AND EXACT LOCATION OF ALL UTILITIES ARE SHOWN OR THAT THE GIVEN LOCATIONS ARE EXACT. CONFIRMATION OF EXISTENCE AND EXACT LOCATION OF ALL SERVICES MUST BE OBTAINED FROM THE INDIVIDUAL UTILITIES BEFORE PROCEEDING WITH CONSTRUCTION.		DATE
	SANITARY/COMBINED SEWER		SURVEY BAR		PLANING / REMOVAL		DATE		DATE
	SSP/DCP		FENCE		DATE		DATE		DATE
	WATERMAIN		BOC / EDGE OF PAVEMENT		DATE		DATE		DATE
	SUBDRAIN		ELEVATION		DATE		DATE		DATE
	DITCH		TRAFFIC SIGN		DATE		DATE		DATE

LOCATION APPROVED UNDERGROUND STRUCTURES

NO.	REVISIONS	DATE	BY
B	ISSUED FOR PRELIMINARY DESIGN REPORT	13/03/28	BE
A	ISSUED FOR CLIENT REVIEW	13/03/11	BE
No.	REVISIONS	YYMMDD	BY

MORRISON HERSHFIELD

DESIGNED BY	BE	CHECKED BY	RPB
DRAWN BY	DID	APPROVED BY	BWB
HOR. SCALE	AS SHOWN	RELEASED FOR CONSTRUCTION	
VERT. SCALE	AS SHOWN		
DATE	12/12/18	DATE	

PROFESSIONAL'S SEAL


CONSULTANT DRAWING No. W12401300-T-001_RX.dwg

THE CITY OF WINNIPEG
PUBLIC WORKS DEPARTMENT
ENGINEERING DIVISION

REHABILITATION OF THE PORTAGE AVENUE TWIN BRIDGES OVER STURGEON CREEK AND RELATED WORKS
PRELIMINARY ENGINEERING
DRAWING INDEX, REMOVALS PLAN & SECTIONS

CITY DRAWING NUMBER: N/A
SHEET 1 OF 3
DRAWING No. 1
REV B

MORRISON HERSHFIELD
Certificate of Authorization
MORRISON HERSHFIELD
No. 1736 Date: 13/03/01




GENERAL ARRANGEMENT



REPAIR LEGEND

[Pattern]	- FULL DEPTH REPAIR
[Pattern]	- PARTIAL DEPTH REPAIR




SECTION "E" SIDEWALK @ NORTH STRUCTURE
SIMILAR @ SOUTH STRUCTURE




LEGEND

[Pattern] - NEW APPLICABLE CONCRETE TYPE




SECTION "F" @ SU-4 EXP
SIMILAR @ SU-1 EXP




LEGEND

[Pattern] - NEW APPLICABLE CONCRETE TYPE




SECTION "G" @ SU-4 EXP
SIMILAR @ SU-1 EXP




LEGEND

[Pattern] - NEW APPLICABLE CONCRETE TYPE



SECTION "H" @ SU-4 EXP
SIMILAR @ SU-1, SU-5 & SU-8 EXP



LEGEND

[Pattern] - NEW APPLICABLE CONCRETE TYPE

METRIC
WHOLE NUMBERS INDICATE MILLIMETRES
DECIMALIZED NUMBERS INDICATE METRES

—	GAS	○	MANHOLE	●	CONCRETE PAVEMENT	[Pattern]
—	MTS	□	CATCH BASIN / CATCH PIT	■	CONC SIDEWALK / MEDIAN	[Pattern]
—	HYDRO	△	CURB INLET WITH BOX	▲	ASPHALT PAVEMENT	[Pattern]
—	CATV / FIBRE OPTIC	⊙	TREE	—	PAVING STONE	[Pattern]
—	TRAFFIC SIGNALS / PIT	⊕	TEST HOLE	—	GRAVEL	[Pattern]
—	LAND DRAINAGE SEWER	⊕-TH-12	PROPERTY LINE	—	RAMP CURB	[Pattern]
—	SANITARY/COMBINED SEWER	—	SURVEY BAR	—	PLANING / REMOVAL	[Pattern]
—	SSP/DCP	—	FENCE	—		
—	WATERMAIN	—	BOC / EDGE OF PAVEMENT	—		
—	SUBDRAIN	33.000	ELEVATION	(33.100)		
—	DITCH	—	TRAFFIC SIGN	—		
—	EXISTING	—	LEGEND - PLAN	—	EXISTING	LEGEND - PLAN
—	NEW	—	LEGEND - PLAN	—	NEW	LEGEND - PLAN

LOCATION APPROVED
UNDERGROUND STRUCTURES

SUPR. U/G STRUCTURES DATE COMMITTEE

NOTE:
LOCATION OF UNDERGROUND STRUCTURES AS SHOWN ARE BASED ON THE BEST INFORMATION AVAILABLE. BUT NO GUARANTEE IS GIVEN THAT ALL EXISTING UTILITIES ARE SHOWN OR THAT THE GIVEN LOCATIONS ARE EXACT. CONFIRMATION OF EXISTENCE AND EXACT LOCATION OF ALL SERVICES MUST BE OBTAINED FROM THE INDIVIDUAL UTILITIES BEFORE PROCEEDING WITH CONSTRUCTION.

BM	GBM No. 39-044 (GSCM-83R-498)		
ELEV	233.848m		
B	ISSUED FOR PRELIMINARY DESIGN REPORT	13/03/28	BE
A	ISSUED FOR CLIENT REVIEW	13/03/11	BE
No.	REVISIONS	YYMMDDI	BY

MORRISON HERSHFIELD

DESIGNED BY	BE	CHECKED BY	RPB
DRAWN BY	DID	APPROVED BY	BWB
HOR. SCALE	AS SHOWN	RELEASED FOR CONSTRUCTION	
VERT. SCALE	AS SHOWN		
DATE	12/12/18	DATE	

PROFESSIONAL'S SEAL

CONSULTANT DRAWING No.
W12401300-T-002_RX.dwg

THE CITY OF WINNIPEG
PUBLIC WORKS DEPARTMENT
ENGINEERING DIVISION

REHABILITATION OF THE PORTAGE AVENUE TWIN BRIDGES OVER STURGEON CREEK AND RELATED WORKS
PRELIMINARY ENGINEERING
GENERAL ARRANGEMENT & SECTIONS

CITY DRAWING NUMBER	N/A
SHEET	2 OF 3
DRAWING No.	2
REV	B

APEGM
Certificate of Authorization
MORRISON HERSHFIELD
No. 1736 Date: 13/03/01

A1 SIZE 894mm x 841mm
PLOT: 3/28/2013 1:06:33 PM
FILE NAME: W12401300-T-002_RX.dwg Saved By: dlane

