

City of Winnipeg
Chlorine Ventilation Upgrades
At Regional Pumping Stations
Tender Opportunity 415-2025

APPENDIX F
Asbestos Reports



2023 Asbestos Reassessment

G.C MacLean Pumping Station
and Reservoir
875 Lagimodiere Boulevard,
Winnipeg, Manitoba

Prepared for:

**City of Winnipeg Water and
Waste Department**

110-1199 Pacific Avenue
Winnipeg, Manitoba R3E 3S8

August 14, 2023

Pinchin File: 327243.000



2023 Asbestos Reassessment

G.C MacLean Pumping Station and Reservoir, 875 Lagimodiere Boulevard, Winnipeg,
Manitoba
City of Winnipeg Water and Waste Department

August 14, 2023
Pinchin File: 327243.000

Issued to: City of Winnipeg Water and Waste Department
Issued on: August 14, 2023
Pinchin File: 327243.000
Issuing Office: Winnipeg, MB

Author:

Ken Brydges, C.E.T. LEED GA
Senior Project Manager
204.452.0983
kbrydges@pinchin.com

Reviewer:

Rodney Legault, C.E.T. EP
Operations Manager
204.452.0983
rlegault@pinchin.com



EXECUTIVE SUMMARY

City of Winnipeg Water and Waste Department (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment of G.C MacLean Pumping Station and Reservoir located at 875 Lagimodiere Boulevard, Winnipeg, Manitoba. The reassessment was performed on June 13, 2023.

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM) and develop corrective action plans as required for the purposes of long-term management. The results of this assessment are not intended for construction, renovation, demolition or project tendering purposes.

SUMMARY OF FINDINGS

Asbestos-containing materials (ACM) are present as follows:

- Asbestos-containing parging cement is present as insulation on pipe system fittings throughout the building. Parging cement is friable and was jacketed with canvas. Parging cement was in GOOD condition.
- Asbestos-containing parging cement is present as duct insulation within Location No.'s 6, 7, 11, 16 and 19. The parging cement is a friable material. The parging cement was jacketed with canvas and is in GOOD condition except for 1 SF of damage rated in FAIR condition within Location No.6.
- Asbestos-containing preformed magnesia block is present as mechanical insulation within exhaust ducting within Location No.'s 18 and 19. Magnesia block is a friable material. The magnesia block is jacketed with metal and is in GOOD condition.
- Asbestos-containing transite boards are present as ceiling finish in the Main Floor Vestibule, Location No.10. Transite cement is a non-friable material which is in GOOD condition.
- Loose fill vermiculite was not observed in the assessed areas; however, demolition of masonry block walls was not performed and vermiculite may be present within these cavities.
- Asbestos-containing caulking is present on the exterior wall finish, Location No.22. Caulking is non-friable and is in GOOD condition.
- Setting compounds present on ceramic floor tiles within Location No.'s 1, 2, 3, 6 and 19 are presumed to contain asbestos. Setting compounds are potentially friable and are in GOOD condition.



SUMMARY OF RECOMMENDATIONS

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations.

1. The following items require immediate remedial action:
 - a. Repair following Moderate Risk procedures 1 SF of damaged/exposed parging cement on Fresh Air Intake duct within the Chlorine Analyzer Room, Location No. 6.
2. Perform a re-assessment of asbestos materials on an annual basis.
3. Prior to renovations or demolition, perform a pre-construction assessment to identify any hazardous materials that may be disturbed by the work.
4. Follow appropriate safe work procedures when handling or disturbing asbestos.

This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.



TABLE OF CONTENTS

| | | |
|--------------|--|---|
| 1.0 | INTRODUCTION AND SCOPE | 1 |
| 1.1 | Scope of Assessment | 1 |
| 2.0 | METHODOLOGY | 1 |
| 3.0 | BACKGROUND INFORMATION | 2 |
| 3.1 | Building Description | 2 |
| 3.2 | Existing Reports and Summary of Asbestos Abatement | 2 |
| 4.0 | FINDINGS | 2 |
| 4.1 | Pipe Insulation | 3 |
| 4.2 | Duct Insulation and Mastic | 3 |
| 4.3 | Mechanical Equipment Insulation | 3 |
| 4.4 | Vermiculite | 3 |
| 4.5 | Asbestos Cement Products (Transite) | 3 |
| 4.6 | Sealants, Caulking, and Putty | 3 |
| 4.7 | Roofing Products | 3 |
| 4.8 | Other Building Materials | 4 |
| 4.9 | Excluded Asbestos Materials | 4 |
| 5.0 | RECOMMENDATIONS | 5 |
| 5.1 | General | 5 |
| 5.2 | Remedial Work | 5 |
| 5.3 | On-going Management and Maintenance | 5 |
| 6.0 | TERMS AND LIMITATIONS | 5 |
| 7.0 | REFERENCES | 6 |
| APPENDICES | | |
| APPENDIX I | Methodology | |
| APPENDIX II | Additional Photographs | |
| APPENDIX III | Location Summary Report | |
| APPENDIX IV | Asbestos Material Summary Report / Sample Log | |
| APPENDIX V | HMIS Data Report | |



1.0 INTRODUCTION AND SCOPE

City of Winnipeg Water and Waste Department (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at 875 Lagimodiere Boulevard, Winnipeg, Manitoba.

Pinchin performed the reassessment on June 13, 2023. The surveyor was accompanied by City of Winnipeg Water and Waste Representatives during the reassessment. The assessed area was occupied at the time of the assessment.

The objectives of the reassessment were to document the locations, quantities and conditions of previously identified asbestos containing building materials and develop corrective action plans as required. This reassessment is only to be used for the purposes of long-term management and routine maintenance. The results of this reassessment are not to be used for construction, renovation, demolition or project tendering purposes.

1.1 Scope of Assessment

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM) and develop corrective action plans as required.

Additional objectives included the following:

- Documentation of any asbestos abatement that was performed since the last reassessment.
- Additional sampling to delineate previously identified ACM.

Please refer to Appendix I for a detailed description of the methodology used for this assessment.

2.0 METHODOLOGY

Pinchin conducted an inspection of previously identified asbestos-containing materials (ACM) to evaluate the current condition of all accessible materials identified in the most recent assessment. The surveyor made reference to any existing assessment or abatement reports (as provided by the Client).

As per the original scope of work, concealed locations such as ceiling spaces above solid ceilings, shafts and chases were accessed via existing access panels. Our investigation did not include demolition of drywall or plaster walls to view concealed conditions. Structural items or exterior building finishes were not removed to determine the presence of concealed materials.

For further details on the methodology including test methods, refer to Appendix I.



3.0 BACKGROUND INFORMATION

3.1 Building Description

| Description Item | Details |
|-------------------|---|
| Use | Pumping Station |
| Number of Floors | Single Storey with Mezzanine and Basement |
| Structure | Structure steel and concrete |
| Exterior Cladding | Masonry |
| HVAC | |
| Roof | Built-up roofing |
| Flooring | Concrete, ceramic tile |
| Interior Walls | Concrete |
| Ceilings | Transite, concrete |

3.2 Existing Reports and Summary of Asbestos Abatement

3.2.1 Review of Previous Reports

The reassessment was based on information gathered from previous comprehensive assessment report completed by Pinchin. The original assessment report for the G.C. MacLean Pumping Station and Reservoir was dated March 6, 2007. The results of the original report and subsequent survey update reports were reviewed prior to completing the reassessment.

3.2.2 Summary of Asbestos Abatement since the Previous Assessment

Abatement work has been completed on site since the last assessment. Based on a review of the above noted abatement reports, and observations made during the reassessment, the following abatement work has been conducted, since completion of the previous report:

- Damaged/exposed parging cement rated in FAIR condition was removed from 3 rainwater leader fittings within Upper Walkway, Location No. 12.

4.0 FINDINGS

The following section summarizes the findings of the reassessment and provides a general description of the asbestos-containing materials (ACM) identified and their locations.

For details on approximate quantities, condition, friability and locations of asbestos materials; refer to the Asbestos Material Summary Report and All Data Report in Appendix IV and V.



4.1 Pipe Insulation

Asbestos-containing parging cement present on pipe fittings of pipe systems in the Chlorine Scale Room (Location No. 7), Chlorine Tonner Room (Location No. 9), Ammonia Room (Location No. 11), Upper Walkways (Location No. 12), Stairwell (Location No. 14), Pump Floor (Location No. 19), Maintenance Room (Location No. 20), and Valve Room (Location No. 21) have been maintained in GOOD condition.

4.2 Duct Insulation and Mastic

Asbestos-containing parging cement is present as duct insulation within the Chlorine Analyser Room (Location No. 6), Chlorine Scale Room (Location No. 7), Ammonia Room (Location No. 11), Fan Room (Location No. 16), and Pump Floor (Location No. 19). Parging cement is a friable material which is jacketed with canvas and is in GOOD condition except for 1 SF of damage rated in FAIR condition within Location No.6.

4.3 Mechanical Equipment Insulation

Asbestos-containing preformed magnesia block insulation is present on the generator exhaust in the Mezzanine Generator Room (Location No. 18), and Pump Floor (Location No.19). Magnesia block is a friable material which is jacketed with metal and is in GOOD condition.

4.4 Vermiculite

Loose fill vermiculite was not observed within the assessed areas; however, demolition of masonry block walls was not performed, and vermiculite may be present within these cavities. Vermiculite debris was not observed.

4.5 Asbestos Cement Products (Transite)

Asbestos-containing transite boards present as a ceiling finish in the Main Floor Vestibule (Location No. 10) are non-friable and are in GOOD condition.

4.6 Sealants, Caulking, and Putty

Asbestos-containing beige and grey caulking present on the exterior wall finish (Location No. 22) is non-friable material which is in GOOD condition.

4.7 Roofing Products

Built-up roofing materials have not been sampled and are presumed to contain asbestos. Destructive testing will be required prior to any renovation or demolition activities.



4.8 Other Building Materials

Setting compounds present on ceramic floor tiles within Location No.'s 1, 2, 3, 6 and 19 are presumed to contain asbestos. Setting compounds are potentially friable and are in GOOD condition.

4.9 Excluded Asbestos Materials

The following is a list of materials which may contain asbestos and was excluded from the assessment.

These materials are presumed to contain asbestos until otherwise proven by sampling and analysis:

- Floor levelling compound
- Elevator and lift brakes
- Electrical components
- Moulded plastic components (laboratory bench tops)
- Refractory materials and insulations in boilers, and stacks
- Insulation under metal clad boilers
- Mechanical packing, ropes and gaskets
- Adhesives and duct mastics
- Fibre-reinforced paints and coatings
- Paper products
- Soffit and fascia boards
- Fire resistant doors
- Metal clad finishes (Galbestos)
- Stucco, plaster or other cementitious parge coatings
- Vibration dampers on HVAC equipment
- Terrazzo
- Ropes and gaskets in cast-iron bell and spigot joints
- Sealants on pipe threads



5.0 RECOMMENDATIONS

5.1 General

Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include; destructive testing (e.g. coring and/or removal of building finishes and components), sampling of other hazardous materials (lead, mercury, PCBs, mould, etc.), and materials not tested in this study (e.g. roofing materials, caulking, mastics).

5.2 Remedial Work

The following remedial work is recommended.

| Material, Quantity & Condition | Location Name (Location #) | Recommended Procedure |
|-------------------------------------|------------------------------|---|
| Parging cement, 1 SF fair condition | Ducting within Location No.6 | Repair in accordance with moderate risk procedures. |

5.3 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the asbestos materials identified.

Perform a re-assessment of asbestos materials on an annual basis.

Remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.

Update the asbestos inventory report for the building upon completion of any abatement of ACM.

6.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.



7.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

Manitoba

1. Workplace Safety and Health Act W210.
2. Workplace Safety and Health Hazard Regulation (Manitoba Regulation 217/2006), under the Workplace Safety and Health Act.
3. Manitoba Regulation MR 474/88, Manitoba PCB Regulation made under The Dangerous Goods Act.
4. Guide for Asbestos Management – Safe Work Manitoba.
5. Guideline Managing Demolition Debris Containing Hazardous Materials – Environmental Enforcement and Compliance Branch – Manitoba Conservation and Climate

Federal

1. Canada Occupational Health and Safety Regulation, SOR/86-304.
2. Consolidated Transportation of Dangerous Goods Regulations, including Amendment SOR/2019-101, Transportation of Dangerous Goods Act.

\\pinchin.com\wpg\Job\327000s\0327243.000 CITYOFWINNIPE,PropertyMB,2023,ASB,CONS\Deliverables\Maclean Pumping Station\327243 Asbestos Reassessment Report, GC Maclean Pumping Station & Reservoir, COWWW, Aug 14 2023.docx

Template: Master Report for Asbestos Reassessment, HAZ, March 2, 2023

APPENDIX I
Methodology



1.0 GENERAL

Pinchin conducted an inspection of previously identified asbestos-containing materials (ACM) to evaluate the current condition of all accessible ACM identified in the most recent assessment.

The surveyor made reference to any existing assessment or abatement reports (as provided by the Client).

Materials listed as exclusions in the previous reports have remained as exclusions. Sampling, assessment or verification of excluded materials was not conducted.

Existing sampling data, where available, was reviewed and relied upon.

Where sampling was conducted, sample collection was conducted in accordance with our Standard Operating Procedures.

A separate set of samples was collected of each type of homogenous material suspected to contain asbestos. A homogenous material is defined by the US EPA as material that is uniform in texture and appearance, was installed at one time, and is unlikely to consist of more than one type or formulation of material. The homogeneous materials were determined by visual examination and available information on the phases of construction and prior renovations.

Samples were collected at a rate that is in compliance with the requirements of local regulations and guidelines. The sampling strategy was also based on known ban dates and phase out dates of the use of asbestos; sampling of certain building materials is not conducted after specific construction dates. In addition, to be conservative, several years past these dates are added to account for some uncertainty in the exact start / finish date of construction and associated usage of ACM. In some cases, manufactured products such as asbestos cement pipe were visually identified without sample confirmation.

The asbestos analysis was completed using a stop-positive approach. Only one result meeting the regulated criteria was required to determine that a material is asbestos-containing, but all samples must be analyzed to conclusively determine that a material is non-asbestos. The laboratory stopped analyzing samples from a homogeneous material once a result equal to or greater than the regulated criteria is detected in any of the samples of that material. All samples of a homogeneous material were analyzed if no asbestos is detected. In some cases, all samples were analyzed in the sample set regardless of result.

The analysis was performed in accordance with Test Method EPA/600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials, July 1993.

The following summarizes the criteria of asbestos definitions. If there is a conflict between federal and provincial criteria, the more stringent will apply.



| Jurisdiction | Friable | Non-Friable |
|---------------------|-------------------|--------------------|
| Manitoba | 0.1% ¹ | 1% |
| Federal | 1% | 1% |

Where building materials are described in the report as “non-asbestos” or “does not contain asbestos”, this means that either no asbestos was detected by the analytical method utilized in any of the multiple samples or, if detected, it is below the lower limit of an asbestos-containing material in the applicable regulation. Additionally, these terms are used for materials which historically are known to not include asbestos in their manufacturing.

Asbestos materials are evaluated in order to make recommendations regarding remedial work. The priority for remedial action is based on several factors:

- Friability (friable or non-friable).
- Condition (good, fair, poor, debris).
- Accessibility (ranking from accessible to all building users to inaccessible).
- Visibility (whether the material is obscured by other building components).
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition).

For a complete description of the Evaluation Criteria and Basis of Recommendations, refer to Annex A.

Template: Methodology for Asbestos Reassessment, HAZ, July 27, 2021

METHODOLOGY ANNEX A EVALUATION CRITERIA

1.0 EVALUATION CRITERIA AND BASIS OF RECOMMENDATIONS

The detailed asbestos assessment provides information regarding the location, condition, accessibility and friability of the asbestos-containing materials (ACM). In order to make recommendations for compliance with current regulations, Pinchin developed the following criteria.

2.0 EVALUATION OF CONDITION

2.1 Friable Sprayed or Trowelled Fireproofing, Thermal Insulation and Texture Finishes (Surfacing Materials)

To evaluate the condition of ACM sprayed or trowelled on fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes, the following criteria are applied:

| | |
|-------------|---|
| Good | Surface of material shows no significant signs of damage, deterioration or delamination. Good condition includes unencapsulated or unpainted fireproofing or texture finishes, where no or limited delamination or damage is observed, or encapsulated fireproofing or texture finishes where the encapsulant or paint has been applied after the damage or fallout occurred. |
| Poor | A sprayed material that shows signs of significant damage or is significantly delaminating or deteriorating. This may be limited to surface delamination or some portion of the substrate may be exposed. |

In Locations where damage exists in isolated areas, both good and poor condition may be applicable. The extent of each condition will be recorded. Fair condition is not utilized in the evaluation of ACM sprayed or trowelled fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes.

The evaluation of the above products above ceilings may be limited by the number of observations and by building components such as ducts or full height walls that obstruct the above ceiling observations.

2.2 Friable Mechanical or Thermal System Insulation (TSI)

To evaluate the condition of mechanical insulation on vessels, boilers, breeching, ducts, pipes, fan units, equipment etc. the following criteria are applied:

| | |
|-------------|---|
| Good | Insulation is completely covered in jacketing and exhibits no evidence of damage or deterioration. No insulation is exposed. Includes conditions where the jacketing has minor damage (i.e. scuffs or stains), but the jacketing is not penetrated. |
| Fair | Minor penetrating damage to jacketed insulation (cuts, tears, nicks, deterioration or delamination) or undamaged insulation that has never been jacketed. Insulation is exposed but not showing surface disintegration. The extent of missing insulation ranges from minor to none. Damage can be repaired. |

| | |
|-------------|---|
| Poor | Original insulation jacket is missing, damaged, deteriorated or delaminated. Insulation is exposed and significant areas have been dislodged. Damage cannot be readily repaired. Includes components where insulation may have been removed incompletely. |
|-------------|---|

The evaluation of mechanical insulation may be limited by the number of observations made and building components such as ducts or full height walls that obstruct observations. It is often not possible to observe each foot of mechanical insulation from all angles.

2.3 Potentially Friable Materials and Miscellaneous Friable Materials

Potentially friable ACM are products that are basically non-friable while in place but have the potential to generate friable dust upon removal or if significantly disturbed without appropriate procedures. These products may become friable if damaged. Potentially friable materials include materials such as acoustic ceiling tiles and plaster. To evaluate the condition of potentially friable materials, the following criteria are applied:

| | |
|-------------|--|
| Good | No significant damage or deterioration. Still serving its intended use as a building material or finish. |
| Fair | Showing signs of some cracking or breakage, but is not deteriorating (e.g. cracked plaster, broken but in place ceiling tile, missing tile or section of plaster etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes. |
| Poor | Significant deterioration or breaking apart of the material. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material has deteriorated to a point it has become friable. Normally potentially friable ACM in Poor condition is not repairable and requires at least localized removal and replacement. |

2.4 Non-Friable Materials

Non-friable ACM cover a wide range of products with a wide variation in their tendency to release dust or asbestos fibres to the air. Many of these materials, (particularly where the matrix is an unweathered bitumen, asphalt or tar material) do not release fibres except in very unusual circumstances or during significant disturbance (e.g. use of abrasive power tools). Others with a cementitious matrix (asbestos-cement products) can more readily release dust due to abrasion, demolition, weathering, etc. The potential for asbestos release from non-friable ACM is always lower than from friable ACM. To evaluate the condition of non-friable Materials, the following criteria are applied:

| | |
|-------------|--|
| Good | No significant damage or deterioration. Still serving its intended use as a building material or finish. |
|-------------|--|

| | |
|-------------|---|
| Fair | Showing signs of some cracking or breakage but is not deteriorating (e.g. cracked vinyl floor tile, missing piece of tile or transite, etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes. |
| Poor | Significant deterioration or breaking apart of the material to the point at which it cannot be repaired, and it will require at least local removal. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material may have deteriorated to a point where traffic or disturbance may cause it to become friable. |

2.5 Evaluation of ACM Debris

The identification of the exact location or presence of debris on the top of ceiling tiles is limited by the number of observations made and the presence of building components such as ducts or full height walls that obstruct observations.

The presence of fallen or dislodged ACM is noted separately from the ACM source and is referred to as Debris. Debris may be friable if from a friable ACM source or a badly deteriorated non-friable ACM source. Debris may also be non-friable (such as fallen pieces of transite sheet or mastic fittings, or broken, dislodged floor tiles).

| | |
|---------------|--|
| Debris | Debris may be friable or non-friable but is always identified as debris. |
|---------------|--|

2.6 Evaluation of Presumed Asbestos-Containing Material (PACM)

Presumed asbestos-containing materials (PACM), are building materials that may contain asbestos but were not sampled or analyzed due to inaccessibility or the need to perform destructive testing to obtain a reasonable sample set. Evaluation of these materials is based on the assumption that these PACM are asbestos-containing.

A list of PACM is provided in the report and they are generally not included in the detailed room by room reports. Typically, they are excluded because they are inaccessible or present in very small quantities. If PACM are evaluated, Pinchin uses the criteria that correspond with the type (and friability) of the material listed above.

3.0 EVALUATION OF ACCESSIBILITY

The accessibility of building materials known or suspected of being ACM is rated according to the following criteria:

| | |
|-----------------------------------|--|
| Access (A) | Common areas of the building within reach of all building users (approximately 8' - 9' from floor or standard ceiling height). Includes other areas where occupant activities may result in disturbance of material that is not normally within reach from floor level, but may be disturbed by common activities (e.g. gymnasiums, workshops) |
| Access (B) | Areas of the building accessed primarily by Maintenance/Caretaking/Janitorial Staff and within reach without use of a ladder. Includes areas within reach in Boiler Rooms, Electrical Rooms, Janitors Closets, Elevator Rooms, Mechanical Rooms, etc. Includes materials within reach from fixed ladders or catwalks, mezzanines, and accessible pipe chases. |
| Access (C) and Visible | Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Only includes ACM that are visible to view without the removal or opening of other building components such as ceiling tiles or service access panels. Visible column on HMIS sheets will say YES. |
| Access (C) and not Visible | Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Includes ACM that are not visible to view and require the removal of a building component to see, such as ceilings tiles or access panels to view and access. Includes rarely entered crawl spaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. Visible column on HMIS sheets will say NO. |
| Access (D) | Areas of the building behind inaccessible solid ceiling systems, walls or equipment etc. where demolition of the ceiling, wall or equipment etc. is required to reach the ACM. Material inaccessible due to height or location or is only accessed under unusual situations. Evaluation of condition and extent of ACM is limited or impossible, depending on the surveyor's ability to visually examine materials in Access D. |

4.0 ACTION MATRIX AND DEFINITIONS

Pinchin's evaluation of the viability of a specific asbestos control option is based on the consideration of the friability, condition, accessibility and visibility of a material. The logic used is that damaged ACM located in an area frequently accessed by all building occupants is of a higher priority than damaged ACM located in an infrequently accessed service area. The action matrix considers the potential for fibre release (primarily from friable ACM) and the possible concerns from regulatory bodies and many building occupants to all damaged ACM (including non-friable).

In any building with asbestos, many current regulations require an Asbestos Management Program be implemented. Depending on the condition and the accessibility, more active measures such as repair or removal may be recommended. The following matrix provides guidance for recommended Actions in the absence of renovation or demolition. In the event of construction or maintenance activity which will disturb ACM more aggressive control or removal will be required.

4.1 Action Matrix

The following tables outline the action decisions based on the relationship of assessed factors. Table I applies to friable ACM. Table II applies to non-friable ACM.

Table I Decision Matrix for Friable ACM

| Access | Condition | | | Debris |
|-----------------|-----------------------|-----------------------|----------|----------|
| | Good | Fair | Poor | |
| (A) | Action 5 ¹ | Action 5 ² | Action 3 | Action 1 |
| (B) | Action 7 | Action 6 ³ | Action 3 | Action 1 |
| (C) Visible | Action 7 | Action 6 | Action 3 | Action 2 |
| (C) Not Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (D) | Action 7 | Action 7 | Action 7 | Action 7 |

Table II Decision Matrix for Potentially Friable and Non-Friable ACM

| Access | Condition | | | Debris |
|-----------------|-----------|-----------------------|----------|----------|
| | Good | Fair | Poor | |
| (A) | Action 7 | Action 7 ⁴ | Action 3 | Action 1 |
| (B) | Action 7 | Action 7 | Action 3 | Action 1 |
| (C) Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (C) Not Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (D) | Action 7 | Action 7 | Action 7 | Action 7 |

4.2 Action Definitions

The following are the definitions in the Action Matrix Table presented above:

| Action Definitions | |
|--------------------|--|
| Action 1 | Clean-Up of ACM Debris Restrict access that is likely to cause a disturbance of the ACM Debris and clean up ACM Debris. Utilize appropriate asbestos precautions. |

¹ If friable ACM in access (A)/Good condition is not proactively removed Action 7 (Manage) is recommended.

² If friable ACM in access (A)/Fair condition is not proactively removed repair is recommended.

³ If friable ACM in access (B)/Fair condition is likely to be disturbed after repair proactive removal is recommended.

⁴ Action 7 is recommended for all non-friable ACM in Fair condition however some clients may wish to repair or take some action primarily for cosmetic reasons

Action Definitions

| | |
|-----------------|--|
| Action 2 | <p>Precautions for Access Which may Disturb ACM Debris</p> <p>Use appropriate means to isolate the debris or to limit entry to the area which may disturb the material. At locations where ACM Debris can remain in place in lieu of removal or clean-up (e.g. Debris on top of ceiling tiles or behind lockable door), Utilize appropriate asbestos precautions to enter the area if this will disturb debris. The precautions will be required until the ACM Debris has been cleaned up.</p> |
| Action 3 | <p>ACM Removal</p> <p>Remove ACM. Utilize asbestos procedures appropriate to the scope of the removal work. Until it is removed, restrict access to the material so it is not disturbed.</p> |
| Action 4 | <p>Precautions for Work Which may Disturb ACM in Poor Condition. Utilize appropriate asbestos precautions if ACM may be disturbed by work on or near ACM. This does not require restricting access to the area, only control of work which may contact or disturb the ACM. Removal is the only viable option if work will disturb ACM.</p> |
| Action 5 | <p>Proactive ACM Removal</p> <p>Remove friable ACM where the presence of friable asbestos in Good condition is not desirable. If friable ACM in Fair condition is not removed, then Repair friable ACM.</p> |
| Action 6 | <p>ACM Repair</p> <p>Repair friable ACM in Fair condition which is not likely to be damaged again or disturbed by normal use of the area or room. Pinchin recommends proactive removal if friable ACM is likely to be damaged or disturbed during normal use of the area or room</p> |
| Action 7 | <p>Asbestos Management Program with Routine Surveillance Implement an Asbestos Management Program, including routine surveillance of ACM. Reassess materials regularly (typically once per year).</p> |

Master Template: Methodology Annex A to Appendix I Evaluation Criteria, HAZ, January 10, 2020

APPENDIX II
Additional Photographs




V0002 (Confirmed Asbestos), Piping, Domestic Water (Hot and Cold), Parging over Fiberglass, Pump Floor (Location #: 19)



V0002 (Confirmed Asbestos), Piping, Domestic Water (Hot and Cold), Parging over Fibreglass, Maintenance Room (Location #: 20)




V0002 (Confirmed Asbestos), Piping, Rain Water Leader, Parging over Fibreglass, Chlorine Scale Room (Location #: 7)



V0004 (Confirmed Asbestos), Piping, Rain Water Leader, Parging over Fibreglass, Ammonia Room (Location #: 11)



V0004 (None), Piping, Domestic Water (Hot and Cold), Abated Material, North Mezzanine (Location #: 15)



V0004 (Confirmed Asbestos), Piping, Rain Water Leader, Parging over Fiberglass, Chlorine Tonner Room (Location #: 9)



V0005 (Confirmed Asbestos), Duct, Fresh Air Intake, Fiberglass w/Parging, Ammonia Room (Location #: 11)



V0005 (Confirmed Asbestos), Duct, Fresh Air Intake, Fiberglass w/Parging, Fan Room (Location #: 16)



V0005 (Confirmed Asbestos), Duct, Fresh Air Intake, Fiberglass w/Parging, Chlorine Analyzer Room (Location #: 6)




S0005 (Confirmed Asbestos), Duct, Fresh Air Intake, Fiberglass w/Parging, Chlorine Scale Room (Location #: 7)



S0006 (Confirmed Asbestos), Mechanical Equipment, Generator Exhaust, Magnesia block, Generator Room (Location #: 18)



V0006 (Confirmed Asbestos), Duct, Exhaust, Magnesia block, Pump Floor (Location #: 19)



V9500 (Presumed Asbestos), Wall, All, Vermiculite/concrete block walls, Vestibule (Location #: 1)



V9500 (Presumed Asbestos), Floor, All, Mortar, Vestibule (Location #: 1)




V9500 (Presumed Asbestos), Floor, All, Mortar, Pump Floor (Location #: 19)



V9500 (Presumed Asbestos), Wall, All, Vermiculite/concrete block walls, Washroom (Location #: 3)



V9500 (Presumed Asbestos), Floor, All, Mortar, Washroom (Location #: 3)



Structure, Vestibule (Location #: 10)

APPENDIX III
Location Summary Report

Client: Cowww

Site: 875 Lagimodiere Boulevard, Winnipeg, MB

Building Name: MacLean Pumping Station

Survey Date:

Last Re-Assessment: 2023-06-13

Building Phases: A:

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|--|----------------------|-------------|-------------|---|
| 1 | Vestibule | 80 | Main | A | Masonry walls suspect to contain vermiculite. Setting compound on ceramic tiles is presumed asbestos containing. |
| 2 | Lobby | 150 | Main | A | Masonry walls suspect to contain vermiculite. Setting compound on ceramic tiles is presumed asbestos containing. |
| 3 | Washroom | 120 | Main | A | Masonry walls suspect to contain vermiculite. Setting compound on ceramic tiles is presumed asbestos containing. |
| 4 | Control Room | 792 | Main | A | Masonry walls suspect to contain vermiculite. |
| 5 | North Stairwell | 200 | Main | A | Masonry walls suspect to contain vermiculite |
| 6 | Chlorine Analyzer Room | 300 | Main | A | Damaged/exposed parging cement on 1 SF air intake - June 29, 2021. Masonry walls suspect to contain vermiculite. setting compound on ceramic tiles is presumed asbestos containing. |
| 7 | Chlorine Scale Room | 300 | Main | A | Masonry walls suspect to contain vermiculite. |
| 8 | Vestibule | 200 | Main | A | |
| 9 | Chlorine Tonner Room | 1200 | Main | A | Masonry walls suspect to contain vermiculite. |
| 10 | Vestibule | 80 | Main | A | Masonry walls suspect to contain vermiculite. |
| 11 | Ammonia Room | 160 | Main | A | Masonry walls suspect to contain vermiculite. |
| 12 | Upper Walkways | 2200 | Main | A | Exterior masonry wall at overhead door inspected for vermiculite. Wall is not insulated. Remaining masonry walls suspect to contain vermiculite. Mortar sampled S0014A-C, 0015A-C April 3, 2023 |
| 13 | Stairwell | 160 | Main | A | Masonry walls suspect to contain vermiculite. |
| 14 | Stairwell | 200 | Mezzanine | A | Masonry walls suspect to contain vermiculite. |
| 15 | North Mezzanine | 600 | Mezzanine | A | Masonry walls suspect to contain vermiculite. |
| 16 | Fan Room | 3600 | Mezzanine | A | Masonry walls suspect to contain vermiculite. |
| 17 | Stairwell | 160 | Mezzanine | A | Masonry walls suspect to contain vermiculite. |
| 18 | Generator Room | 300 | Mezzanine | A | Masonry walls suspect to contain vermiculite |
| 19 | Pump Floor | 5400 | Lower Level | A | Masonry walls suspect to contain vermiculite. setting compound on ceramic tiles is presumed asbestos containing. |
| 20 | Maintenance Room | 600 | Lower Level | A | |
| 21 | Valve Room | 3600 | Lower Level | A | Room Not accessible June 29, 2021 |
| 22 | MacLean Pump Station Building Exterior | 0 | NA | A | Masonry walls suspect to contain vermiculite. Roof sections needs to be tested prior to any renovation or demolition activities |

APPENDIX IV
Asbestos Material Summary Report / Sample Log

Client: Cowww

Site: 875 Lagimodiere Boulevard, Winnipeg, MB

Building Name: MacLean Pumping Station

Survey Date:

| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
|----------|-----------|---|-----------------|-------------|-----|-----|-----|-----|---------------|----------|------------|
| Asbestos | V0002 | Piping Rain Water Leader, Domestic Water (hot And Cold) Parging Over Fibreglass Parging/ftg/dw/location 3 | 7,14,19,20,21 | A | 0 | 0 | 188 | 0 | Chrysotile | Yes | F |
| Asbestos | S0003 | Piping Rain Water Leader, Domestic Water (hot And Cold) Sweat Wrap Pipe Insulation Sweatwrap/rwl/location 4 - 2 Phases | 4,9,11,12,14,16 | A | 179 | 0 | 0 | 0 | None Detected | No | |
| Asbestos | S0004 | Piping Rain Water Leader Parging Over Fibreglass Parging/ftg/rwl/location 12 | 9,11,12 | A | 0 | 0 | 9 | 0 | Chrysotile | Yes | F |
| Asbestos | S0005 | Duct Fresh Air Intake Fibreglass W/parging Parging/fai/location 7 | 6,7,11,16 | A | 0 | 575 | 0 | 0 | Chrysotile | Yes | F |
| Asbestos | S0006 | Mechanical Equipment, Duct Generator Exhaust, Exhaust Magnesia Block Magblock | 18,19 | A | 64 | 0 | 0 | 0 | Chrysotile | Yes | F |
| Asbestos | S0007 | Other Ceiling Tiles (glue-on) Glue On Tile/12x12, Location 19 | 19 | A | 0 | 36 | 0 | 0 | None Detected | No | |
| Asbestos | S0008 | Piping Domestic Water (hot And Cold) Sweat Wrap Pipe Insulation Sweat Wrap Insulation On Straight Pipe, Domestic Water Supply, Mezzanine (location 15), Maclean Pumping Station | 15 | A | 30 | 0 | 0 | 0 | None Detected | No | |
| Asbestos | S0009 | Wall Exterior Plaster Stucco Plaster, Exterior Bottom Wall, Maclean Pumping Station (sample No. 0020- August 27, 2015 - 1517151_plm) (for Sample 0009b-c It Was Sample No. 0020b-c- June 30, 2016 - B131169) | 22 | A | 0 | 43 | 0 | 0 | None Detected | No | |
| Asbestos | S0010 | Wall Base Plaster Plaster On Concrete, Exterior Bottom Wall, Maclean Pumping Station (sample No. 0021- August 27, 2015 - 1517151_plm) (for Sample 0010b-c It Was Sample No. 0021b-c- June 30, 2016 - B131169) | 22 | A | 0 | 300 | 0 | 0 | None Detected | No | |
| Asbestos | S0011 | Wall, Other Exterior Caulking Caulking, Exterior Wall, Maclean Pumping Station (sample No. 0022- August 27, 2015 - 1517151_plm) (for Sample 0011b-c It Was Sample No. 0022b-c- June 30, 2016 - B131169) | 22 | A | 0 | 4 | 0 | 100 | Chrysotile | Yes | NF |
| Asbestos | S0012 | Piping Chilled Water Supply Parging Over Fibreglass Parging, Fitting, Chilled Water Supply, Location 16, Fan Room, Mezzanine, Maclean Pumping Station (for Sample 0012 It Was Sample No. 0038- June 30, 2016 - B131169), Maclean Pumping Station (for Sample 0012b & C It Was June 13, 2017 - | 16 | A | 0 | 0 | 18 | 0 | None Detected | No | |

| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
|----------|-----------|--|--|-------------|----|------|----|-----|--------------------|----------|------------|
| | | B171926) | | | | | | | | | |
| Asbestos | S0013 | Piping Chilled Water Return Parging Over Fibreglass Parging, Fitting, Chilled Water Return, Location 16, Fan Room, Mezzanine, Maclean Pumping Station (for Sample 0013 It Was Sample No. 0039- June 30, 2016 - B131169), Maclean Pumping Station (for Sample 0013b & C It Was June 13, 2017 - B171926) | 16 | A | 0 | 0 | 10 | 0 | None Detected | No | |
| Asbestos | S0014 ABC | Wall Mortar Off White | 12 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0015 ABC | Wall Mortar Of White | 12 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | V9000 | Ceiling Cement Product | 10 | A | 0 | 80 | 0 | 0 | Confirmed Asbestos | Yes | NF |
| Asbestos | V9500 | Floor All Mortar | 1,2,3,6,19 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | NF |
| Asbestos | V9500 | Wall Fascia Plaster | 22 | A | 0 | 300 | 0 | 0 | Presumed Asbestos | Yes | PF |
| Asbestos | V9500 | Wall All Vermiculite/concrete Block Walls | 1,2,3,4,5,6,7,9,11,12,13,14,16,17,18,19,22 | A | 0 | 7135 | 0 | 100 | Presumed Asbestos | Yes | F |
| Asbestos | V0000 | Mechanical Equipment Heating Water Tank Fibreglass | 3 | A | 0 | 0 | 0 | 100 | Non Asbestos | No | |
| Asbestos | V0000 | Piping Domestic Water (hot And Cold), Gas Pipe Line Not Insulated | 3,6,18 | A | 0 | 0 | 0 | 100 | Non Asbestos | No | |

Legend:

| Sample number | | Units | | |
|---------------|--|-------|-------------|---------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | NF Non Friable material. |
| L#### | Paint sample collected | LF | Linear feet | F Friable material |
| P#### | PCB sample collected | EA | Each | PF Potentially Friable material |
| M#### | Mould sample collected | % | Percentage | |
| V#### | Material visually similar to numbered sample collected | | | |
| V0000 | Known non Hazardous Material | | | |
| V9000 | Material is visually identified as Hazardous Material | | | |
| V9500 | Material is presumed to be Hazardous Material | | | |
| [Loc. No.] | Abated Material | | | |

APPENDIX V
HMIS Data Report

Client: Cowww
Location: #1 : Vestibule
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 80

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|----------------------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | | | | | | | | | | | | | | |
| Duct | Not Found | NI | | | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Floor | All | Mortar | Surface | Ceramic Tiles | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Mechanical Equipment | Not Found | NI | | | | | | | | | | | | | | |
| Other | Not Found | NI | | | | | | | | | | | | | | |
| Piping | Not Found | NI | | | | | | 800 | | | | | | | | |
| Structure | Beam, Deck | Concrete (precast) | | | | | | 800 | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | ALL | | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite. Setting compound on ceramic tiles is presumed asbestos containing.

Client: Cowww
Location: #2 : Lobby
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 150

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|----------------------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Metal | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | All | Mortar | Surface | Ceramic Tiles | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | ALL | N/A | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite. Setting compound on ceramic tiles is presumed asbestos containing.

Client: Cowww
Location: #3 : Washroom
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 120

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Metal | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | All | Mortar | Surface | Ceramic Tiles | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Mechanical Equipment | Heating Water Tank | Fibreglass | Surface | Foil Face | B | Y | | 100 | | | % | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Heating Water Tank | Horsehair | Surface | Canvas | B | Y | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Fibreglass | Straight | Canvas | B | Y | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Not Insulated | Fitting | N/A | B | Y | | 100 | | | % | V0000 | Non-Asbestos | | None | |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | ALL | | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite. Setting compound on ceramic tiles is presumed asbestos containing.

Client: Cowww
Location: #4 : Control Room
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 792

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Metal | No Information | NI | | | | | | | | | | | | |
| Duct | | Foil Face | | | | | | | | | | | | | | |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Electrical Panel | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Fibreglass | Straight | Canvas | B | Y | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Abated Material | Fitting | Canvas | B | Y | | | | | EA | V0002 | [None] | 25-50% | [Abated] | |
| Piping | Rain Water Leader | Sweat Wrap pipe insulation | Straight | Canvas | B | Y | | 12 | | | LF | S0003 | None Detected | N.D. | None | |
| Piping | Rain Water Leader | Sweat Wrap pipe insulation | Straight | Canvas | C | N | | 12 | | | LF | V0003 | None Detected | N.D. | None | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | ALL | N/A | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite.

Client: Cowww
Location: #5 : North Stairwell
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|----------------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | ALL | N/A | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite

Client: Cowww
Location: #6 : Chlorine Analyzer Room
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Fresh Air Intake | Fibreglass w/Parging | Surface | Canvas | C | Y | | 29 | 1 | | SF | V0005 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Floor | All | Mortar | Surface | Ceramic Tiles | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Fibreglass | Straight | Canvas | B | Y | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Not Insulated | Fitting | N/A | B | Y | | 100 | | | % | V0000 | Non-Asbestos | | None | |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 960 | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Damaged/exposed parging cement on 1 SF air intake - June 29, 2021 Masonry walls suspect to contain vermiculite. setting compound on ceramic tiles is presumed asbestos containing.

Client: Cowww
Location: #7 : Chlorine Scale Room
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|----------------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Fresh Air Intake | Fibreglass w/Parging | Surface | Canvas | C | Y | | 30 | | | SF | S0005 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Rain Water Leader | Parging over Fibreglass | Fitting | Canvas | B | Y | | 2 | | | EA | V0002 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 1040 | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite.

Client: Cowww
Location: #8 : Vestibule
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|--------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #9 : Chlorine Tonner Room
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 1200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|----------------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Rain Water Leader | Parging over Fibreglass | Fitting | Canvas | C | Y | | 5 | | | EA | V0004 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | Rain Water Leader | Sweat Wrap pipe insulation | Straight | Canvas | C | Y | | 40 | | | LF | V0003 | None Detected | N.D. | None | |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite.

Client: Cowww
Location: #10 : Vestibule
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 80

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|--------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Cement Product | Surface | N/A | C | Y | | 80 | | | SF | V9000 | Confirmed Asbestos | | Confirmed Asbestos | NF |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | | | | | | | | | | | | | | | | |
| Structure | N/a | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |

Masonry walls suspect to contain vermiculite.

Client: Cowww
Location: #11 : Ammonia Room
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 160

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|----------------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Fresh Air Intake | Fibreglass w/Parging | Surface | Canvas | C | Y | | 15 | | | SF | V0005 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Rain Water Leader | Parging over Fibreglass | Fitting | Canvas | C | Y | | 2 | | | EA | V0004 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | Rain Water Leader | Sweat Wrap pipe insulation | Straight | Canvas | C | Y | | 10 | | | LF | V0003 | None Detected | N.D. | None | |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 1160 | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite.

Client: Cowww
Location: #12 : Upper Walkways
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 2200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|----------------------------------|----------------|----------|----|----|-----|------|------|------|------|----------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Metal | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Rain Water Leader | Parging over Fibreglass | Fitting | Canvas | C | Y | | 2 | | | EA | S0004 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | Rain Water Leader | Sweat Wrap pipe insulation | Straight | Canvas | C | Y | | 20 | | | LF | V0003 | None Detected | N.D. | None | |
| Piping | Rain Water Leader | Sweat Wrap pipe insulation | Straight | Canvas | C | N | | 4 | | | LF | V0003 | None Detected | N.D. | None | |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall ¹ | | Mortar, Off White | | | | | | 100 | | | % | S0014ABC | None Detected | N.D. | None | |
| Wall ² | | Mortar, Of White | | | | | | 100 | | | % | S0015ABC | None Detected | N.D. | None | |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 3500 | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Exterior masonry wall at overhead door inspected for vermiculite. Wall is not insulated. Remaining masonry walls suspect to contain vermiculite. Mortar sampled S0014A-C, 0015A-C April 3, 2023

1 - Lower 5 feet

2 - Above 5 feet (2 styles of brick present)

Client: Cowww
Location: #13 : Stairwell
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Main

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 160

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|----------------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | ALL | N/A | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite.

Client: Cowww
Location: #14 : Stairwell
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Mezzanine

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Parging over Fibreglass | Fitting | Canvas | C | Y | | 1 | | | EA | V0002 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | Domestic Water (hot And Cold) | Sweat Wrap pipe insulation | Straight | Canvas | C | Y | | 11 | | | LF | V0003 | None Detected | N.D. | None | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 475 | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite.

Client: Cowww
Location: #15 : North Mezzanine
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Mezzanine

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 600

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|----------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Sweat Wrap pipe insulation | Straight | Canvas | C | Y | | 30 | | | LF | S0008 | None Detected | N.D. | None | |
| Piping | Domestic Water (hot And Cold) | Abated Material | Fitting | Canvas | C | Y | | 3 | | | EA | V0002 | [None] | 25-50% | [Abated] | |
| Piping | Domestic Water (hot And Cold) | Abated Material | Fitting | Canvas | C | Y | | 3 | | | EA | V0004 | [None] | 25-50% | [Abated] | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |

Masonry walls suspect to contain vermiculite.

Client: Cowww
Location: #16 : Fan Room
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Mezzanine

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 3600

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------------|----------------|-----------------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Fresh Air Intake | Fibreglass w/Parging | Surface | Canvas | C | Y | | 500 | | | SF | V0005 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Air Handling Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Air Handling Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Air Handling Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Air Handling Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Air Handling Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Exchanger | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Chilled Water Return | Parging over Fibreglass | | Canvas | B | Y | | 8 | 2 | | EA | S0013 | None Detected | N.D. | None | |
| Piping | Chilled Water Supply | Parging over Fibreglass | | Canvas | B | Y | | 15 | 3 | | EA | S0012 | None Detected | N.D. | None | |
| Piping | Domestic Water (hot And Cold) | Sweat Wrap pipe insulation | Straight | Canvas | C | Y | | 70 | | | LF | V0003 | None Detected | N.D. | None | |
| Piping | Domestic Water (hot And Cold) | Abated Material | Fitting | Canvas | C | Y | | | | | EA | V0002 | [None] | 25-50% | [Abated] | |
| Structure Wall | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | Surface | Preformed Block | A | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite.

Client: Cowww
Location: #17 : Stairwell
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Mezzanine

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 160

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------------|----------------|-----------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Abated Material | Fitting | Canvas | C | Y | | | | | EA | V0002 | [None] | 25-50% | [Abated] | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | ALL | Preformed Block | A | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite.

Client: Cowww
Location: #18 : Generator Room
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Mezzanine

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------------|----------------|-----------------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Generator Exhaust | Magnesia block | System | | C | Y | | 40 | | | LF | S0006 | Amosite | 5-10% | Confirmed Asbestos | F |
| Mechanical Equipment | Generator Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Generator Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Abated Material | Fitting | Canvas | C | Y | | | | | EA | V0002 | [None] | 25-50% | [Abated] | |
| Piping | Gas Pipe Line | Not Insulated | Fitting | N/A | C | Y | | 100 | | | % | V0000 | Non-Asbestos | | None | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | ALL | Preformed Block | A | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite

Client: Cowww
Location: #19 : Pump Floor
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Lower Level

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 5400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------------|----------------|-----------------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Exhaust | Magnesia block | System | | C | Y | | 24 | | | LF | V0006 | [Asbestos] | 5-10% | [Asbestos] | F |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Floor | All | Mortar | Surface | Ceramic Tiles | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Other | | Ceiling tiles (glue-on) | Surface | N/A | B | Y | | 36 | | | SF | S0007 | None Detected | N.D. | None | |
| Piping | | Abated Material | Fitting | Canvas | B | Y | | | | | EA | V0002 | [None] | 25-50% | [Abated] | |
| Piping | Domestic Water (hot And Cold) | Parging over Fibreglass | Fitting | Canvas | C | Y | | 35 | | | EA | V0002 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Structure | Beam, Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | All | Vermiculite/concrete block walls | ALL | Preformed Block | A | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain vermiculite. setting compound on ceramic tiles is presumed asbestos containing.

Client: Cowww
Location: #20 : Maintenance Room
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Lower Level

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 600

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|-------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Parging over Fibreglass | Fitting | Canvas | C | Y | | 10 | | | EA | V0002 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #21 : Valve Room
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: Lower Level

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 3600

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|-------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Parging over Fibreglass | Fitting | Canvas | C | Y | | 140 | | | EA | V0002 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Room Not accessible June 29, 2021

Client: Cowww
Location: #22 : MacLean Pump Station Building
Exterior
Survey Date: 2023-06-09

Site: 875 Lagimodiere Boulevard, Winnipeg, MB
Floor: NA

Building Name: MacLean Pumping Station
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 0

| ASBESTOS | | | | | | | | | | | | | | | | |
|--------------------|-----------|----------------------------------|------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other ¹ | | Caulking | | | | | | 4 | | | SF | V0011 | Chrysotile | 1-5% | Confirmed Asbestos | NF |
| Wall | | Clay Tile (block) | Exterior | | A | Y | | 100 | | | % | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |
| Wall | Base | Plaster | Base | | A | Y | | 300 | | | SF | S0010 | None Detected | N.D. | None | |
| Wall | Exterior | Plaster | Base | | A | Y | | 43 | | | SF | S0009 | None Detected | N.D. | None | |
| Wall | Exterior | Caulking | | | A | Y | | 100 | | | % | S0011 | Chrysotile | 1-5% | Confirmed Asbestos | NF |
| Wall | Fascia | Plaster | Exterior | | A | Y | | 300 | | | SF | V9500 | [None] | | [None] | |

Masonry walls suspect to contain vermiculite. Roof sections needs to be tested prior to any renovation or demolition activities

1 - Debris present on ground North East side of building

Legend:

| Sample number | | Units | | Other | |
|---------------|--|-------|-------------|-------|------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | A | Access |
| V#### | Material visually similar to numbered sample collected | LF | Linear feet | V | Visible |
| V0000 | Known non-asbestos material | EA | Each | AP | Air Plenum |
| V9000 | Visually identified as an asbestos material | % | Percentage | F | Friable material |
| V9500 | Material is presumed to be an asbestos material | | | NF | Non Friable material |
| | | | | PF | Potentially Friable material |

| Access | |
|--------|---|
| A | Accessible to all building occupants |
| B | Accessible to maintenance and operations staff without a ladder |
| C | Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas |
| D | Not normally accessible |

| Condition | |
|-----------|---|
| Good | No visible damage or deterioration |
| Fair | Minor, repairable damage, cracking, delamination or deterioration |
| Poor | Irreparable damage or deterioration with exposed and missing material |

| Visible | |
|---------|---|
| Y | The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels). |
| N | The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. |

| Air Plenum | |
|------------|---|
| Yes or No | The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation. |

| Colour Coding | |
|--|---|
|  | The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code). |
|  | The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling. |



2023 Asbestos Reassessment

McPhillips Street
Pumping Station
360 McPhillips Street,
Winnipeg, Manitoba

Prepared for:

**City of Winnipeg Water
and Waste Department**
110-1199 Pacific Avenue
Winnipeg, Manitoba R3E 3S8

August 22, 2023

Pinchin File: 327243.000



2023 Asbestos Reassessment

McPhillips Street Pumping Station, 360 McPhillips Street, Winnipeg, Manitoba
City of Winnipeg Water and Waste Department

August 22, 2023
Pinchin File: 327243.000

Issued to: City of Winnipeg Water and Waste Department
Issued on: August 22, 2023
Pinchin File: 327243.000
Issuing Office: Winnipeg, MB

Author:

Ken Brydges, C.E.T. LEED GA
Senior Project Manager
204.452.0983
kbrydges@pinchin.com

Reviewer:

Rodney Legault, C.E.T. EP
Operations Manager
204.452.0983
rlegault@pinchin.com



EXECUTIVE SUMMARY

City of Winnipeg Water and Waste Department (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment of McPhillips Street Pumping Station located at 360 McPhillips Street, Winnipeg, Manitoba. The reassessment was performed on June 13, 2023.

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM), and develop corrective action plans as required for the purposes of long-term management. The results of this assessment are not intended for construction, renovation, demolition or project tendering purposes. The following buildings have been previously confirmed to contain asbestos therefore were included in our assessment:

| | |
|---|---|
| <ul style="list-style-type: none"> • Chlorine Building | <ul style="list-style-type: none"> • Pump Building |
| <ul style="list-style-type: none"> • Garage Building | <ul style="list-style-type: none"> • Storage Shed Building |
| <ul style="list-style-type: none"> • Old Pump Building | |

SUMMARY OF FINDINGS

Asbestos-containing materials (ACM) are present as follows:

- Parging cement, containing asbestos is present on pipe fittings within the Pump Building, Chlorine Building, and Old Pump Building. Parging cement is friable and is in good condition except for minor amounts of damage rated in poor condition.
- Sweat wrap containing asbestos is present on straight sections of the rainwater leader pipes throughout Pump Building A and Chlorine Building. Sweat wrap is non-friable and is in good condition.
- Asbestos-containing magnesia block is present as insulation on exhaust ducting within the Pump Building, Location No.1. Magnesia block is a friable material. Is jacketed with metal and is in good condition.
- Asbestos-containing ceiling tiles are present in the Shop of the Old Pump Building (Location No. 22). The acoustic ceiling tiles are potentially friable and remain concealed above the metal ceiling tiles.
- Asbestos-containing transite cement boards are present throughout the Old Pump Building. Transite cement is non-friable and is in good condition.
- Asbestos-containing black tar mastic is present on the exterior lower wall finish of the Pump and Chlorine Buildings. Tar mastic is non-friable and is in good condition.



- Asbestos-containing 12" x 12" beige vinyl floor tiles are present within the Pump Building, Electrical Room, Location No.6. Vinyl floor tiles are non-friable and are in good condition.
- Drywall (gypsum board) and joint compound suspect to contain asbestos is present in the Old Pump Building and Garage; Drywall joint compound is potentially friable and is in good condition.
- Loose fill vermiculite has been confirmed present within the Old Pump Building and is presumed present throughout the Storage Shed, Garage, and Chlorine Buildings. The Pump Building does not contain vermiculite. 5 SF of vermiculite debris was present on the floor within the Electrical Room Location 30 of the Old Pump Building.
- Setting compounds on ceramic tile finishes within the Pump Building are presumed to contain asbestos. Setting compounds are potentially friable and are in good condition.

SUMMARY OF RECOMMENDATIONS

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations.

1. The following items require immediate remedial action:
 - a. Remove following Moderate Risk procedures vermiculite debris from the floor within the Electrical Room Location No. 30 of the Old Pump Building.
 - b. Remove following Moderate Risk Glovebag procedures damaged/exposed parging cement on 1 domestic water fitting rated in poor condition within the Old Pump Building, Furnace Room Location No.21.
2. Perform a re-assessment of asbestos materials on an annual basis.
3. Prior to renovations or demolition, perform a pre-construction assessment to identify any hazardous materials that may be disturbed by the work.
4. Follow appropriate safe work procedures when handling or disturbing asbestos.

This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.



TABLE OF CONTENTS

| | | |
|------|--|---|
| 1.0 | INTRODUCTION AND SCOPE | 1 |
| 1.1 | Scope of Assessment | 1 |
| 2.0 | METHODOLOGY | 1 |
| 3.0 | BACKGROUND INFORMATION | 2 |
| 3.1 | Building Description | 2 |
| 3.2 | Existing Reports and Summary of Asbestos Abatement | 2 |
| 4.0 | FINDINGS | 2 |
| 4.1 | Pipe Insulation | 3 |
| 4.2 | Duct Insulation | 3 |
| 4.3 | Vermiculite | 3 |
| 4.4 | Acoustic Ceiling Tiles | 3 |
| 4.5 | Drywall Joint Compound | 3 |
| 4.6 | Asbestos Cement Products (Transite) | 4 |
| 4.7 | Vinyl Floor Tiles | 4 |
| 4.8 | Sealants, Caulking, and Putty | 4 |
| 4.9 | Roofing Products | 4 |
| 4.10 | Other Building Materials | 4 |
| 4.11 | Excluded Asbestos Materials | 4 |
| 5.0 | RECOMMENDATIONS | 5 |
| 5.1 | General | 5 |
| 5.2 | Remedial Work | 5 |
| 5.3 | On-going Management and Maintenance | 5 |
| 6.0 | TERMS AND LIMITATIONS | 6 |
| 7.0 | REFERENCES | 6 |

APPENDICES

| | |
|--------------|---|
| APPENDIX I | Methodology |
| APPENDIX II | Additional Photographs |
| APPENDIX III | Location Summary Report |
| APPENDIX IV | Asbestos Material Summary Report / Sample Log |
| APPENDIX V | HMIS Data Report |



1.0 INTRODUCTION AND SCOPE

City of Winnipeg Water and Waste Department (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment at 360 McPhillips Street, Winnipeg, Manitoba.

Pinchin performed the reassessment on June 13, 2023. The surveyor was accompanied by City of Winnipeg Water and Waste Representatives during the reassessment. The assessed area was occupied at the time of the assessment.

The objectives of the reassessment were to document the locations, quantities and conditions of previously identified asbestos containing building materials and develop corrective action plans as required. This reassessment is only to be used for the purposes of long-term management and routine maintenance. The results of this reassessment are not to be used for construction, renovation, demolition or project tendering purposes. The following buildings have been previously confirmed to contain asbestos therefore were included in our assessment:

| | |
|---|--|
| <ul style="list-style-type: none"> • Chlorine Building | <ul style="list-style-type: none"> • Pump Building; and |
| <ul style="list-style-type: none"> • Garage Building | <ul style="list-style-type: none"> • Storage Shed Building. |
| <ul style="list-style-type: none"> • Old Pump Building | |

1.1 Scope of Assessment

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM), and develop corrective action plans as required.

Additional objectives included the following:

- Documentation of any asbestos abatement that was performed since the last reassessment.

Please refer to Appendix I for a detailed description of the methodology used for this assessment.

2.0 METHODOLOGY

Pinchin conducted an inspection of previously identified asbestos-containing materials (ACM) to evaluate the current condition of all accessible materials identified in the most recent assessment. The surveyor made reference to any existing assessment or abatement reports (as provided by the Client).



As per the original scope of work, concealed locations such as ceiling spaces above solid ceilings, shafts and chases were accessed via existing access panels. Our investigation did not include demolition of drywall or plaster walls to view concealed conditions. Structural items or exterior building finishes were not removed to determine the presence of concealed materials.

For further details on the methodology including test methods, refer to Appendix I.

3.0 BACKGROUND INFORMATION

3.1 Building Description

| Description Item | Details |
|-------------------|--|
| Use | City of Winnipeg Water and Waste |
| Structure | Structure steel and concrete |
| Exterior Cladding | Masonry |
| HVAC | Furnace, Forced Air, Boiler |
| Roof | Not Accessed |
| Flooring | Vinyl floor tiles, exposed concrete, ceramic tiles |
| Interior Walls | Masonry, Drywall, Ceramic tiles, transite cement |
| Ceilings | Transite cement and acoustic ceiling tiles |

3.2 Existing Reports and Summary of Asbestos Abatement

3.2.1 Review of Previous Reports

The reassessment was based on information gathered from the original comprehensive assessment report completed by Pinchin. The original assessment report for the McPhillips Pumping Station was dated March 6, 2007. The results of the original report and subsequent survey update reports were reviewed prior to completing the reassessment.

3.2.2 Summary of Asbestos Abatement since the Previous Assessment

Based on a review of the above noted abatement reports, and observations made during the reassessment, asbestos abatement has not been conducted since the last assessment.

4.0 FINDINGS

The following section summarizes the findings of the reassessment and provides a general description of the asbestos-containing materials (ACM) identified and their locations.

For details on approximate quantities, condition, friability and locations of asbestos materials; refer to the Asbestos Material Summary Report and All Data Report in Appendix IV and V.



4.1 Pipe Insulation

Parging cement, containing asbestos is present on pipe fittings of the City Water Supply, Rainwater Leader, Domestic Water, Chilled Water and Heating Water pipe systems within the Pump Building, Chlorine Building, and Old Pump Building. Parging cement is a friable material which was jacketed with canvas. The parging cement was in good condition except for minor amounts rated in fair and poor condition.

Sweatwrap (brown layered paper) containing asbestos in the tar paper layer, is present on straight sections of the City Water Supply, Rainwater leader pipes in the Pump Building and Chlorine Building (Location Nos. 1, 2, 4, 7, 8, 9, and 11). Since the asbestos is present in the tar paper layer only it is a non-friable material. The Sweatwrap was jacketed with canvas and is in good condition.

The following damage was noted during the 2023 update:

| Location | Quantity and Condition of Damage |
|--|---|
| Old Pump Building, Furnace Room (Location No. 21). | 1 fitting insulated with parging cement rated in POOR condition on the domestic water system. |

4.2 Duct Insulation

Preformed block insulation containing chrysotile and amosite asbestos is present on the generator exhaust duct in the Basement Pump Building (Location No. 1). The preformed block insulation is a friable material which was jacketed with metal and is in GOOD condition.

4.3 Vermiculite

Loose fill vermiculite has been confirmed present within the Old Pump Building within Location No.'s 30 and 31 and is presumed present within the remainder of the building and throughout the Storage Shed, Garage, and Chlorine Buildings. Vermiculite is a friable material. Vermiculite debris was observed present on the floor of the Electrical Room, Location No.30 Old Pump Building.

4.4 Acoustic Ceiling Tiles

Asbestos-containing ceiling tiles located above the metal ceiling tiles in the Old Pump Building - Shop (Location No. 22) remain present and are not accessible.

4.5 Drywall Joint Compound

Drywall (gypsum board) and joint compound suspect to contain asbestos is present in the Old Pump Building and Garage. Drywall joint compound is potentially friable and is in GOOD condition.



4.6 Asbestos Cement Products (Transite)

Asbestos-containing transite boards are present as ceiling and wall finishes in the Old Pump Building Washroom, Dispatch, and Vestibule (Location Nos. 13, 16, and 17). Transite is a non-friable material that has been maintained in GOOD condition.

4.7 Vinyl Floor Tiles

Vinyl floor tiles present within the Pump Building Electrical Room, Location No.6 are non-friable and in GOOD condition.

4.8 Sealants, Caulking, and Putty

Asbestos-containing black tar mastic is applied as a sealant on the exterior lower wall finish of the Pump Building (Location No. 42) and Chlorine Building (Location No. 43). Mastic is a non-friable material which is in GOOD condition.

4.9 Roofing Products

No visual inspection or sampling was conducted at this location. Destructive testing will be required prior to any renovation or demolition activities.

4.10 Other Building Materials

Setting compounds on ceramic tile finishes within the Pump Building are presumed to contain asbestos. Setting compounds are potentially friable and are in GOOD condition.

4.11 Excluded Asbestos Materials

The following is a list of materials which may contain asbestos and was excluded from the assessment. These materials are presumed to contain asbestos until otherwise proven by sampling and analysis:

- Roofing felts and tar, mastics;
- Floor levelling compound;
- Ceramic tile setting compound;
- Elevator and lift brakes;
- Electrical components;
- Moulded plastic components (laboratory bench tops);
- Refractory materials and insulations in boilers, and stacks;
- Insulation under metal clad boilers;
- Mechanical packing, ropes and gaskets;



- Vermiculite;
- Adhesives and duct mastics;
- Caulking and putties;
- Fibre-reinforced paints and coatings;
- Paper products;
- Soffit and fascia boards;
- Fire resistant doors;
- Metal clad finishes (Galbestos);
- Stucco, plaster or other cementitious parge coatings;
- Vibration dampers on HVAC equipment;
- Terrazzo;
- Ropes and gaskets in cast-iron bell and spigot joints; and
- Sealants on pipe threads.

5.0 RECOMMENDATIONS

5.1 General

Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include; destructive testing (e.g. coring and/or removal of building finishes and components), sampling of other hazardous materials (lead, mercury, PCBs, mould, etc.), and materials not tested in this study (e.g. roofing materials, caulking, mastics).

5.2 Remedial Work

The following remedial work is recommended.

| Material, Quantity & Condition | Location Name (Location #) | Recommended Procedure |
|---|---|---|
| Vermiculite, 5 SF debris | Old Pump Building Electrical Room, Location No.30 | Remove in accordance with Moderate Risk Procedures |
| Parging cement, Pipe insulation 1 fitting in POOR condition | Pump Building Furnace Room, Location No.21 | Remove in accordance with Moderate Risk Glovebag Procedures |

5.3 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the asbestos materials identified.



Perform a re-assessment of asbestos materials on an annual basis.

Remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.

Update the asbestos inventory report for the building upon completion of any abatement of ACM.

6.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

7.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

Manitoba

1. Workplace Safety and Health Act W210.
2. Workplace Safety and Health Hazard Regulation (Manitoba Regulation 217/2006), under the Workplace Safety and Health Act.
3. Manitoba Regulation MR 474/88, Manitoba PCB Regulation made under The Dangerous Goods Act.
4. Guide for Asbestos Management – Safe Work Manitoba.
5. Guideline Managing Demolition Debris Containing Hazardous Materials – Environmental Enforcement and Compliance Branch – Manitoba Conservation and Climate

Federal

1. Canada Occupational Health and Safety Regulation, SOR/86-304.
2. Consolidated Transportation of Dangerous Goods Regulations, including Amendment SOR/2019-101, Transportation of Dangerous Goods Act.

\\pinchin.com\wpg\Job\327000s\0327243.000 CITYOFWINNIPE,PropertyMB,2023,ASB,CONS\Deliverables\McPhillips\327243, 2023 Asbestos Reassessment Report, McPhillipsStPumpingStation, 360 McPhillips St, Wpg, MB, COWWW, Aug 22, 2023.docx

Template: Master Report for Asbestos Reassessment, HAZ, March 2, 2023

APPENDIX I
Methodology



1.0 GENERAL

Pinchin conducted an inspection of previously identified asbestos-containing materials (ACM) to evaluate the current condition of all accessible ACM identified in the most recent assessment.

The surveyor made reference to any existing assessment or abatement reports (as provided by the Client).

Materials listed as exclusions in the previous reports have remained as exclusions. Sampling, assessment or verification of excluded materials was not conducted.

Existing sampling data, where available, was reviewed and relied upon.

Where sampling was conducted, sample collection was conducted in accordance with our Standard Operating Procedures.

A separate set of samples was collected of each type of homogenous material suspected to contain asbestos. A homogenous material is defined by the US EPA as material that is uniform in texture and appearance, was installed at one time, and is unlikely to consist of more than one type or formulation of material. The homogeneous materials were determined by visual examination and available information on the phases of construction and prior renovations.

Samples were collected at a rate that is in compliance with the requirements of local regulations and guidelines. The sampling strategy was also based on known ban dates and phase out dates of the use of asbestos; sampling of certain building materials is not conducted after specific construction dates. In addition, to be conservative, several years past these dates are added to account for some uncertainty in the exact start / finish date of construction and associated usage of ACM. In some cases, manufactured products such as asbestos cement pipe were visually identified without sample confirmation.

The asbestos analysis was completed using a stop-positive approach. Only one result meeting the regulated criteria was required to determine that a material is asbestos-containing, but all samples must be analyzed to conclusively determine that a material is non-asbestos. The laboratory stopped analyzing samples from a homogeneous material once a result equal to or greater than the regulated criteria is detected in any of the samples of that material. All samples of a homogeneous material were analyzed if no asbestos is detected. In some cases, all samples were analyzed in the sample set regardless of result.

The analysis was performed in accordance with Test Method EPA/600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials, July 1993.



The following summarizes the criteria of asbestos definitions. If there is a conflict between federal and provincial criteria, the more stringent will apply:

| Jurisdiction | Friable | Non-Friable |
|---------------------|-------------------|--------------------|
| Manitoba | 0.1% ¹ | 1% |
| Federal | 1% | 1% |

Where building materials are described in the report as “non-asbestos” or “does not contain asbestos”, this means that either no asbestos was detected by the analytical method utilized in any of the multiple samples or, if detected, it is below the lower limit of an asbestos-containing material in the applicable regulation. Additionally, these terms are used for materials which historically are known to not include asbestos in their manufacturing.

Asbestos materials are evaluated in order to make recommendations regarding remedial work. The priority for remedial action is based on several factors:

- Friability (friable or non-friable).
- Condition (good, fair, poor, debris).
- Accessibility (ranking from accessible to all building users to inaccessible).
- Visibility (whether the material is obscured by other building components).
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition).

For a complete description of the Evaluation Criteria and Basis of Recommendations, refer to Annex A.

Template: Methodology for Asbestos Reassessment, HAZ, July 27, 2021

METHODOLOGY ANNEX A EVALUATION CRITERIA

1.0 EVALUATION CRITERIA AND BASIS OF RECOMMENDATIONS

The detailed asbestos assessment provides information regarding the location, condition, accessibility and friability of the asbestos-containing materials (ACM). In order to make recommendations for compliance with current regulations, Pinchin developed the following criteria.

2.0 EVALUATION OF CONDITION

2.1 Friable Sprayed or Trowelled Fireproofing, Thermal Insulation and Texture Finishes (Surfacing Materials)

To evaluate the condition of ACM sprayed or trowelled on fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes, the following criteria are applied:

| | |
|-------------|---|
| Good | Surface of material shows no significant signs of damage, deterioration or delamination. Good condition includes unencapsulated or unpainted fireproofing or texture finishes, where no or limited delamination or damage is observed, or encapsulated fireproofing or texture finishes where the encapsulant or paint has been applied after the damage or fallout occurred. |
| Poor | A sprayed material that shows signs of significant damage or is significantly delaminating or deteriorating. This may be limited to surface delamination or some portion of the substrate may be exposed. |

In Locations where damage exists in isolated areas, both good and poor condition may be applicable. The extent of each condition will be recorded. Fair condition is not utilized in the evaluation of ACM sprayed or trowelled fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes.

The evaluation of the above products above ceilings may be limited by the number of observations and by building components such as ducts or full height walls that obstruct the above ceiling observations.

2.2 Friable Mechanical or Thermal System Insulation (TSI)

To evaluate the condition of mechanical insulation on vessels, boilers, breeching, ducts, pipes, fan units, equipment etc. the following criteria are applied:

| | |
|-------------|---|
| Good | Insulation is completely covered in jacketing and exhibits no evidence of damage or deterioration. No insulation is exposed. Includes conditions where the jacketing has minor damage (i.e. scuffs or stains), but the jacketing is not penetrated. |
| Fair | Minor penetrating damage to jacketed insulation (cuts, tears, nicks, deterioration or delamination) or undamaged insulation that has never been jacketed. Insulation is exposed but not showing surface disintegration. The extent of missing insulation ranges from minor to none. Damage can be repaired. |

| | |
|-------------|---|
| Poor | Original insulation jacket is missing, damaged, deteriorated or delaminated. Insulation is exposed and significant areas have been dislodged. Damage cannot be readily repaired. Includes components where insulation may have been removed incompletely. |
|-------------|---|

The evaluation of mechanical insulation may be limited by the number of observations made and building components such as ducts or full height walls that obstruct observations. It is often not possible to observe each foot of mechanical insulation from all angles.

2.3 Potentially Friable Materials and Miscellaneous Friable Materials

Potentially friable ACM are products that are basically non-friable while in place but have the potential to generate friable dust upon removal or if significantly disturbed without appropriate procedures. These products may become friable if damaged. Potentially friable materials include materials such as acoustic ceiling tiles and plaster. To evaluate the condition of potentially friable materials, the following criteria are applied:

| | |
|-------------|--|
| Good | No significant damage or deterioration. Still serving its intended use as a building material or finish. |
| Fair | Showing signs of some cracking or breakage, but is not deteriorating (e.g. cracked plaster, broken but in place ceiling tile, missing tile or section of plaster etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes. |
| Poor | Significant deterioration or breaking apart of the material. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material has deteriorated to a point it has become friable. Normally potentially friable ACM in Poor condition is not repairable and requires at least localized removal and replacement. |

2.4 Non-Friable Materials

Non-friable ACM cover a wide range of products with a wide variation in their tendency to release dust or asbestos fibres to the air. Many of these materials, (particularly where the matrix is an unweathered bitumen, asphalt or tar material) do not release fibres except in very unusual circumstances or during significant disturbance (e.g. use of abrasive power tools). Others with a cementitious matrix (asbestos-cement products) can more readily release dust due to abrasion, demolition, weathering, etc. The potential for asbestos release from non-friable ACM is always lower than from friable ACM. To evaluate the condition of non-friable Materials, the following criteria are applied:

| | |
|-------------|--|
| Good | No significant damage or deterioration. Still serving its intended use as a building material or finish. |
|-------------|--|

| | |
|-------------|---|
| Fair | Showing signs of some cracking or breakage but is not deteriorating (e.g. cracked vinyl floor tile, missing piece of tile or transite, etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes. |
| Poor | Significant deterioration or breaking apart of the material to the point at which it cannot be repaired, and it will require at least local removal. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material may have deteriorated to a point where traffic or disturbance may cause it to become friable. |

2.5 Evaluation of ACM Debris

The identification of the exact location or presence of debris on the top of ceiling tiles is limited by the number of observations made and the presence of building components such as ducts or full height walls that obstruct observations.

The presence of fallen or dislodged ACM is noted separately from the ACM source and is referred to as Debris. Debris may be friable if from a friable ACM source or a badly deteriorated non-friable ACM source. Debris may also be non-friable (such as fallen pieces of transite sheet or mastic fittings, or broken, dislodged floor tiles).

| | |
|---------------|--|
| Debris | Debris may be friable or non-friable but is always identified as debris. |
|---------------|--|

2.6 Evaluation of Presumed Asbestos-Containing Material (PACM)

Presumed asbestos-containing materials (PACM), are building materials that may contain asbestos but were not sampled or analyzed due to inaccessibility or the need to perform destructive testing to obtain a reasonable sample set. Evaluation of these materials is based on the assumption that these PACM are asbestos-containing.

A list of PACM is provided in the report and they are generally not included in the detailed room by room reports. Typically, they are excluded because they are inaccessible or present in very small quantities. If PACM are evaluated, Pinchin uses the criteria that correspond with the type (and friability) of the material listed above.

3.0 EVALUATION OF ACCESSIBILITY

The accessibility of building materials known or suspected of being ACM is rated according to the following criteria:

| | |
|-----------------------------------|--|
| Access (A) | Common areas of the building within reach of all building users (approximately 8' - 9' from floor or standard ceiling height). Includes other areas where occupant activities may result in disturbance of material that is not normally within reach from floor level, but may be disturbed by common activities (e.g. gymnasiums, workshops) |
| Access (B) | Areas of the building accessed primarily by Maintenance/Caretaking/Janitorial Staff and within reach without use of a ladder. Includes areas within reach in Boiler Rooms, Electrical Rooms, Janitors Closets, Elevator Rooms, Mechanical Rooms, etc. Includes materials within reach from fixed ladders or catwalks, mezzanines, and accessible pipe chases. |
| Access (C) and Visible | Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Only includes ACM that are visible to view without the removal or opening of other building components such as ceiling tiles or service access panels. Visible column on HMIS sheets will say YES. |
| Access (C) and not Visible | Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Includes ACM that are not visible to view and require the removal of a building component to see, such as ceilings tiles or access panels to view and access. Includes rarely entered crawl spaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. Visible column on HMIS sheets will say NO. |
| Access (D) | Areas of the building behind inaccessible solid ceiling systems, walls or equipment etc. where demolition of the ceiling, wall or equipment etc. is required to reach the ACM. Material inaccessible due to height or location or is only accessed under unusual situations. Evaluation of condition and extent of ACM is limited or impossible, depending on the surveyor's ability to visually examine materials in Access D. |

4.0 ACTION MATRIX AND DEFINITIONS

Pinchin's evaluation of the viability of a specific asbestos control option is based on the consideration of the friability, condition, accessibility and visibility of a material. The logic used is that damaged ACM located in an area frequently accessed by all building occupants is of a higher priority than damaged ACM located in an infrequently accessed service area. The action matrix considers the potential for fibre release (primarily from friable ACM) and the possible concerns from regulatory bodies and many building occupants to all damaged ACM (including non-friable).

In any building with asbestos, many current regulations require an Asbestos Management Program be implemented. Depending on the condition and the accessibility, more active measures such as repair or removal may be recommended. The following matrix provides guidance for recommended Actions in the absence of renovation or demolition. In the event of construction or maintenance activity which will disturb ACM more aggressive control or removal will be required.

4.1 Action Matrix

The following tables outline the action decisions based on the relationship of assessed factors. Table I applies to friable ACM. Table II applies to non-friable ACM.

Table I Decision Matrix for Friable ACM

| Access | Condition | | | Debris |
|-----------------|-----------------------|-----------------------|----------|----------|
| | Good | Fair | Poor | |
| (A) | Action 5 ¹ | Action 5 ² | Action 3 | Action 1 |
| (B) | Action 7 | Action 6 ³ | Action 3 | Action 1 |
| (C) Visible | Action 7 | Action 6 | Action 3 | Action 2 |
| (C) Not Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (D) | Action 7 | Action 7 | Action 7 | Action 7 |

Table II Decision Matrix for Potentially Friable and Non-Friable ACM

| Access | Condition | | | Debris |
|-----------------|-----------|-----------------------|----------|----------|
| | Good | Fair | Poor | |
| (A) | Action 7 | Action 7 ⁴ | Action 3 | Action 1 |
| (B) | Action 7 | Action 7 | Action 3 | Action 1 |
| (C) Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (C) Not Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (D) | Action 7 | Action 7 | Action 7 | Action 7 |

4.2 Action Definitions

The following are the definitions in the Action Matrix Table presented above:

Action Definitions

| | |
|-----------------|--|
| Action 1 | Clean-Up of ACM Debris Restrict access that is likely to cause a disturbance of the ACM Debris and clean up ACM Debris. Utilize appropriate asbestos precautions. |
|-----------------|--|

¹ If friable ACM in access (A)/Good condition is not proactively removed Action 7 (Manage) is recommended.

² If friable ACM in access (A)/Fair condition is not proactively removed repair is recommended.

³ If friable ACM in access (B)/Fair condition is likely to be disturbed after repair proactive removal is recommended.

⁴ Action 7 is recommended for all non-friable ACM in Fair condition however some clients may wish to repair or take some action primarily for cosmetic reasons



Action Definitions


| | |
|-----------------|--|
| Action 2 | <p>Precautions for Access Which may Disturb ACM Debris</p> <p>Use appropriate means to isolate the debris or to limit entry to the area which may disturb the material. At locations where ACM Debris can remain in place in lieu of removal or clean-up (e.g. Debris on top of ceiling tiles or behind lockable door), Utilize appropriate asbestos precautions to enter the area if this will disturb debris. The precautions will be required until the ACM Debris has been cleaned up.</p> |
| Action 3 | <p>ACM Removal</p> <p>Remove ACM. Utilize asbestos procedures appropriate to the scope of the removal work. Until it is removed, restrict access to the material so it is not disturbed.</p> |
| Action 4 | <p>Precautions for Work Which may Disturb ACM in Poor Condition. Utilize appropriate asbestos precautions if ACM may be disturbed by work on or near ACM. This does not require restricting access to the area, only control of work which may contact or disturb the ACM. Removal is the only viable option if work will disturb ACM.</p> |
| Action 5 | <p>Proactive ACM Removal</p> <p>Remove friable ACM where the presence of friable asbestos in Good condition is not desirable. If friable ACM in Fair condition is not removed, then Repair friable ACM.</p> |
| Action 6 | <p>ACM Repair</p> <p>Repair friable ACM in Fair condition which is not likely to be damaged again or disturbed by normal use of the area or room. Pinchin recommends proactive removal if friable ACM is likely to be damaged or disturbed during normal use of the area or room</p> |
| Action 7 | <p>Asbestos Management Program with Routine Surveillance Implement an Asbestos Management Program, including routine surveillance of ACM. Reassess materials regularly (typically once per year).</p> |

Master Template: Methodology Annex A to Appendix I Evaluation Criteria, HAZ, January 10, 2020

APPENDIX II
Additional Photographs



V0001 (Confirmed Asbestos), Piping, Rain Water Leader,
Chlorine Building - Stairwell (Location #: 11)



V0001 (Confirmed Asbestos), Piping, Rain Water Leader,
Chlorine Building - Chlorine Tonner Room (Location #: 8)




V0001 (Confirmed Asbestos), Piping, Rain Water Leader,
Chlorine Building - Chlorinator Room (Location #: 9)



V0007 (Confirmed Asbestos), Piping, Rain Water Leader, Parging over Fibreglass,
Chlorine Building - Stairwell (Location #: 11)



V0007 (Confirmed Asbestos), Piping, Rain Water Leader, Parging over Fibreglass,
Chlorine Building - Chlorine Tonner Room (Location #: 8)



S0007 (Confirmed Asbestos), Piping, Rain Water Leader, Parging over Fibreglass,
Chlorine Building - Chlorinator Room (Location #: 9)



V9500 (Presumed Asbestos), Wall, Vermiculite,
Chlorine Building - Vestibule (Location #: 10)



V0004 (Confirmed Asbestos), Damaged Piping, Domestic Water (Hot and Cold), Parging over Fibreglass, Old Pump Building
- Furnace Room (Location #: 21)



S0025 (Confirmed Asbestos), Wall, Vermiculite/concrete block walls,
Old Pump Building - Electrical Room (Location #: 30)




V9000 (Confirmed Asbestos), Wall, Cement Product,
Old Pump Building - Dispatch (Location #: 13)



V9000 (Confirmed Asbestos), Wall, Cement Product,
Old Pump Building - Washroom (Location #: 16)



V9000 (Confirmed Asbestos), Ceiling, Cement Product,
Old Pump Building - Washroom (Location #: 16)



V9500 (Presumed Asbestos), Wall, All, Mortar,
Old Pump Building - Washroom (Location #: 28)



V9500 (Presumed Asbestos), Wall, All, Mortar,
Old Pump Building - Locker Room (Location #: 29) setting compound




S0001 (Confirmed Asbestos), Piping, Rain Water Leader, Pump Building - Basement (Location #: 1)




S0003 (Confirmed Asbestos), Duct, Generator Exhaust, Magnesia block, Pump Building - Basement (Location #: 1)



V0004 (Confirmed Asbestos), Piping, Chilled Water Return, Parging Cement, Pump Building - Basement (Location #: 1)



V0004 (Confirmed Asbestos), Piping, Rain Water Leader, Parging Cement, Pump Building - Basement (Location #: 1)



V0006 (Confirmed Asbestos), Piping, Heating Water Return, Parging over Fibreglass, Pump Building - Chlorine Analyzer Room (Location #: 2)



V0007 (Confirmed Asbestos), Piping, Rain Water Leader, Parging over Fibreglass, Pump Building - Chlorine Analyzer Room (Location #: 2)



V0007 (Confirmed Asbestos), Piping, Rain Water Leader, Parging over Fibreglass, Pump Building - Vestibule/Stairwell (Location #: 4)



V0007 (Confirmed Asbestos), Piping, Rain Water Leader, Parging Cement, Pump Building - Filter Room (Location #: 7)

APPENDIX III
Location Summary Report

Client: Cowww

Site: 360 McPhillips Ave., Winnipeg, MB

Building Name: Chlorine Building (Bldg. B)

Survey Date:

Last Re-Assessment: 2023-06-19

Building Phases: A:

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|--|----------------------|------------------------|-------------|--|
| 8 | Chlorine Building - Chlorine Tonner Room | 1200 | Main-Chlorine Building | A | There was no vermiculite insulation found inside masonry block walls. Mortar on masonry walls is not asbestos containing. |
| 9 | Chlorine Building - Chlorinator Room | 300 | Main-Chlorine Building | A | There was no vermiculite insulation found inside masonry block walls. Mortar on masonry walls is not asbestos containing. |
| 10 | Chlorine Building - Vestibule | 40 | Main-Chlorine Building | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. Mortar on masonry walls is not asbestos containing. |
| 11 | Chlorine Building - Stairwell | 160 | Main-Chlorine Building | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. Mortar on masonry walls is not asbestos containing. |
| 43 | Chlorine Building Exterior | 0 | NA | A | 2019 - Confirmed No vermiculite in hollow core walls. Roof sections needs to be tested prior to any renovation or demolition activities. Mortar on masonry walls is not asbestos containing. |

Client: Cowww

Site: 360 McPhillips Ave., Winnipeg, MB

Building Name: Garage (Bldg. F)

Survey Date:

Last Re-Assessment: 2023-06-19

Building Phases: A:

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|--------------------------|----------------------|-------------|-------------|---|
| 12 | Garage - Garage | 960 | Main-Garage | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. |
| 44 | Garage Building Exterior | 0 | NA | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. Roof sections needs to be tested prior to any renovation |

Client: Cowww

Site: 360 McPhillips Ave., Winnipeg, MB

Building Name: Storage Shed (Bldg. E)

Survey Date:

Last Re-Assessment: 2023-06-13

Building Phases: A:

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|-----------------------------|----------------------|-------------------|-------------|---|
| 40 | Storage Shed - Storage Shed | 300 | Main-Storage Shed | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. |
| 45 | Storage Building Exterior | 0 | NA | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. Roof sections needs to be tested prior to any renovation or demolition activities. |

Client: Cowww

Site: 360 McPhillips Ave., Winnipeg, MB

Building Name: Old Pump Building (Bldg. D)

Survey Date:

Last Re-Assessment: 2023-06-13

Building Phases: A:

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|--|----------------------|----------------------------|-------------|---|
| 13 | Old Pump Building - Dispatch | 1050 | Second-Old Pump Building | A | |
| 14 | Old Pump Building - Office | 108 | Second-Old Pump Building | A | |
| 15 | Old Pump Building - Office | 108 | Second-Old Pump Building | A | Drywall joint compound of the drywall sections needs to be tested prior to any renovation or demolition works |
| 16 | Old Pump Building - Washroom | 85 | Second-Old Pump Building | A | |
| 17 | Old Pump Building - Vestibule | 35 | Second-Old Pump Building | A | |
| 18 | Old Pump Building - Stairwell | 70 | Second-Old Pump Building | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. |
| 19 | Old Pump Building - Storage | 120 | Third-Old Pump Building | A | |
| 20 | Old Pump Building - Hallway | 70 | Main-Old Pump Building | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. |
| 21 | Old Pump Building - Furnace Room | 105 | Main-Old Pump Building | A | Rain Water Leader Pipe is present at the back of the duct Masonry walls suspect to contain asbestos containing vermiculite insulation. Damage DW fittings present June 2017 and still present 2022 |
| 22 | Old Pump Building - Shop | 1835 | Main-Old Pump Building | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. |
| 23 | Old Pump Building - Office | 140 | Main-Old Pump Building | A | |
| 24 | Old Pump Building - Office | 160 | Main-Old Pump Building | A | |
| 25 | Old Pump Building - Office | 170 | Main-Old Pump Building | A | |
| 26 | Old Pump Building - Office | 154 | Main-Old Pump Building | A | |
| 27 | Old Pump Building - Tool Crib | 240 | Main-Old Pump Building | A | Location Demolished now part of location 22 |
| 28 | Old Pump Building - Washroom | 132 | Main-Old Pump Building | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. Setting compound on ceramic wall tiles is presumed asbestos containing. |
| 29 | Old Pump Building - Locker Room | 425 | Main-Old Pump Building | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. Setting compound on ceramic tiles presumed asbestos |
| 30 | Old Pump Building - Electrical Room | 200 | Main-Old Pump Building | A | Masonry walls contain asbestos containing vermiculite insulation. |
| 31 | Old Pump Building - Generator Room | 600 | Main-Old Pump Building | A | Masonry walls contain asbestos containing vermiculite insulation. |
| 32 | Old Pump Building - NE Corner Storage Room | 100 | Basement-Old Pump Building | A | |
| 33 | Old Pump Building - Basement | 1650 | Basement-Old Pump Building | A | |
| 34 | Old Pump Building - Storage | 200 | Basement- | A | |

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|--|----------------------|----------------------------|-------------|--|
| | Room | | Old Pump Building | | |
| 35 | Old Pump Building - Record Storage Vault | 150 | Basement-Old Pump Building | A | Masonry walls suspect to contain asbestos containing vermiculite insulation. |
| 36 | Old Pump Building - Crawlspace | 800 | Basement-Old Pump Building | A | |
| 37 | Old Pump Building - Hallway | 450 | Basement-Old Pump Building | A | |
| 38 | Old Pump Building - Sump Pit Area | 80 | Basement-Old Pump Building | A | |
| 39 | Old Pump Building - Sump Room | 300 | Basement-Old Pump Building | A | |
| 41 | Old Pump Building Exterior | 0 | NA | A | Roof sections needs to be tested prior to any renovation or demolition activities. |

Client: Cowww

Site: 360 McPhillips Ave., Winnipeg, MB

Building Name: Pump Building (Bldg. A)

Survey Date:

Last Re-Assessment: 2023-06-19

Building Phases: A:

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|--|----------------------|------------------------|-------------|--|
| 1 | Pump Building - Basement | 9000 | Basement-Pump Building | A | Setting compound on ceramic tiles is found not to contain asbestos. |
| 2 | Pump Building - Chlorine Analyzer Room | 225 | Main-Pump Building | A | There was no vermiculite insulation found inside masonry block walls. Mortar on Masonry walls confirmed non-asbestos |
| 3 | Pump Building - Washroom | 75 | Main-Pump Building | A | There was no vermiculite insulation found inside masonry block walls. Mortar on Masonry walls confirmed non-asbestos |
| 4 | Pump Building - Vestibule/Stairwell | 450 | Main-Pump Building | A | 2019 - Confirmed no vermiculite in hollow core walls Mortar on Masonry walls confirmed non-asbestos |
| 5 | Pump Building - Control Room | 350 | Main-Pump Building | A | No vermiculite insulation found inside masonry walls October 9, 2019 Mortar on Masonry walls confirmed non-asbestos |
| 6 | Pump Building - Electrical Room | 400 | Main-Pump Building | A | 2019 - Masonry walls confirmed - no vermiculite insulation. Mortar on Masonry walls confirmed non-asbestos |
| 7 | Pump Building - Filter Room | 250 | Main-Pump Building | A | There was no vermiculite insulation found inside masonry block walls. Mortar on Masonry walls confirmed non-asbestos |
| 42 | Pump Building Exterior | 0 | NA | A | 2019 - Confirmed No vermiculite in hollow core walls Roof sections needs to be tested prior to any renovation or demolition activities. July 2020 Exterior Stucco Does not contain asbestos 275519 |

APPENDIX IV

Asbestos Material Summary Report / Sample Log

Client: Cowww

Site: 360 McPhillips Ave., Winnipeg, MB

Building Name: Chlorine Building (Bldg. B)

Survey Date:

| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
|----------|-----------|--|--------------|-------------|----|----|----|-----|-------------------|----------|------------|
| Asbestos | V0001 | Piping Rain Water Leader Sweatwrap/fai/gen/loc 1 | 8,9,11 | A | 93 | 0 | 0 | 0 | Chrysotile | Yes | NF |
| Asbestos | S0007 | Piping Rain Water Leader Parging Over Fibreglass Parging/ftg/rwl/loc 9 | 8,9,11 | A | 0 | 0 | 15 | 0 | Chrysotile | Yes | F |
| Asbestos | V0015 | Wall Exterior Plaster Plaster On Concrete, Exterior Wall Foundation, Pump Bldg (sample No. 0034 - August 28, 2015 - 1517151_plm) (for Sample 0015b-c It Was Sample No. 0034b-c- June 30, 2016 - B131169) | 43 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0019 | Wall All Mortar Plaster/gout On Masonry Block Walls (loc. 8 & 9), Chlorine Tonner Room And Chlorinator Room, Chlorine Bldg. (jan. 15, 2020 - Lab. Ref. B224881) | 8,9,10,11,43 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | V9500 | Other Roof Roofing Material | 43 | A | 0 | 0 | 0 | 0 | Presumed Asbestos | Yes | NF |
| Asbestos | V9500 | Wall Vermiculite | 10,11 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | F |
| Asbestos | V0000 | Wall Vermiculite | 8,9 | A | 0 | 0 | 0 | 100 | Non Asbestos | No | |

Legend:

| Sample number | | Units | | |
|---------------|--|-------|-------------|---------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | NF Non Friable material. |
| L#### | Paint sample collected | LF | Linear feet | F Friable material |
| P#### | PCB sample collected | EA | Each | PF Potentially Friable material |
| M#### | Mould sample collected | % | Percentage | |
| V#### | Material visually similar to numbered sample collected | | | |
| V0000 | Known non Hazardous Material | | | |
| V9000 | Material is visually identified as Hazardous Material | | | |
| V9500 | Material is presumed to be Hazardous Material | | | |
| [Loc. No.] | Abated Material | | | |

Client: Cowww

Site: 360 McPhillips Ave., Winnipeg, MB

Building Name: Garage (Bldg. F)

Survey Date:

| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
|----------|-----------|--|-----------|-------------|----|----|----|-----|-------------------|----------|------------|
| Asbestos | S0018 | Wall Exterior Plaster Plaster On Concrete, Exterior Wall Foundation, Garage Bldg (sample No. 0037 - August 28, 2015 - 1517151_plm) (for Sample 0018b-c It Was Sample No. 0037b-c- June 30, 2016 - B131169) | 44 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | V9500 | Wall Roof Roofing Material | 44 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | NF |
| Asbestos | V9500 | Wall Vermiculite | 12 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | F |
| Asbestos | V9500 | Wall Vermiculite/concrete Block Walls | 44 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | F |

Legend:

| Sample number | | Units | | |
|---------------|--|-------|-------------|---------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | NF Non Friable material. |
| L#### | Paint sample collected | LF | Linear feet | F Friable material |
| P#### | PCB sample collected | EA | Each | PF Potentially Friable material |
| M#### | Mould sample collected | % | Percentage | |
| V#### | Material visually similar to numbered sample collected | | | |
| V0000 | Known non Hazardous Material | | | |
| V9000 | Material is visually identified as Hazardous Material | | | |
| V9500 | Material is presumed to be Hazardous Material | | | |
| [Loc. No.] | Abated Material | | | |

Client: Cowww

Site: 360 McPhillips Ave., Winnipeg, MB

Building Name: Storage Shed (Bldg. E)

Survey Date:

| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
|----------|-----------|--|-----------|-------------|----|----|----|-----|-------------------|----------|------------|
| Asbestos | V0018 | Wall Exterior Plaster Plaster On Concrete, Exterior Wall Foundation, Garage Bldg (sample No. 0037 - August 28, 2015 - 1517151_plm) (for Sample 0018b-c It Was Sample No. 0037b-c- June 30, 2016 - B131169) | 45 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | V9500 | Other Roof Roofing Material | 45 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | NF |
| Asbestos | V9500 | Wall Vermiculite/concrete Block Walls | 40,45 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | F |

Legend:

| Sample number | | Units | | |
|---------------|--|-------|-------------|---------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | NF Non Friable material. |
| L#### | Paint sample collected | LF | Linear feet | F Friable material |
| P#### | PCB sample collected | EA | Each | PF Potentially Friable material |
| M#### | Mould sample collected | % | Percentage | |
| V#### | Material visually similar to numbered sample collected | | | |
| V0000 | Known non Hazardous Material | | | |
| V9000 | Material is visually identified as Hazardous Material | | | |
| V9500 | Material is presumed to be Hazardous Material | | | |
| [Loc. No.] | Abated Material | | | |

Client: Cowww

Site: 360 McPhillips Ave., Winnipeg, MB

Building Name: Pump Building (Bldg. A)

Survey Date:

| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
|----------|-----------|--|-----------|-------------|-----|-----|----|-----|---------------|----------|------------|
| Asbestos | S0001 | Piping Rain Water Leader Sweatwrap / Fai / Gen / Loc 1 | 1,2,4,7 | A | 228 | 0 | 0 | 0 | Chrysotile | Yes | NF, F |
| Asbestos | S0002 | Piping Domestic Water (hot And Cold) Sweat Wrap Pipe Insulation Sweatwrap / Dw / Loc 1 | 1 | A | 0 | 0 | 0 | 800 | None Detected | No | |
| Asbestos | S0003 | Duct Generator Exhaust Magnesia Block Magblock / Gene / Loc 1 | 1 | A | 145 | 0 | 0 | 0 | Chrysotile | Yes | F |
| Asbestos | V0004 | Piping Chilled Water Return, Rain Water Leader Parging Cement Parging / Ftg / Dw / Loc 1 | 1 | A | 0 | 0 | 9 | 0 | Chrysotile | Yes | F |
| Asbestos | S0005 | Piping City Water/service Water Parging Over Fibreglass Parging / Ftg / Fai / Gen / Loc 1 | 1 | A | 0 | 0 | 8 | 0 | Chrysotile | Yes | F |
| Asbestos | S0006 | Piping Heating Water Supply, Heating Water Return Parging Over Fibreglass Parging / Ftg / Hws / Loc 2 | 2 | A | 0 | 0 | 12 | 0 | Chrysotile | Yes | F |
| Asbestos | V0007 | Piping Rain Water Leader Parging Cement Parging / Ftg / Rwl / Loc 9 | 2,4,7 | A | 0 | 0 | 9 | 0 | Chrysotile | Yes | F |
| Asbestos | S0012 | Floor All Vinyl Floor Tile And Mastic Vinyl Floor Tiles (grey With Black Stripes) (homogenous, Beige, Consolidated Rubbery) (homogenous, Yellow, Soft, Sticky Material On Back), Control Room-pump Bldg, Loc No. 05, Mcphilips Pumping Station | 5 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0014 | Wall Exterior Plaster Stucco Plaster, Exterior Wall, Pump Bldg (sample No. 0033 - August 28, 2015 - 1517151_plm) (for Sample 0014b-c It Was Sample No. 0033b-c- June 30, 2016 - B131169) | 42 | A | 0 | 422 | 0 | 0 | None Detected | No | |
| Asbestos | S0015 | Wall Exterior Plaster Plaster On Concrete, Exterior Wall Foundation, Pump Bldg (sample No. 0034- August 28, 2015 - 1517151_plm) (for Sample 0015b-c It Was Sample No. 0034b-c- June 30, 2016 - B131169) | 42 | A | 0 | 360 | 0 | 0 | None Detected | No | |
| Asbestos | S0016 | Wall Exterior Tar Black Tar, Exterior Wall, Pump Bldg (sample No. 0035 - August 28, 2015) 1517151_plm | 42 | A | 0 | 0 | 0 | 100 | Chrysotile | Yes | NF |
| Asbestos | S0019 | Wall All Mortar Grout/cement Mortar/plaster On Block Walls, Control Room (loc. 5) And Electrical Room (loc. 6), Pump Bldg. (october 23, 2019 - Lab Ref. B220159) | 5,6 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0020 | Wall All Mortar Thin Set Back Of Blue Tile, Vestibule/stairwell (loc. 4), Pump Bldg. (october 23, 2019 - Lab Ref. B220159) | 4 | A | 0 | 0 | 0 | 100 | None Detected | No | |

| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
|----------|-----------|---|-----------|-------------|----|----|----|-----|-------------------|----------|------------|
| Asbestos | S0021 | Floor All Adhesive/mastic Adhesive Mastic And Terrazo Tile (loc. 2 & 3), Chlorine Room And Washroom, Pump Bldg. (jan. 15, 2020 - Lab. Ref. B224880 | 2,3 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0022 | Floor All Plaster Plaster/grout On Terrazo Tile (loc. 2 & 3), Chlorine Room And Washroom, Pump Bldg. (jan. 15, 2020 - Lab. Ref. B224880 | 2,3 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0023 | Wall All Mortar Plaster/grout On Cinder Block Walls (loc. 2, 3 & 7), Chlorine Room, Washroom And Filter Room, Pump Bldg. (jan. 15, 2020 - Lab. Ref. B224880 | 2,3,7 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0025 | Floor All Mortar Plaster/grout On Ceramic Tile (loc. 1), Pump Floor, Pump Bldg. (jan. 15, 2020 - Lab. Ref. B224880 | 1 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | V9500 | Other Built Up Roofing Roofing Material | 42 | A | 0 | 0 | 0 | 0 | Presumed Asbestos | Yes | NF |
| Asbestos | V0000 | Floor All Adhesive/mastic | 4 | A | 0 | 0 | 0 | 100 | Non Asbestos | No | |
| Asbestos | V0000 | Floor All Plaster | 4 | A | 0 | 0 | 0 | 100 | Non Asbestos | No | |
| Asbestos | V0000 | Piping Chilled Water Return, Chilled Water Supply Fibreglass | 1,7 | A | 14 | 0 | 2 | 0 | Non Asbestos | No | |
| Asbestos | V0000 | Wall Mortar | 4 | A | 0 | 0 | 0 | 0 | Non Asbestos | No | |
| Asbestos | V0000 | Wall All Plaster | 42 | A | 0 | 0 | 0 | 100 | Non Asbestos | No | |

Legend:

| Sample number | | Units | | | |
|---------------|--|-------|-------------|----|------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | NF | Non Friable material. |
| L#### | Paint sample collected | LF | Linear feet | F | Friable material |
| P#### | PCB sample collected | EA | Each | PF | Potentially Friable material |
| M#### | Mould sample collected | % | Percentage | | |
| V#### | Material visually similar to numbered sample collected | | | | |
| V0000 | Known non Hazardous Material | | | | |
| V9000 | Material is visually identified as Hazardous Material | | | | |
| V9500 | Material is presumed to be Hazardous Material | | | | |
| [Loc. No.] | Abated Material | | | | |

| Client: Cowww | | Site: 360 McPhillips Ave., Winnipeg, MB | | Building Name: Old Pump Building (Bldg. D) | | | | Survey Date: | | | |
|---------------|-----------|--|-----------|--|----|------|----|--------------|--------------------------|----------|------------|
| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
| Asbestos | V0002 | Piping Domestic Water (hot And Cold) Sweat Wrap Pipe Insulation Sweatwrap / Dw / Loc 1 | 21,36,39 | A | 70 | 0 | 0 | 0 | None Detected | No | |
| Asbestos | V0004 | Piping Domestic Water (hot And Cold) Parging Over Fibreglass Parging / Ftg / Dw / Loc 1 | 21,36,39 | A | 0 | 0 | 17 | 0 | Chrysotile | Yes | F, NF |
| Asbestos | S0008 | Ceiling Ceiling Tiles (lay-in) Ceiling Tile / At-1 / 24 X 48 Lay In / Loc 13 | 13,14,15 | A | 0 | 1266 | 0 | 0 | None Detected | No | |
| Asbestos | V0009 | Ceiling Ceiling Tiles (glue-on) Ceiling Tile / At-2 / 12 X 12 Glued On / Loc 18 | 17,18,20 | A | 0 | 175 | 0 | 0 | None Detected | No | |
| Asbestos | S0010 | Wall Plaster Plaster Wall / Shop / Old Pump Building / Loc 22 | 22 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0011 | Ceiling All Ceiling Tiles (lay-in) Ceiling Tile / Shop / Old Pump Building / Loc 22 Note: From Proj. No. 64431/s-0001/lab Ref:b78109/dated Jan. 27, 2011 | 22 | A | 0 | 0 | 0 | 100 | Chrysotile | Yes | PF |
| Asbestos | S0017 | Wall Plaster Plaster On Concrete, Exterior Wall, Old Pump Bldg (sample No. 0036 - August 28, 2015 - 1517151_plm) (for Sample 0017b-c It Was Sample No. 0036b-c- June 30, 2016 - B131169) | 41 | A | 0 | 300 | 0 | 0 | None Detected | No | |
| Asbestos | S0019 | Floor All Terrazzo Terrazo Floor, Electrical Room And Shop Floor (loc. 30 & 22), Old Pump Bldg.(jan. 15, 2020 - B224882) | 22,30 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0020 | Wall Drywall And Joint Compound Drywall Joint Cpd. On Walls, Electrical Room And Generator Room(loc. 30 & 31), Old Pump Bldg. (jan. 15, 2020 - B224882) | 30,31 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0021 | Wall All Plaster Plaster/grout On Masonry Block Walls, Electrical Room And Generator Room(loc. 30 & 31), Old Pump Bldg.(jan. 15, 2020 - B224882) | 30,31 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0023 | Wall All Mortar Plaster/grout On Ceramic Clay Tile On Walls, Electrical Room And Generator Room(loc. 30 & 31), Old Pump Bldg. (jan. 15, 2020 - B224882) | 30 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0024 | Wall All Plaster Plaster/grout On Quarry Tiles On Walls, Generator Room And Shop Floor(loc. 31 & 22), Old Pump Bldg.(jan. 15, 2020 - B224882) | 22,31 | A | 0 | 0 | 0 | 100 | None Detected | No | |
| Asbestos | S0025 | Wall Vermiculite/concrete Block Walls Vermiculite Insulation In Masonry Block Walls, Electrical Room And Generator Room(loc. 30 & 31), Old Pump Bldg.(jan. 15, 2020 - B224883) | 30,31 | A | 0 | 5 | 0 | 100 | Libby Amphibole Detected | Yes | F |

| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
|----------|-----------|--|-------------------------|-------------|----|------|----|-----|--------------------|----------|------------|
| Asbestos | V9000 | Ceiling Cement Product | 16 | A | 0 | 128 | 0 | 0 | Confirmed Asbestos | Yes | NF |
| Asbestos | V9000 | Wall Cement Product | 13,16,17 | A | 0 | 914 | 0 | 0 | Confirmed Asbestos | Yes | NF |
| Asbestos | V9500 | Ceiling Drywall And Joint Compound | 13,14,15 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | NF |
| Asbestos | V9500 | Other Built Up Roofing Roofing Material | 41 | A | 0 | 0 | 0 | 0 | Presumed Asbestos | Yes | NF |
| Asbestos | V9500 | Wall Drywall And Joint Compound | 13,14,15,28,29 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | NF |
| Asbestos | V9500 | Wall All Mortar | 28,29 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | NF |
| Asbestos | V9500 | Wall Vermiculite | 18,20,22,27,28,35 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | F |
| Asbestos | V9500 | Wall Vermiculite/concrete Block Walls | 21,29 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | F |
| Asbestos | V0000 | Floor Vinyl Sheet Flooring | 13,14,15,16,17,24,25,31 | A | 0 | 2316 | 0 | 0 | Non Asbestos | No | |

Legend:

| Sample number | | Units | | |
|---------------|--|-------|-------------|---------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | NF Non Friable material. |
| L#### | Paint sample collected | LF | Linear feet | F Friable material |
| P#### | PCB sample collected | EA | Each | PF Potentially Friable material |
| M#### | Mould sample collected | % | Percentage | |
| V#### | Material visually similar to numbered sample collected | | | |
| V0000 | Known non Hazardous Material | | | |
| V9000 | Material is visually identified as Hazardous Material | | | |
| V9500 | Material is presumed to be Hazardous Material | | | |
| [Loc. No.] | Abated Material | | | |

APPENDIX V
HMIS Data Report

Client: Cowww
Location: #12 : Garage - Garage
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Garage

Building Name: Garage (Bldg. F)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 960

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-----------------------|----------------|-----------------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Drywall (no compound) | | | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Joist | Wood | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | Drywall (no compound) | B | N | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |
| Wall | | Drywall (no compound) | | | | | | | | | | | | | | |

Masonry walls suspect to contain asbestos containing vermiculite insulation.

Client: Cowww
Location: #44 : Garage Building Exterior
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: NA

Building Name: Garage (Bldg. F)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 0

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------------|------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |
| Wall | Exterior | Plaster | Base | Paint | A | Y | | 100 | | | % | S0018 | None Detected | N.D. | None | |
| Wall | Exterior | Masonry | Surface | Paint | A | Y | | | | | | | | | | |
| Wall | Roof | Roofing material | Surface | | C | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |

Masonry walls suspect to contain asbestos containing vermiculite insulation. Roof sections needs to be tested prior to any renovation

Legend:

| Sample number | | Units | | Other | |
|---------------|--|-------|-------------|-------|------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | A | Access |
| V#### | Material visually similar to numbered sample collected | LF | Linear feet | V | Visible |
| V0000 | Known non-asbestos material | EA | Each | AP | Air Plenum |
| V9000 | Visually identified as an asbestos material | % | Percentage | F | Friable material |
| V9500 | Material is presumed to be an asbestos material | | | NF | Non Friable material |
| | | | | PF | Potentially Friable material |

| Access | |
|--------|---|
| A | Accessible to all building occupants |
| B | Accessible to maintenance and operations staff without a ladder |
| C | Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas |
| D | Not normally accessible |

| Condition | |
|-----------|---|
| Good | No visible damage or deterioration |
| Fair | Minor, repairable damage, cracking, delamination or deterioration |
| Poor | Irreparable damage or deterioration with exposed and missing material |

| Visible | |
|---------|---|
| Y | The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels). |
| N | The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. |

| Air Plenum | |
|------------|---|
| Yes or No | The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation. |

| Colour Coding | |
|--|---|
|  | The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code). |
|  | The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling. |

Client: Cowww
Location: #1 : Pump Building - Basement
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Basement-Pump Building

Building Name: Pump Building (Bldg. A)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 9000

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | N/A | No Information | NI | | | | | | | | | | | | |
| Duct | Generator Exhaust | Magnesia block | System | Metal | C | Y | | 145 | | | LF | S0003 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Floor ¹ | All | Mortar | Surface | Ceramic Tiles | A | Y | | 100 | | | % | S0025 | None Detected | N.D. | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Chilled Water Return | Fibreglass | Straight | Canvas | C | Y | | | | | | V0000 | Non-Asbestos | | None | |
| Piping | Chilled Water Return | Parging Cement | Fitting | Canvas | C | Y | | 5 | | | EA | V0004 | Chrysotile | 10-25% | Confirmed Asbestos | F |
| Piping | Chilled Water Supply | Fibreglass | Straight | Canvas | C | Y | | | | | | V0000 | Non-Asbestos | | None | |
| Piping | City Water/service Water | Parging over Fibreglass | Fitting | Canvas | C | Y | | 8 | | | EA | S0005 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | Domestic Water (hot And Cold) | Sweat Wrap pipe insulation | Straight | Canvas | C | Y | | 800 | | | % | S0002 | None Detected | N.D. | None | |
| Piping | Rain Water Leader | | Straight | Canvas | C | Y | | 40 | | | LF | S0001 | Chrysotile | 50-75% | Confirmed Asbestos | |
| Piping | Rain Water Leader | Parging Cement | Fitting | Canvas | C | Y | | 4 | | | EA | V0004 | Chrysotile | 10-25% | Confirmed Asbestos | F |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Setting compound on ceramic tiles is found not to contain asbestos.

1 - setting compound

Client: Cowww
Location: #2 : Pump Building - Chlorine Analyzer Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Pump Building

Building Name: Pump Building (Bldg. A)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 225

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|----------------------|----------------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Floor | All | Plaster | Surface | Ceramic Tiles | A | Y | | 100 | | | % | S0022 | None Detected | N.D. | None | |
| Floor | All | Adhesive/mastic | Surface | Ceramic Tiles | A | N | | 100 | | | % | S0021 | None Detected | N.D. | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Heating Water Return | Fibreglass | Straight | Canvas | C | Y | | | | | | | | | | |
| Piping | Heating Water Return | Parging over Fibreglass | Fitting | Canvas | C | Y | | 6 | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | Heating Water Supply | Fibreglass | Straight | Canvas | C | Y | | | 3 | | | | | | | |
| Piping | Heating Water Supply | Parging over Fibreglass | Fitting | Canvas | C | Y | | 6 | | | EA | S0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | Rain Water Leader | Parging over Fibreglass | Fitting | Canvas | C | Y | | 2 | | | EA | V0007 | Chrysotile | 10-25% | Confirmed Asbestos | F |
| Piping | Rain Water Leader | Sweat Wrap pipe insulation | Straight | Canvas | C | Y | | 16 | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | All | Mortar | Surface | Masonry | A | Y | | 100 | | | % | S0023 | None Detected | N.D. | None | |

There was no vermiculite insulation found inside masonry block walls. Mortar on Masonry walls confirmed non-asbestos

Client: Cowww
Location: #3 : Pump Building - Washroom
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Pump Building

Building Name: Pump Building (Bldg. A)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 75

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-----------------|----------------|---------------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Metal | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | IN | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Floor | All | Plaster | Surface | Ceramic Tiles | A | Y | | 100 | | | % | S0022 | None Detected | N.D. | None | |
| Floor | All | Adhesive/mastic | Surface | Ceramic Tiles | A | N | | 100 | | | % | S0021 | None Detected | N.D. | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | IN | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | IN | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | IN | | | | |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | All | Mortar | Surface | Masonry | A | Y | | 100 | | | % | S0023 | None Detected | N.D. | None | |

There was no vermiculite insulation found inside masonry block walls. Mortar on Masonry walls confirmed non-asbestos

Client: Cowww
Location: #4 : Pump Building - Vestibule/Stairwell
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Pump Building

Building Name: Pump Building (Bldg. A)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 450

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|----------------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Metal | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Floor ¹ | All | Plaster | Surface | Ceramic Tiles | A | Y | | 100 | | | % | V0000 | Non-Asbestos | | None | |
| Floor ² | All | Adhesive/mastic | Surface | Ceramic Tiles | A | N | | 100 | | | % | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Rain Water Leader | Parging over Fibreglass | Fitting | Canvas | C | Y | | 3 | | | EA | V0007 | Chrysotile | 10-25% | Confirmed Asbestos | F |
| Piping | Rain Water Leader | Sweat Wrap pipe insulation | Straight | Canvas | C | N | | 150 | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall ³ | | Mortar | No Information | Masonry | | | | | | | | V0000 | Non-Asbestos | | None | |
| Wall | All | Mortar | Surface | Ceramic Tiles | A | Y | | 100 | | | % | S0020 | None Detected | N.D. | None | |

2019 - Confirmed no vermiculite in hollow core walls Mortar on Masonry walls confirmed non-asbestos

- 1 - Determined to be non-asbestos by representative sampling in other locations
- 2 - Determined to be non-asbestos by representative sampling in other locations
- 3 - Drilled hollow cor - no vermiculite present

Client: Cowww
Location: #5 : Pump Building - Control Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Pump Building

Building Name: Pump Building (Bldg. A)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 350

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------------|-----------------------------|----------------|-----------------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Metal | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Floor | All | Vinyl Floor Tile and Mastic | Not Applicable | N/A | B | Y | | 100 | | | % | S0012 | None Detected | N.D. | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Electrical Panel | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Piping | All | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | All | Mortar | Surface | Preformed Block | A | Y | | 100 | | | % | S0019 | None Detected | N.D. | None | |

No vermiculite insulation found inside masonry walls October 9, 2019 Mortar on Masonry walls confirmed non-asbestos

Client: Cowww
Location: #6 : Pump Building - Electrical Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Pump Building

Building Name: Pump Building (Bldg. A)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------------|---------------|----------------|-----------------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Metal | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Electrical Panel | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall ¹ | | Masonry | No Information | | | | | | | | | 0000 | Non-Asbestos | | | |
| Wall | All | Mortar | Surface | Preformed Block | A | Y | | 100 | | | % | S0019 | None Detected | N.D. | None | |

2019 - Masonry walls confirmed - no vermiculite insulation. Mortar on Masonry walls confirmed non-asbestos
1 - Drilled test holes, no vermiculite present

Client: Cowww
Location: #7 : Pump Building - Filter Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Pump Building

Building Name: Pump Building (Bldg. A)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 250

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|----------------------|-------------------|----------------|------------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Concrete (poured) | No Information | Paint | | Y | | | | | | | | | | |
| Ceiling | | Concrete (poured) | | | | | | | | | | | | | | |
| Ceiling | | Metal | No Information | Paint | | | | | | | | | | | | |
| Duct | Not Found | NI | | | | | | | | | | | | | | |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | | | | | | | | | | | | | | |
| Mechanical Equipment | Air Handling Unit | Fibreglass | | Canvas | B | Y | | | | | | | | | | |
| Mechanical Equipment | Air Handling Unit | Not Insulated | No Information | Fibreglass | B | Y | | | | | | | | | | |
| Mechanical Equipment | Motor | Not Insulated | | | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Chilled Water Return | Fibreglass | Straight | Canvas | B | Y | | 7 | | | LF | V0000 | Non-Asbestos | | None | |
| Piping | Chilled Water Return | Fibreglass | Fitting | Canvas | B | Y | | 1 | | | EA | V0000 | Non-Asbestos | | None | |
| Piping | Chilled Water Return | Fibreglass | Straight | Canvas | B | Y | | | | | | | | | | |
| Piping | Chilled Water Return | Abated Material | Fitting | Canvas | B | Y | | | | | EA | V0004 | [None] | 10-25% | [Abated] | |
| Piping | Chilled Water Supply | Fibreglass | Straight | Canvas | B | Y | | 7 | | | LF | V0000 | Non-Asbestos | | None | |
| Piping | Chilled Water Supply | Fibreglass | Fitting | Canvas | B | Y | | 1 | | | EA | V0000 | Non-Asbestos | | None | |
| Piping | Chilled Water Supply | Fibreglass | Straight | Canvas | B | Y | | | | | | | | | | |
| Piping | Chilled Water Supply | Abated Material | Fitting | Canvas | B | Y | | | | | EA | V0004 | [None] | 10-25% | [Abated] | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Rain Water Leader | Parging Cement | Fitting | Canvas | C | Y | | 4 | | | EA | V0007 | Chrysotile | 10-25% | Confirmed Asbestos | F |
| Piping | Rain Water Leader | Sweatwrap | Straight | Canvas | C | Y | | 22 | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Structure | | Steel | | | | | | | | | | | | | | |
| Structure | Beam, Deck | Metal | No Information | Paint | | | | | | | | | | | | |
| Wall | | Concrete (poured) | | | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|---------------|---------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Ceramic Tiles | | | | | | | | | | | | | | |
| Wall | All | Mortar | Surface | Masonry | A | Y | | 100 | | | % | S0023 | None Detected | N.D. | None | |

There was no vermiculite insulation found inside masonry block walls. Mortar on Masonry walls confirmed non-asbestos

Client: Cowww
Location: #42 : Pump Building Exterior
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: NA

Building Name: Pump Building (Bldg. A)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 0

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|------------------|-------------------|---------|-------------------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other | Built Up Roofing | Roofing material | | | | | | | | | | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Masonry | | Clay Tile (block) | B | N | | | | | | | | | | |
| Wall | All | Plaster | Surface | Quarry tile | A | Y | | 100 | | | % | V0000 | Non-Asbestos | | None | |
| Wall | Exterior | Clay Tile (block) | Surface | N/A | A | Y | | | | | | | | | | |
| Wall | Exterior | Plaster | Surface | Paint | A | Y | | 420 | | 2 | SF | S0014 | None Detected | N.D. | None | |
| Wall | Exterior | Plaster | Base | N/A | A | Y | | 360 | | | SF | S0015 | None Detected | N.D. | None | |
| Wall | Exterior | Tar | | | A | Y | | 100 | | | % | S0016 | Chrysotile | 5-10% | Confirmed Asbestos | NF |

2019 - Confirmed No vermiculite in hollow core walls Roof sections needs to be tested prior to any renovation or demolition activities. July 2020 Exterior Stucco Does not contain asbestos 275519

Legend:

| Sample number | | Units | | Other | |
|---------------|--|-------|-------------|-------|------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | A | Access |
| V#### | Material visually similar to numbered sample collected | LF | Linear feet | V | Visible |
| V0000 | Known non-asbestos material | EA | Each | AP | Air Plenum |
| V9000 | Visually identified as an asbestos material | % | Percentage | F | Friable material |
| V9500 | Material is presumed to be an asbestos material | | | NF | Non Friable material |
| | | | | PF | Potentially Friable material |

| Access | |
|--------|---|
| A | Accessible to all building occupants |
| B | Accessible to maintenance and operations staff without a ladder |
| C | Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas |
| D | Not normally accessible |

| Condition | |
|-----------|---|
| Good | No visible damage or deterioration |
| Fair | Minor, repairable damage, cracking, delamination or deterioration |
| Poor | Irreparable damage or deterioration with exposed and missing material |

| Visible | |
|---------|---|
| Y | The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels). |
| N | The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. |

| Air Plenum | |
|------------|---|
| Yes or No | The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation. |

| Colour Coding | |
|--|---|
|  | The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code). |
|  | The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling. |

Client: Cowww
Location: #40 : Storage Shed - Storage Shed
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Storage Shed

Building Name: Storage Shed (Bldg. E)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|----------------------------------|----------------|-----------------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Drywall (no compound) | | | | | | | | | | | | | | |
| Duct | Exhaust | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Joist | Wood | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | Drywall (no compound) | B | N | | | | | | | | | | |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |
| Wall | | Drywall (no compound) | | | | | | | | | | | | | | |

Masonry walls suspect to contain asbestos containing vermiculite insulation.

Client: Cowww
Location: #45 : Storage Building Exterior
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: NA

Building Name: Storage Shed (Bldg. E)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 0

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------------|------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other | Roof | Roofing material | Surface | | C | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |
| Wall | Exterior | Plaster | Base | Paint | A | Y | | 100 | | | % | V0018 | None Detected | N.D. | None | |
| Wall | Exterior | Masonry | Surface | Paint | A | Y | | | | | | | | | | |

Masonry walls suspect to contain asbestos containing vermiculite insulation. Roof sections needs to be tested prior to any renovation or demolition activities.

Legend:

| Sample number | | Units | | Other | |
|---------------|--|-------|-------------|-------|------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | A | Access |
| V#### | Material visually similar to numbered sample collected | LF | Linear feet | V | Visible |
| V0000 | Known non-asbestos material | EA | Each | AP | Air Plenum |
| V9000 | Visually identified as an asbestos material | % | Percentage | F | Friable material |
| V9500 | Material is presumed to be an asbestos material | | | NF | Non Friable material |
| | | | | PF | Potentially Friable material |

| Access | |
|--------|---|
| A | Accessible to all building occupants |
| B | Accessible to maintenance and operations staff without a ladder |
| C | Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas |
| D | Not normally accessible |

| Condition | |
|-----------|---|
| Good | No visible damage or deterioration |
| Fair | Minor, repairable damage, cracking, delamination or deterioration |
| Poor | Irreparable damage or deterioration with exposed and missing material |

| Visible | |
|---------|---|
| Y | The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels). |
| N | The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. |

| Air Plenum | |
|------------|---|
| Yes or No | The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation. |

| Colour Coding | |
|--|---|
|  | The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code). |
|  | The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling. |

Client: Cowww
Location: #8 : Chlorine Building - Chlorine
Tonner Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Chlorine Building

Building Name: Chlorine Building (Bldg. B)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 1200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|-------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Rain Water Leader | | Straight | Canvas | C | Y | | 40 | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | |
| Piping | Rain Water Leader | Parging over Fibreglass | Fitting | Canvas | C | Y | | 6 | | | EA | V0007 | Chrysotile | 10-25% | Confirmed Asbestos | F |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | 1230 | | | SF | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V0000 | Non-Asbestos | | None | |
| Wall | All | Mortar | Surface | Masonry | A | Y | | 100 | | | % | S0019 | None Detected | N.D. | None | |

There was no vermiculite insulation found inside masonry block walls. Mortar on masonry walls is not asbestos containing.

Client: Cowww
Location: #9 : Chlorine Building - Chlorinator Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Chlorine Building

Building Name: Chlorine Building (Bldg. B)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|-------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Rain Water Leader | | Straight | Canvas | C | Y | | 45 | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | |
| Piping | Rain Water Leader | Parging over Fibreglass | Fitting | Canvas | C | Y | | 6 | | | EA | S0007 | Chrysotile | 10-25% | Confirmed Asbestos | F |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | 600 | | | SF | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V0000 | Non-Asbestos | | None | |
| Wall | All | Mortar | Surface | Masonry | A | Y | | 100 | | | % | S0019 | None Detected | N.D. | None | |

There was no vermiculite insulation found inside masonry block walls. Mortar on masonry walls is not asbestos containing.

Client: Cowww
Location: #10 : Chlorine Building - Vestibule
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Chlorine Building

Building Name: Chlorine Building (Bldg. B)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 40

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |
| Wall | All | Mortar | Surface | Masonry | A | Y | | 100 | | | % | V0019 | None Detected | N.D. | None | |

Masonry walls suspect to contain asbestos containing vermiculite insulation. Mortar on masonry walls is not asbestos containing.

Client: Cowww
Location: #11 : Chlorine Building - Stairwell
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Chlorine Building

Building Name: Chlorine Building (Bldg. B)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 160

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|-------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Rain Water Leader | | Straight | Canvas | C | Y | | 8 | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | |
| Piping | Rain Water Leader | Parging over Fibreglass | Fitting | Canvas | C | Y | | 3 | | | EA | V0007 | Chrysotile | 10-25% | Confirmed Asbestos | F |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |
| Wall | All | Mortar | Surface | Masonry | A | Y | | 100 | | | % | V0019 | None Detected | N.D. | None | |

Masonry walls suspect to contain asbestos containing vermiculite insulation. Mortar on masonry walls is not asbestos containing.

Client: Cowww
Location: #43 : Chlorine Building Exterior
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: NA

Building Name: Chlorine Building (Bldg. B)
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 0

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|-------------------|---------|-------------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other | Roof | Roofing material | | | | | | | | | | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Masonry | | Clay Tile (block) | B | N | | | | | | | | | | |
| Wall | All | Mortar | Surface | Masonry | A | Y | | 100 | | | % | V0019 | None Detected | N.D. | None | |
| Wall | Exterior | Clay Tile (block) | Surface | N/A | A | Y | | | | | | | | | | |
| Wall | Exterior | Plaster | Base | N/A | A | Y | | 100 | | | % | V0015 | None Detected | N.D. | None | |

2019 - Confirmed No vermiculite in hollow core walls. Roof sections needs to be tested prior to any renovation or demolition activities. Mortar on masonry walls is not asbestos containing.

Legend:

| Sample number | | Units | | Other | |
|---------------|--|-------|-------------|-------|------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | A | Access |
| V#### | Material visually similar to numbered sample collected | LF | Linear feet | V | Visible |
| V0000 | Known non-asbestos material | EA | Each | AP | Air Plenum |
| V9000 | Visually identified as an asbestos material | % | Percentage | F | Friable material |
| V9500 | Material is presumed to be an asbestos material | | | NF | Non Friable material |
| | | | | PF | Potentially Friable material |

| Access | |
|--------|---|
| A | Accessible to all building occupants |
| B | Accessible to maintenance and operations staff without a ladder |
| C | Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas |
| D | Not normally accessible |

| Condition | |
|-----------|---|
| Good | No visible damage or deterioration |
| Fair | Minor, repairable damage, cracking, delamination or deterioration |
| Poor | Irreparable damage or deterioration with exposed and missing material |

| Visible | |
|---------|---|
| Y | The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels). |
| N | The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. |

| Air Plenum | |
|------------|---|
| Yes or No | The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation. |

| Colour Coding | |
|--|---|
|  | The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code). |
|  | The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling. |

Client: Cowww
Location: #13 : Old Pump Building - Dispatch
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Second-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 1050

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|----------------|----------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|--------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Ceiling Tiles (lay-in) | Surface | N/A | C | Y | | 1050 | | | SF | S0008 | None Detected | N.D. | None | |
| Ceiling | | Drywall and joint compound | | | C | | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Vinyl Sheet Flooring | Surface | N/A | A | Y | | 1050 | | | SF | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Not Accessible | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Drywall and joint compound | | | A | | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | | Cement Product | Surface | | A | Y | | 450 | | | SF | V9000 | Confirmed Asbestos | | Confirmed Asbestos | NF |

Client: Cowww
Location: #14 : Old Pump Building - Office
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Second-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 108

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|----------------|----------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Ceiling Tiles (lay-in) | Surface | N/A | C | Y | | 108 | | | SF | V0008 | None Detected | N.D. | None | |
| Ceiling | | Drywall and joint compound | | | C | | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Vinyl Sheet Flooring | Surface | N/A | A | Y | | 108 | | | SF | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Not Accessible | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Drywall and joint compound | | | A | | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |

Client: Cowww
Location: #15 : Old Pump Building - Office
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Second-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 108

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|----------------|----------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Ceiling Tiles (lay-in) | Surface | N/A | C | Y | | 108 | | | SF | V0008 | None Detected | N.D. | None | |
| Ceiling | | Drywall and joint compound | | | C | | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Vinyl Sheet Flooring | Surface | N/A | A | Y | | 108 | | | SF | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Not Accessible | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Drywall and joint compound | | | A | | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |

Drywall joint compound of the drywall sections needs to be tested prior to any renovation or demolition works

Client: Cowww
Location: #16 : Old Pump Building - Washroom
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Second-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 85

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|----------------|----------------------|----------------|----------|----|----|-----|------|------|------|------|--------|--------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Cement Product | Surface | | A | Y | | 128 | | | SF | V9000 | Confirmed Asbestos | | Confirmed Asbestos | NF |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Vinyl Sheet Flooring | Surface | N/A | A | Y | | 85 | | | SF | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Not Accessible | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Cement Product | Surface | | A | Y | | 352 | | | SF | V9000 | Confirmed Asbestos | | Confirmed Asbestos | NF |

Client: Cowww
Location: #17 : Old Pump Building - Vestibule
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Second-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 35

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|--------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Ceiling tiles (glue-on) | Surface | N/A | C | Y | | 35 | | | SF | V0009 | None Detected | N.D. | None | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Vinyl Sheet Flooring | Surface | N/A | A | Y | | 35 | | | SF | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Wood | | | | | | | | | | | | | | |
| Wall | | Cement Product | Surface | | A | Y | | 112 | | | SF | V9000 | Confirmed Asbestos | | Confirmed Asbestos | NF |

Client: Cowww
Location: #18 : Old Pump Building - Stairwell
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Second-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 70

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Ceiling tiles (glue-on) | Surface | N/A | C | Y | | 70 | | | SF | V0009 | None Detected | N.D. | None | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | All | Terrazzo | Surface | | A | Y | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain asbestos containing vermiculite insulation.

Client: Cowww
Location: #19 : Old Pump Building - Storage
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Third-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 120

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |

Client: Cowww
Location: #20 : Old Pump Building - Hallway
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 70

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Ceiling tiles (glue-on) | Surface | N/A | C | Y | | 70 | | | SF | V0009 | None Detected | N.D. | None | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | All | Terrazzo | Surface | | A | Y | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Wood | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain asbestos containing vermiculite insulation.

Client: Cowww
Location: #21 : Old Pump Building - Furnace Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Area (sqft): 105
Last Re-Assessment: 2023-06-13

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Fresh Air Intake | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Air Handling Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Parging over Fibreglass | Fitting | Canvas | B | Y | | 4 | 2 | 1 | EA | V0004 | Chrysotile | 10-25% | Confirmed Asbestos | F |
| Piping | Domestic Water (hot And Cold) | Sweat Wrap pipe insulation | Straight | Canvas | B | Y | | 20 | | | LF | V0002 | None Detected | N.D. | None | |
| Structure | Beam, Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Rain Water Leader Pipe is present at the back of the duct Masonry walls suspect to contain asbestos containing vermiculite insulation. Damage DW fittings present June 2017 and still present 2022

Client: Cowww
Location: #22 : Old Pump Building - Shop
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 1835

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|----------------|------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Metal | No Information | NI | | | | | | | | | | | | |
| Ceiling | All | Ceiling Tiles (lay-in) | No Information | Metal | C | N | | 100 | | | % | S0011 | Chrysotile | >75% | Confirmed Asbestos | PF |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | All | Terrazzo | Surface | N/A | A | Y | | 100 | | | % | S0019 | [None] | | [None] | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Not Accessible | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Plaster | Surface | N/A | A | Y | | 100 | | | % | S0010 | None Detected | N.D. | None | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |
| Wall | All | Mortar | Surface | Masonry | A | Y | | 100 | | | % | S0024 | None Detected | N.D. | None | |

Masonry walls suspect to contain asbestos containing vermiculite insulation.

Client: Cowww
Location: #23 : Old Pump Building - Office
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 140

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Wood | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | Surface | Carpet | A | Y | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Wood | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #24 : Old Pump Building - Office
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 160

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|----------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Wood | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Vinyl Sheet Flooring | Surface | Carpet | A | N | | 160 | | | SF | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Wood | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #25 : Old Pump Building - Office
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 170

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|----------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Wood | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Vinyl Sheet Flooring | Surface | N/A | A | Y | | 170 | | | SF | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Wood | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #26 : Old Pump Building - Office
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 154

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Wood | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | Surface | | A | Y | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Wood | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #27 : Old Pump Building - Tool Crib
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 240

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | All | Terrazzo | Surface | | A | Y | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Joist | Wood | No Information | NI | | | | | | | | | | | | |
| Wall | | Wood | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Location Demolished now part of location 22

Client: Cowww
Location: #28 : Old Pump Building - Washroom
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 132

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|----------------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Supply Air | Drywall (no compound) | | | | | | | | | | | | | | |
| Floor | All | Terrazzo | ALL | | A | Y | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Drywall and joint compound | | | A | | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |
| Wall | All | Mortar | Surface | Ceramic Tiles | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |

Masonry walls suspect to contain asbestos containing vermiculite insulation. Setting compound on ceramic wall tiles is presumed asbestos containing.

Client: Cowww
Location: #29 : Old Pump Building - Locker Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 425

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|----------------------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Exhaust | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | All | Terrazzo | Surface | | A | Y | | | | | | | | | | |
| Mechanical Equipment | Fan Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Drywall and joint compound | | | A | | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |
| Wall ¹ | All | Mortar | Surface | Ceramic Tiles | A | Y | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |

Masonry walls suspect to contain asbestos containing vermiculite insulation. Setting compound on ceramic tiles presumed asbestos
1 - setting compound

Client: Cowww
Location: #30 : Old Pump Building - Electrical Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Area (sqft): 200
Last Re-Assessment: 2023-06-13

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------------|----------------------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | | NI | No Information | NI | | | | | | | | | | | | |
| Floor | All | Terrazzo | Surface | N/A | A | Y | | 100 | | | % | S0019 | [None] | | [None] | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Electrical Panel | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Drywall and joint compound | | | A | | | 100 | | | % | S0020 | None Detected | N.D. | None | |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | | | 5 | SF | S0025 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 100 | | | % | S0025 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |
| Wall | All | Mortar | Surface | Masonry | A | Y | | 100 | | | % | S0021 | None Detected | N.D. | None | |
| Wall | All | Mortar | Surface | Ceramic Tiles | A | Y | | 100 | | | % | S0023 | None Detected | N.D. | None | |

Masonry walls contain asbestos containing vermiculite insulation.

Client: Cowww
Location: #31 : Old Pump Building - Generator Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Main-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Area (sqft): 600
Last Re-Assessment: 2023-06-13

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------------|----------------------------------|----------------|-----------------|----|----|-----|------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Exhaust | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Duct | Fresh Air Intake | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Vinyl Sheet Flooring | Surface | N/A | A | Y | | 600 | | | SF | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Generator Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Generator Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Generator Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Other | Electrical Panel | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite/concrete block walls | Insulation | Masonry | B | N | | 100 | | | % | S0025 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |
| Wall | | Drywall (no compound) | | | A | | | 100 | | | % | S0020 | None Detected | N.D. | None | |
| Wall | All | Plaster | Surface | Preformed Block | A | Y | | 100 | | | % | S0021 | None Detected | N.D. | None | |
| Wall | All | Plaster | Surface | Quarry tile | A | Y | | 100 | | | % | S0024 | None Detected | N.D. | None | |

Masonry walls contain asbestos containing vermiculite insulation.

Client: Cowww
Location: #32 : Old Pump Building - NE Corner
Storage Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Basement-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Area (sqft): 100
Last Re-Assessment: 2023-06-13

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #33 : Old Pump Building - Basement
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Basement-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Area (sqft): 1650
Last Re-Assessment: 2023-06-13

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #34 : Old Pump Building - Storage Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Basement-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Area (sqft): 200
Last Re-Assessment: 2023-06-13

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Wood | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Wood | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #35 : Old Pump Building - Record Storage Vault
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Basement-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Area (sqft): 150
Last Re-Assessment: 2023-06-13

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain asbestos containing vermiculite insulation.

Client: Cowww
Location: #36 : Old Pump Building - Crawlspace
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Basement-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 800

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Dirt | | | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Parging over Fibreglass | Fitting | Canvas | D | Y | | 5 | | | EA | V0004 | Chrysotile | 10-25% | Confirmed Asbestos | F |
| Piping | Domestic Water (hot And Cold) | Sweat Wrap pipe insulation | Straight | Canvas | D | Y | | 20 | | | LF | V0002 | None Detected | N.D. | None | |
| Structure | Beam, Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #37 : Old PUM Building - Hallway
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Basement-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 450

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #38 : Old Pump Building - Sump Pit Area
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Basement-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 80

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #39 : Old Pump Building - Sump Room
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: Basement-Old Pump Building

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------------------|----------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Domestic Water (hot And Cold) | Rubber Foam on Metal | Fitting | Canvas | B | Y | | 5 | | | EA | V0004 | Chrysotile | 10-25% | Confirmed Asbestos | NF |
| Piping | Domestic Water (hot And Cold) | Sweat Wrap pipe insulation | Straight | Canvas | B | Y | | 30 | | | LF | V0002 | None Detected | N.D. | None | |
| Structure | Beam, Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Client: Cowww
Location: #41 : Old Pump Building Exterior
Survey Date: 2023-06-09

Site: 360 McPhillips Ave., Winnipeg, MB
Floor: NA

Building Name: Old Pump Building (Bldg. D)
Room #:
Last Re-Assessment: 2023-06-13

Area (sqft): 0

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|------------------|-------------------|---------|-------------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other | Built Up Roofing | Roofing material | | | | | | | | | | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Clay Tile (block) | Surface | N/A | A | Y | | 100 | | | % | | | | | |
| Wall | | Plaster | Base | N/A | A | Y | | 300 | | | SF | S0017 | None Detected | N.D. | None | |
| Wall | | Masonry | | Clay Tile (block) | B | N | | 100 | | | % | | | | | |
| Wall | | Masonry | | | | | | | | | | | | | | |

Roof sections needs to be tested prior to any renovation or demolition activities.

Legend:

| Sample number | | Units | | Other | |
|---------------|--|-------|-------------|-------|------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | A | Access |
| V#### | Material visually similar to numbered sample collected | LF | Linear feet | V | Visible |
| V0000 | Known non-asbestos material | EA | Each | AP | Air Plenum |
| V9000 | Visually identified as an asbestos material | % | Percentage | F | Friable material |
| V9500 | Material is presumed to be an asbestos material | | | NF | Non Friable material |
| | | | | PF | Potentially Friable material |

| Access | |
|--------|---|
| A | Accessible to all building occupants |
| B | Accessible to maintenance and operations staff without a ladder |
| C | Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas |
| D | Not normally accessible |

| Condition | |
|-----------|---|
| Good | No visible damage or deterioration |
| Fair | Minor, repairable damage, cracking, delamination or deterioration |
| Poor | Irreparable damage or deterioration with exposed and missing material |

| Visible | |
|---------|---|
| Y | The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels). |
| N | The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. |

| Air Plenum | |
|------------|---|
| Yes or No | The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation. |

| Colour Coding | |
|--|---|
|  | The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code). |
|  | The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling. |



2023 Asbestos Reassessment

W.D. Hurst Pumping Station e
60 Hurst Way Winnipeg,
Manitoba

Prepared for:

**City of Winnipeg Water and
Waste Department**

110-1199 Pacific Avenue
Winnipeg, Manitoba R3E 3S8

August 16, 2023

Pinchin File: 327243.000



2023 Asbestos Reassessment

W.D. Hurst Pumping Station e, 60 Hurst Way Winnipeg, Manitoba
City of Winnipeg Water and Waste Department

August 16, 2023
Pinchin File: 327243.000

Issued to: City of Winnipeg Water and Waste Department
Issued on: August 16, 2023
Pinchin File: 327243.000
Issuing Office: Winnipeg, MB

Author:

Ken Brydges, C.E.T. LEED GA
Senior Project Manager
204.452.0983
kbrydges@pinchin.com

Reviewer:

Rodney Legault, C.E.T. EP
Operations Manager
204.452.0983
rlegault@pinchin.com



EXECUTIVE SUMMARY

City of Winnipeg Water and Waste Department (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment of W.D. Hurst Pumping Station e located at 60 Hurst Way Winnipeg, Manitoba. The reassessment was performed on June 12, 2023.

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM), and develop corrective action plans as required for the purposes of long-term management. The results of this assessment are not intended for construction, renovation, demolition or project tendering purposes.

SUMMARY OF FINDINGS

Asbestos-containing materials (ACM) are present as follows:

- Mag Block present on exhaust ducting within Pump Floor Location No.10 is presumed to contain asbestos. Mag Block is jacketed with metal and is in GOOD condition.
- Asbestos-containing transite boards present as wall finish in the Landing/Loading Area (Location No. 5), and Pump Room (Location No. 10) are non-friable and are in GOOD condition.
- Asbestos-containing caulking present as a sealant on exterior walls is non-friable and is in GOOD condition.
- Loose fill vermiculite is suspect to be present within hollow core wall cavities of Location No.'s 17 and 18. Debris was not present.
- Setting compound/adhesive on the back of ceramic tile wall finish within Location No.10 was confirmed to contain asbestos, is non-friable and is in good condition.
- Setting compound on the back of ceramic tiles throughout the remainder of the building is presumed to contain asbestos. It is potentially friable and is in GOOD condition.

SUMMARY OF RECOMMENDATIONS

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations.

1. Perform a re-assessment of asbestos materials on an annual basis.
2. Prior to renovations or demolition, perform a pre-construction assessment to identify any hazardous materials that may be disturbed by the work.
3. Follow appropriate safe work procedures when handling or disturbing asbestos.

This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.



TABLE OF CONTENTS

| | | |
|-----|--|---|
| 1.0 | INTRODUCTION AND SCOPE | 1 |
| 1.1 | Scope of Assessment | 1 |
| 2.0 | METHODOLOGY | 1 |
| 3.0 | BACKGROUND INFORMATION | 2 |
| 3.1 | Building Description | 2 |
| 3.2 | Existing Reports and Summary of Asbestos Abatement | 2 |
| 4.0 | FINDINGS | 2 |
| 4.1 | Mechanical Equipment Insulation | 2 |
| 4.2 | Vermiculite | 3 |
| 4.3 | Asbestos Cement Products (Transite) | 3 |
| 4.4 | Sealants, Caulking, and Putty | 3 |
| 4.5 | Roofing Products | 3 |
| 4.6 | Other Building Materials | 3 |
| 4.7 | Excluded Asbestos Materials | 4 |
| 5.0 | RECOMMENDATIONS | 4 |
| 5.1 | General | 4 |
| 5.2 | On-going Management and Maintenance | 5 |
| 6.0 | TERMS AND LIMITATIONS | 5 |
| 7.0 | REFERENCES | 5 |

APPENDICES

| | |
|--------------|---|
| APPENDIX I | Methodology |
| APPENDIX II | Additional Photographs |
| APPENDIX III | Location Summary Report |
| APPENDIX IV | Asbestos Material Summary Report / Sample Log |
| APPENDIX V | HMIS Data Report |



1.0 INTRODUCTION AND SCOPE

City of Winnipeg Water and Waste Department (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials reassessment of W.D Hurst Pumping Station located at 60 Hurst Way Winnipeg, Manitoba.

Pinchin performed the reassessment on June 12, 2023. The surveyor was accompanied by City of Winnipeg Water and Waste Representatives during the reassessment. The assessed area was occupied at the time of the assessment.

The objectives of the reassessment were to document the locations, quantities and conditions of previously identified asbestos containing building materials and develop corrective action plans as required. This reassessment is only to be used for the purposes of long-term management and routine maintenance. The results of this reassessment are not to be used for construction, renovation, demolition or project tendering purposes.

1.1 Scope of Assessment

The objective of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM), and develop corrective action plans as required.

Additional objectives included the following:

- Documentation of any asbestos abatement that was performed since the last reassessment.
- Additional sampling to delineate previously identified ACM.

Please refer to Appendix II for a detailed description of the methodology used for this assessment.

2.0 METHODOLOGY

Pinchin conducted an inspection of previously identified asbestos-containing materials (ACM) to evaluate the current condition of all accessible materials identified in the most recent assessment. The surveyor made reference to any existing assessment or abatement reports (as provided by the Client).

As per the original scope of work, concealed locations such as ceiling spaces above solid ceilings, shafts and chases were accessed via existing access panels. Our investigation did not include demolition of drywall or plaster walls to view concealed conditions. Structural items or exterior building finishes were not removed to determine the presence of concealed materials.

For further details on the methodology including test methods, refer to Appendix I.



3.0 BACKGROUND INFORMATION

3.1 Building Description

| Description Item | Details |
|-------------------|---|
| Use | Pumping Station |
| Number of Floors | The building is 1 storey plus 2 levels below grade. |
| Structure | Structure steel and concrete |
| Exterior Cladding | Masonry |
| Roof | Built Up Roofing |
| Flooring | Concrete, ceramic tile |
| Interior Walls | Transite cement, masonry, concrete, Drywall |
| Ceilings | Acoustic ceiling tiles, transite cement, drywall |

3.2 Existing Reports and Summary of Asbestos Abatement

3.2.1 Review of Previous Reports

The reassessment was based on information gathered from previous comprehensive assessment reports completed by Pinchin. The original assessment report was completed in 2007. The results of the original report and subsequent survey update reports were reviewed prior to completing the reassessment.

3.2.2 Summary of Asbestos Abatement since the Previous Assessment

Based on a review of the last re-assessment report and observations made during the reassessment, asbestos abatement has not been conducted since the last assessment.

4.0 FINDINGS

The following section summarizes the findings of the reassessment and provides a general description of the asbestos-containing materials (ACM) identified and their locations.

For details on approximate quantities, condition, friability and locations of asbestos materials; refer to the Asbestos Material Summary Report and All Data Report in Appendix IV and V.

4.1 Mechanical Equipment Insulation

One sample of Mag Block present on mechanical exhaust (30 LF) within Pump Floor Location No.10 was previously sampled and determined to be non-asbestos. Two additional samples are required to rule out the presence of asbestos. In the absence of additional sampling the Mag Block is presumed to contain asbestos. Mag Block is jacketed with metal and is in GOOD condition.



4.2 Vermiculite

As reported by client walls have been previously assessed and do not contain vermiculite within the Main Building, Northwest Building, and Drain Pump Building Location No.'s 1-16 and 19.

Loose fill vermiculite debris was not observed within the North Reservoir Building or B Pit Building (Location No.'s 17 and 18) however; demolition of masonry block walls has not been performed and vermiculite may be present within these cavities. Loose fill vermiculite was not observed within the cavities.

4.3 Asbestos Cement Products (Transite)

Asbestos-containing transite cement wall finish is present within Location No's 5 and 10. Approximately 166 SF of transite cement is present. Transite cement is non-friable and is in GOOD condition.

4.4 Sealants, Caulking, and Putty

Asbestos-containing grey caulking is present on exterior wall finish of the Main Building (Location No. 19). Caulking is a non-friable material which is in GOOD condition.

4.5 Roofing Products

Built up roofing materials on Location 19. Hurst Pumping Station were replaced during the 2021 renovation therefore are not suspect to contain asbestos.

Built up roofing materials present on the North Reservoir Building Location No.17 have not been sampled therefore are suspect to contain asbestos.

4.6 Other Building Materials

Setting compound on the back of ceramic tile floor finish within Location No.10 were determined to be non-asbestos by analysis of Samples 0015A-C.

Setting compounds on ceramic tile wall finish within Location No,10 were confirmed to contain asbestos in an adhesive finish. The adhesive is non-friable and is concealed behind the tiles.

Setting compound on the back of ceramic tiles throughout the remainder of the building is presumed to contain asbestos. It is potentially friable and is in GOOD condition.

4.7 Excluded Asbestos Materials

The following is a list of materials which may contain asbestos and was excluded from the assessment. These materials are presumed to contain asbestos until otherwise proven by sampling and analysis:

- Roofing felts and tar, mastics
- Floor levelling compound
- Elevator and lift brakes
- Electrical components
- Moulded plastic components (laboratory bench tops)
- Refractory materials and insulations in boilers and stacks
- Insulation under metal clad boilers
- Mechanical packing, ropes and gaskets
- Vermiculite
- Adhesives and duct mastics
- Caulking and putties
- Fibre-reinforced paints and coatings
- Paper products
- Soffit and fascia boards
- Fire resistant doors
- Metal clad finishes (Galbestos)
- Stucco, plaster or other cementitious parge coatings
- Vibration dampers on HVAC equipment
- Terrazzo
- Ropes and gaskets in cast-iron bell and spigot joints
- Sealants on pipe threads

5.0 RECOMMENDATIONS

5.1 General

Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include; destructive testing (e.g. coring and/or removal of building finishes and components), sampling of other hazardous materials (lead, mercury, PCBs, mould, etc.), and materials not tested in this study (e.g. roofing materials, caulking, mastics).



5.2 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the asbestos materials identified.

Perform a re-assessment of asbestos materials on an annual basis.

Remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.

Update the asbestos inventory report for the building upon completion of any abatement of ACM.

6.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

7.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

Manitoba

1. Workplace Safety and Health Act W210.
2. Workplace Safety and Health Hazard Regulation (Manitoba Regulation 217/2006), under the Workplace Safety and Health Act.
3. Manitoba Regulation MR 474/88, Manitoba PCB Regulation made under The Dangerous Goods Act.
4. Guide for Asbestos Management – Safe Work Manitoba.
5. Guideline Managing Demolition Debris Containing Hazardous Materials – Environmental Enforcement and Compliance Branch – Manitoba Conservation and Climate



2023 Asbestos Reassessment

W.D. Hurst Pumping Station e, 60 Hurst Way Winnipeg, Manitoba
City of Winnipeg Water and Waste Department

August 16, 2023
Pinchin File: 327243.000

Federal

1. Canada Occupational Health and Safety Regulation, SOR/86-304.
2. Consolidated Transportation of Dangerous Goods Regulations, including Amendment SOR/2019-101, Transportation of Dangerous Goods Act.

\\pinchin.com\lwp\Job\327000s\0327243.000 CITYOFWINNIPE,PropertyMB,2023,ASB,CONS\Deliverables\Hurst\327243 Asbestos Reassessment Report, WD Hurst Pumping Station, COWWW, Aug 16 2023.docx

Template: Master Report for Asbestos Reassessment, HAZ, March 2, 2023

APPENDIX I
Methodology



1.0 GENERAL

Pinchin conducted an inspection of previously identified asbestos-containing materials (ACM) to evaluate the current condition of all accessible ACM identified in the most recent assessment.

The surveyor made reference to any existing assessment or abatement reports (as provided by the Client).

Materials listed as exclusions in the previous reports have remained as exclusions. Sampling, assessment or verification of excluded materials was not conducted.

Existing sampling data, where available, was reviewed and relied upon.

Where sampling was conducted, sample collection was conducted in accordance with our Standard Operating Procedures.

A separate set of samples was collected of each type of homogenous material suspected to contain asbestos. A homogenous material is defined by the US EPA as material that is uniform in texture and appearance, was installed at one time, and is unlikely to consist of more than one type or formulation of material. The homogeneous materials were determined by visual examination and available information on the phases of construction and prior renovations.

Samples were collected at a rate that is in compliance with the requirements of local regulations and guidelines. The sampling strategy was also based on known ban dates and phase out dates of the use of asbestos; sampling of certain building materials is not conducted after specific construction dates. In addition, to be conservative, several years past these dates are added to account for some uncertainty in the exact start / finish date of construction and associated usage of ACM. In some cases, manufactured products such as asbestos cement pipe were visually identified without sample confirmation.

The asbestos analysis was completed using a stop-positive approach. Only one result meeting the regulated criteria was required to determine that a material is asbestos-containing, but all samples must be analyzed to conclusively determine that a material is non-asbestos. The laboratory stopped analyzing samples from a homogeneous material once a result equal to or greater than the regulated criteria is detected in any of the samples of that material. All samples of a homogeneous material were analyzed if no asbestos is detected. In some cases, all samples were analyzed in the sample set regardless of result.

The analysis was performed in accordance with Test Method EPA/600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials, July 1993.

The following summarizes the criteria of asbestos definitions. If there is a conflict between federal and provincial criteria, the more stringent will apply.



| Jurisdiction | Friable | Non-Friable |
|---------------------|-------------------|--------------------|
| Manitoba | 0.1% ¹ | 1% |
| Federal | 1% | 1% |

Where building materials are described in the report as “non-asbestos” or “does not contain asbestos”, this means that either no asbestos was detected by the analytical method utilized in any of the multiple samples or, if detected, it is below the lower limit of an asbestos-containing material in the applicable regulation. Additionally, these terms are used for materials which historically are known to not include asbestos in their manufacturing.

Asbestos materials are evaluated in order to make recommendations regarding remedial work. The priority for remedial action is based on several factors:

- Friability (friable or non-friable).
- Condition (good, fair, poor, debris).
- Accessibility (ranking from accessible to all building users to inaccessible).
- Visibility (whether the material is obscured by other building components).
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition).

For a complete description of the Evaluation Criteria and Basis of Recommendations, refer to Annex A.

Template: Methodology for Asbestos Reassessment, HAZ, July 27, 2021

METHODOLOGY ANNEX A EVALUATION CRITERIA

1.0 EVALUATION CRITERIA AND BASIS OF RECOMMENDATIONS

The detailed asbestos assessment provides information regarding the location, condition, accessibility and friability of the asbestos-containing materials (ACM). In order to make recommendations for compliance with current regulations, Pinchin developed the following criteria.

2.0 EVALUATION OF CONDITION

2.1 Friable Sprayed or Trowelled Fireproofing, Thermal Insulation and Texture Finishes (Surfacing Materials)

To evaluate the condition of ACM sprayed or trowelled on fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes, the following criteria are applied:

| | |
|-------------|---|
| Good | Surface of material shows no significant signs of damage, deterioration or delamination. Good condition includes unencapsulated or unpainted fireproofing or texture finishes, where no or limited delamination or damage is observed, or encapsulated fireproofing or texture finishes where the encapsulant or paint has been applied after the damage or fallout occurred. |
| Poor | A sprayed material that shows signs of significant damage or is significantly delaminating or deteriorating. This may be limited to surface delamination or some portion of the substrate may be exposed. |

In Locations where damage exists in isolated areas, both good and poor condition may be applicable. The extent of each condition will be recorded. Fair condition is not utilized in the evaluation of ACM sprayed or trowelled fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes.

The evaluation of the above products above ceilings may be limited by the number of observations and by building components such as ducts or full height walls that obstruct the above ceiling observations.

2.2 Friable Mechanical or Thermal System Insulation (TSI)

To evaluate the condition of mechanical insulation on vessels, boilers, breeching, ducts, pipes, fan units, equipment etc. the following criteria are applied:

| | |
|-------------|---|
| Good | Insulation is completely covered in jacketing and exhibits no evidence of damage or deterioration. No insulation is exposed. Includes conditions where the jacketing has minor damage (i.e. scuffs or stains), but the jacketing is not penetrated. |
| Fair | Minor penetrating damage to jacketed insulation (cuts, tears, nicks, deterioration or delamination) or undamaged insulation that has never been jacketed. Insulation is exposed but not showing surface disintegration. The extent of missing insulation ranges from minor to none. Damage can be repaired. |

| | |
|-------------|---|
| Poor | Original insulation jacket is missing, damaged, deteriorated or delaminated. Insulation is exposed and significant areas have been dislodged. Damage cannot be readily repaired. Includes components where insulation may have been removed incompletely. |
|-------------|---|

The evaluation of mechanical insulation may be limited by the number of observations made and building components such as ducts or full height walls that obstruct observations. It is often not possible to observe each foot of mechanical insulation from all angles.

2.3 Potentially Friable Materials and Miscellaneous Friable Materials

Potentially friable ACM are products that are basically non-friable while in place but have the potential to generate friable dust upon removal or if significantly disturbed without appropriate procedures. These products may become friable if damaged. Potentially friable materials include materials such as acoustic ceiling tiles and plaster. To evaluate the condition of potentially friable materials, the following criteria are applied:

| | |
|-------------|--|
| Good | No significant damage or deterioration. Still serving its intended use as a building material or finish. |
| Fair | Showing signs of some cracking or breakage, but is not deteriorating (e.g. cracked plaster, broken but in place ceiling tile, missing tile or section of plaster etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes. |
| Poor | Significant deterioration or breaking apart of the material. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material has deteriorated to a point it has become friable. Normally potentially friable ACM in Poor condition is not repairable and requires at least localized removal and replacement. |

2.4 Non-Friable Materials

Non-friable ACM cover a wide range of products with a wide variation in their tendency to release dust or asbestos fibres to the air. Many of these materials, (particularly where the matrix is an unweathered bitumen, asphalt or tar material) do not release fibres except in very unusual circumstances or during significant disturbance (e.g. use of abrasive power tools). Others with a cementitious matrix (asbestos-cement products) can more readily release dust due to abrasion, demolition, weathering, etc. The potential for asbestos release from non-friable ACM is always lower than from friable ACM. To evaluate the condition of non-friable Materials, the following criteria are applied:

| | |
|-------------|--|
| Good | No significant damage or deterioration. Still serving its intended use as a building material or finish. |
|-------------|--|

| | |
|-------------|---|
| Fair | Showing signs of some cracking or breakage but is not deteriorating (e.g. cracked vinyl floor tile, missing piece of tile or transite, etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes. |
| Poor | Significant deterioration or breaking apart of the material to the point at which it cannot be repaired, and it will require at least local removal. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material may have deteriorated to a point where traffic or disturbance may cause it to become friable. |

2.5 Evaluation of ACM Debris

The identification of the exact location or presence of debris on the top of ceiling tiles is limited by the number of observations made and the presence of building components such as ducts or full height walls that obstruct observations.

The presence of fallen or dislodged ACM is noted separately from the ACM source and is referred to as Debris. Debris may be friable if from a friable ACM source or a badly deteriorated non-friable ACM source. Debris may also be non-friable (such as fallen pieces of transite sheet or mastic fittings, or broken, dislodged floor tiles).

| | |
|---------------|--|
| Debris | Debris may be friable or non-friable but is always identified as debris. |
|---------------|--|

2.6 Evaluation of Presumed Asbestos-Containing Material (PACM)

Presumed asbestos-containing materials (PACM), are building materials that may contain asbestos but were not sampled or analyzed due to inaccessibility or the need to perform destructive testing to obtain a reasonable sample set. Evaluation of these materials is based on the assumption that these PACM are asbestos-containing.

A list of PACM is provided in the report and they are generally not included in the detailed room by room reports. Typically, they are excluded because they are inaccessible or present in very small quantities. If PACM are evaluated, Pinchin uses the criteria that correspond with the type (and friability) of the material listed above.

3.0 EVALUATION OF ACCESSIBILITY

The accessibility of building materials known or suspected of being ACM is rated according to the following criteria:

| | |
|-----------------------------------|--|
| Access (A) | Common areas of the building within reach of all building users (approximately 8' - 9' from floor or standard ceiling height). Includes other areas where occupant activities may result in disturbance of material that is not normally within reach from floor level, but may be disturbed by common activities (e.g. gymnasiums, workshops) |
| Access (B) | Areas of the building accessed primarily by Maintenance/Caretaking/Janitorial Staff and within reach without use of a ladder. Includes areas within reach in Boiler Rooms, Electrical Rooms, Janitors Closets, Elevator Rooms, Mechanical Rooms, etc. Includes materials within reach from fixed ladders or catwalks, mezzanines, and accessible pipe chases. |
| Access (C) and Visible | Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Only includes ACM that are visible to view without the removal or opening of other building components such as ceiling tiles or service access panels. Visible column on HMIS sheets will say YES. |
| Access (C) and not Visible | Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Includes ACM that are not visible to view and require the removal of a building component to see, such as ceilings tiles or access panels to view and access. Includes rarely entered crawl spaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. Visible column on HMIS sheets will say NO. |
| Access (D) | Areas of the building behind inaccessible solid ceiling systems, walls or equipment etc. where demolition of the ceiling, wall or equipment etc. is required to reach the ACM. Material inaccessible due to height or location or is only accessed under unusual situations. Evaluation of condition and extent of ACM is limited or impossible, depending on the surveyor's ability to visually examine materials in Access D. |

4.0 ACTION MATRIX AND DEFINITIONS

Pinchin's evaluation of the viability of a specific asbestos control option is based on the consideration of the friability, condition, accessibility and visibility of a material. The logic used is that damaged ACM located in an area frequently accessed by all building occupants is of a higher priority than damaged ACM located in an infrequently accessed service area. The action matrix considers the potential for fibre release (primarily from friable ACM) and the possible concerns from regulatory bodies and many building occupants to all damaged ACM (including non-friable).

In any building with asbestos, many current regulations require an Asbestos Management Program be implemented. Depending on the condition and the accessibility, more active measures such as repair or removal may be recommended. The following matrix provides guidance for recommended Actions in the absence of renovation or demolition. In the event of construction or maintenance activity which will disturb ACM more aggressive control or removal will be required.

4.1 Action Matrix

The following tables outline the action decisions based on the relationship of assessed factors. Table I applies to friable ACM. Table II applies to non-friable ACM.

Table I Decision Matrix for Friable ACM

| Access | Condition | | | Debris |
|-----------------|-----------------------|-----------------------|----------|----------|
| | Good | Fair | Poor | |
| (A) | Action 5 ¹ | Action 5 ² | Action 3 | Action 1 |
| (B) | Action 7 | Action 6 ³ | Action 3 | Action 1 |
| (C) Visible | Action 7 | Action 6 | Action 3 | Action 2 |
| (C) Not Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (D) | Action 7 | Action 7 | Action 7 | Action 7 |

Table II Decision Matrix for Potentially Friable and Non-Friable ACM

| Access | Condition | | | Debris |
|-----------------|-----------|-----------------------|----------|----------|
| | Good | Fair | Poor | |
| (A) | Action 7 | Action 7 ⁴ | Action 3 | Action 1 |
| (B) | Action 7 | Action 7 | Action 3 | Action 1 |
| (C) Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (C) Not Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (D) | Action 7 | Action 7 | Action 7 | Action 7 |

4.2 Action Definitions

The following are the definitions in the Action Matrix Table presented above:

| Action Definitions | |
|--------------------|--|
| Action 1 | Clean-Up of ACM Debris Restrict access that is likely to cause a disturbance of the ACM Debris and clean up ACM Debris. Utilize appropriate asbestos precautions. |

¹ If friable ACM in access (A)/Good condition is not proactively removed Action 7 (Manage) is recommended.

² If friable ACM in access (A)/Fair condition is not proactively removed repair is recommended.

³ If friable ACM in access (B)/Fair condition is likely to be disturbed after repair proactive removal is recommended.

⁴ Action 7 is recommended for all non-friable ACM in Fair condition however some clients may wish to repair or take some action primarily for cosmetic reasons

Action Definitions

| | |
|-----------------|--|
| Action 2 | <p>Precautions for Access Which may Disturb ACM Debris</p> <p>Use appropriate means to isolate the debris or to limit entry to the area which may disturb the material. At locations where ACM Debris can remain in place in lieu of removal or clean-up (e.g. Debris on top of ceiling tiles or behind lockable door), Utilize appropriate asbestos precautions to enter the area if this will disturb debris. The precautions will be required until the ACM Debris has been cleaned up.</p> |
| Action 3 | <p>ACM Removal</p> <p>Remove ACM. Utilize asbestos procedures appropriate to the scope of the removal work. Until it is removed, restrict access to the material so it is not disturbed.</p> |
| Action 4 | <p>Precautions for Work Which may Disturb ACM in Poor Condition. Utilize appropriate asbestos precautions if ACM may be disturbed by work on or near ACM. This does not require restricting access to the area, only control of work which may contact or disturb the ACM. Removal is the only viable option if work will disturb ACM.</p> |
| Action 5 | <p>Proactive ACM Removal</p> <p>Remove friable ACM where the presence of friable asbestos in Good condition is not desirable. If friable ACM in Fair condition is not removed, then Repair friable ACM.</p> |
| Action 6 | <p>ACM Repair</p> <p>Repair friable ACM in Fair condition which is not likely to be damaged again or disturbed by normal use of the area or room. Pinchin recommends proactive removal if friable ACM is likely to be damaged or disturbed during normal use of the area or room</p> |
| Action 7 | <p>Asbestos Management Program with Routine Surveillance Implement an Asbestos Management Program, including routine surveillance of ACM. Reassess materials regularly (typically once per year).</p> |

Master Template: Methodology Annex A to Appendix I Evaluation Criteria, HAZ, January 10, 2020

APPENDIX II
Additional Photographs



S0003 (Confirmed Asbestos), Mechanical Equipment, Generator Exhaust, Magnesia block, Main Building - Pump Room (Location #: 10)



V0006 (Confirmed Asbestos), Wall, Cement Product, Main Building - Pump Room (Location #: 10)




V0006 (Confirmed Asbestos), Wall, Cement Product, Main Building - Landing/Loading Area (Location #: 5)



S0010 (Confirmed Asbestos), Wall, Window Liner, Caulking, Hurst Pump Station Main Building Exterior (Location #: 19)



V9500 (Presumed Asbestos), Floor, All, Mortar, Main Building - Vestibule (Location #: 1)
Setting compound



V9500 (Presumed Asbestos), Wall, Ceramic Tiles, Main Building - Pump Room (Location #: 10)



V9500 (Presumed Asbestos), Floor, All, Mortar, Main Building - Pump Room (Location #: 10)
Setting compound



V9500 (Presumed Asbestos), Wall, Vermiculite, B Pit Building (Location #: 18)



V9500 (Presumed Asbestos), Floor, All, Mortar, Main Building - Walkway (Location #: 4)

APPENDIX III
Location Summary Report

Client: Cowww

Site: , , MB

Building Name: W.D. Hurst Pumping Station

Survey Date:

Last Re-Assessment: 2023-06-19

Building Phases: A:

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|---|----------------------|-------------------------------|-------------|---|
| 1 | Main Building - Vestibule | 96 | Main-Main Building | A | Floor setting compound is presumed asbestos containing. KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was also sampled and determined to be non ACM. |
| 2 | Main Building - Office | 308 | Main-Main Building | A | KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was also sampled and determined to be non ACM. |
| 3 | Main Building - Electrical Room | 1080 | Main-Main Building | A | KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was also sampled and determined to be non ACM. |
| 4 | Main Building - Walkway | 1500 | Main-Main Building | A | Setting compound on ceramic tiles is presumed to contain asbestos KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was also sampled and determined to be non ACM. |
| 5 | Main Building - Landing/Loading Area | 750 | Main-Main Building | A | KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM. |
| 6 | Main Building - Walkway | 120 | Main-Main Building | A | KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM. |
| 7 | Main Building - Stairwell | 375 | Main-Main Building | A | |
| 8 | Main Building - Chlorine Room | 400 | Main-Main Building | A | KGS group determined there was no vermiculite inside hollow core block walls as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non acm. |
| 9 | Main Building - Chlorine Tonner Room | 2200 | Main-Main Building | A | KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM. |
| 10 | Main Building - Pump Room | 7700 | Basement-Main Building | A | Magnesia Block on generator exhaust duct is presumed asbestos containing KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was also sampled and determined to be non ACM. |
| 11 | Main Building - Custodian Closet | 32 | Basement-Main Building | A | Ceramic tile setting compound is presumed asbestos containing. KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM. |
| 12 | Main Building - Washroom | 32 | Basement-Main Building | A | KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM. |
| 13 | Main Building - Crawlspace | 2200 | Basement-Main Building | A | |
| 14 | Main Building - Sub Basement | 7700 | Sub Basement-Main Building | A | |
| 15 | Northwest Building - Northwest Building | 300 | Main-Northwest Building | A | KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM. Roof sections needs to be tested prior to any renovation or demolition activities. |
| 16 | Drain Pump Building | 225 | Main-Drain Pump Building | A | KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM Roof sections needs to be tested prior to any renovation or demolition activities. |
| 17 | North Reservoir Building | 300 | Main-North Reservoir Building | A | Roof sections needs to be tested prior to any renovation or demolition activities. Vermiculite suspect to be present. |
| 18 | B Pit Building | 150 | Main-B Pit Building | A | Masonry walls suspect to contain asbestos containing vermiculite insulation Roof sections needs to be tested prior to any renovation or demolition activities. |
| 19 | Hurst Pump Station Main Building Exterior | 0 | NA | A | KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar and roofing materials were replaced in 2021. |

APPENDIX IV

Asbestos Material Summary Report / Sample Log

Client: City of Winnipeg Water and Waste Dept

Site: , , MB

Building Name: W.D. Hurst Pumping Station

Survey Date: 2006-05-03

| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
|----------|-----------|---|-----------|-------------|----|-----|----|-----|---------------|----------|------------|
| Asbestos | S0001 | Ceiling Ceiling Tiles (lay-in) Acoustic Tile/at-1/24x48/location 2 | 1,2 | A | 0 | 404 | 0 | 0 | None Detected | No | |
| Asbestos | S0002 | Other Ceiling Tiles (glue-on) Glue On Tile/12 X 12/location 10 | 10 | A | 0 | 70 | 0 | 0 | None Detected | No | |
| Asbestos | S0003 | Mechanical Equipment, Duct Generator Exhaust Magnesia Block Magblock/gene/location 10 | 5,10 | A | 70 | 0 | 0 | 0 | None Detected | No | |
| Asbestos | V0006 | Wall Cement Product Transite Ceiling Panel - Pump Area | 5,10 | A | 0 | 166 | 0 | 0 | Chrysotile | Yes | NF |
| Asbestos | S0007 | Wall Adhesive/mastic Black Adhesive On Cork, Loc. 4, Walkway, Main Flr. Main Bldg. (black, Non Fibrous, Heterogenous) | 4 | A | 0 | 0 | 0 | 0 | None Detected | No | |
| Asbestos | V0008 | Wall Adhesive/mastic Black Adhesive On Cork, Loc. 5, Landing/loading Area, Main Flr. Main Bldg. (black, Non Fibrous, Heterogenous) | 5 | A | 0 | 0 | 0 | 0 | None Detected | No | |
| Asbestos | S0010 | Wall Window Liner Caulking Caulking, Exterior Wall, Hurst Pumping Station (sample No. 0027 - August 27, 2015 - 1517151_plm) (for Sample 0010b-c It Was Sample No. 0027b-c- June 30, 2016 - B131169) | 19 | A | 0 | 0 | 0 | 100 | Chrysotile | Yes | NF |
| Asbestos | S0011 | Wall Exterior Plaster Plaster With Wire Mesh, Exterior Wall Foundation, Hurst Pumping Station (sample No. 0028 - August 27, 2015 - 1517151_plm) (for Sample 0011b-c It Was Sample No. 0028b-c- June 30, 2016 - B131169) | 19 | A | 0 | 100 | 0 | 0 | None Detected | No | |
| Asbestos | S0012 | Wall Exterior Plaster Plaster On Concrete, Exterior Wall Foundation, Hurst Pumping Station (sample No. 0029 - August 27, 2015 - 1517151_plm) (for Sample 0012b-c It Was Sample No. 0029b-c- June 30, 2016 - B131169) | 19 | A | 0 | 24 | 0 | 0 | None Detected | No | |
| Asbestos | S0013 | Wall Description Pending Plaster Cemented Small Stones, Exterior Wall, Hurst Pumping Station (sample No. 0030 - August 27, 2015 - 1517151_plm) (for Sample 0013b-c It Was Sample No. 0030b-c- June 30, 2016 - B131169) | 19 | A | 0 | 244 | 0 | 0 | None Detected | No | |
| Asbestos | S0014 | Other All Plaster Grout From Floor Tiles, Location 5, Landing Loading Area, Main Bldg., W.d. Hurst Pumping Station B215313 Aug 2019 | 5 | A | 0 | 0 | 0 | 100 | None Detected | No | |

| HAZMAT | Sample No | System/Component/Material/Sample Description | Locations | Bldg. Phase | LF | SF | EA | % | Type | Positive | Friability |
|----------|-----------|--|-------------|-------------|----|------|----|-----|-------------------|----------|------------|
| Asbestos | S0015 ABC | Floor All Adhesive/mastic | 10 | A | 0 | 1000 | 0 | 100 | None Detected | No | |
| Asbestos | S0016 ABC | Wall Adhesive/mastic South Wall | 10 | A | 0 | 1000 | 0 | 100 | Chrysotile | Yes | NF |
| Asbestos | V9500 | Floor All Mortar | 1,4,6,11,12 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | NF |
| Asbestos | V9500 | Wall Vermiculite | 17,18 | A | 0 | 0 | 0 | 100 | Presumed Asbestos | Yes | F |
| Asbestos | V0000 | Floor Metal | 10 | A | 0 | 0 | 0 | 0 | Non Asbestos | No | |
| Asbestos | V0000 | Floor Vinyl Sheet Flooring | 2 | A | 0 | 308 | 0 | 0 | Non Asbestos | No | |
| Asbestos | V0000 | Mechanical Equipment Heating Water Tank Fibreglass | 10 | A | 0 | 0 | 0 | 100 | Non Asbestos | No | |

Legend:

| Sample number | | Units | | |
|---------------|--|-------|-------------|---------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | NF Non Friable material. |
| L#### | Paint sample collected | LF | Linear feet | F Friable material |
| P#### | PCB sample collected | EA | Each | PF Potentially Friable material |
| M#### | Mould sample collected | % | Percentage | |
| V#### | Material visually similar to numbered sample collected | | | |
| V0000 | Known non Hazardous Material | | | |
| V9000 | Material is visually identified as Hazardous Material | | | |
| V9500 | Material is presumed to be Hazardous Material | | | |
| [Loc. No.] | Abated Material | | | |

APPENDIX V
HMIS Data Report

Client: City of Winnipeg Water and Waste Dept
Location: #1 : Main Building - Vestibule
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 96

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------|---------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | N/A | Surface | N/A | C | Y | | 96 | | | SF | V0001 | None Detected | N.D. | None | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Floor ¹ | All | Mortar | Surface | Ceramic Tiles | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Mechanical Equipment | Not Found | N/A | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | 800 | | | | | | | | |
| Structure | Steel Truss | Metal | No Information | NI | | | | 800 | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |

Floor setting compound is presumed asbestos containing. KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was also sampled and determined to be non ACM.

1 - Setting compound

Client: City of Winnipeg Water and Waste Dept
Location: #2 : Main Building - Office
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 308

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------|------------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Ceiling Tiles (lay-in) | Surface | N/A | C | Y | | 308 | | | SF | S0001 | None Detected | N.D. | None | |
| Duct | Return Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Vinyl Sheet Flooring | Surface | N/A | A | Y | | 308 | | | SF | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Steel Truss | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |

KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was also sampled and determined to be non ACM.

Client: City of Winnipeg Water and Waste Dept
Location: #3 : Main Building - Electrical Room
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 1080

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Air Handling Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Other | Electrical Panel | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Steel Truss | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |

KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was also sampled and determined to be non ACM.

Client: City of Winnipeg Water and Waste Dept
Location: #4 : Main Building - Walkway
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 1500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|-----------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | | | | C | Y | | | | | | | | | | |
| Duct | Exhaust | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | All | Mortar | Surface | Ceramic Tiles | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Electrical Panel | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Piping | Rain Water Leader | Fibreglass | Straight | N/A | C | Y | | | | | | | | | | |
| Piping | Rain Water Leader | Fibreglass | Fitting | N/A | C | Y | | | | | | | | | | |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | Surface | Cork | B | Y | | | | | | | | | | |
| Wall | | Adhesive/mastic | Surface | Cork | B | N | | | | | | S0007 | [None] | | [None] | |

Setting compound on ceramic tiles is presumed to contain asbestos KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was also sampled and determined to be non ACM.

Client: City of Winnipeg Water and Waste Dept
Location: #5 : Main Building - Landing/Loading Area
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 750

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-------------------|-------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | | | | C | Y | | | | | SF | | | | | |
| Duct | Generator Exhaust | Mortar | No Information | NI | C | Y | | 40 | | | LF | V0003 | None Detected | N.D. | None | |
| Duct | Generator Exhaust | Mortar | No Information | NI | C | Y | | | | | LF | V0003 | None Detected | N.D. | None | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | All | Plaster | Surface | Ceramic Tiles | A | Y | | 100 | | | % | S0014 | None Detected | N.D. | None | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | Surface | Cork | B | Y | | | | | | | | | | |
| Wall | | Cement Product | Surface | | C | Y | | 150 | | | SF | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | NF |
| Wall | | Adhesive/mastic | Surface | Cork | B | N | | | | | | V0008 | [None] | | [None] | |

KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM.

Client: City of Winnipeg Water and Waste Dept
Location: #6 : Main Building - Walkway
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 120

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|---------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | | Surface | | C | Y | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Floor | All | Mortar | Surface | Ceramic Tiles | A | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | Surface | Cork | B | Y | | | | | | | | | | |

KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM.

Client: City of Winnipeg Water and Waste Dept
Location: #7 : Main Building - Stairwell
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 375

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | | Metal | No Information | NI | | | | | | | | | | | | |

Client: City of Winnipeg Water and Waste Dept
Location: #8 : Main Building - Chlorine Room
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |

KGS group determined there was no vermiculite inside hollow core block walls as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non acm.

Client: City of Winnipeg Water and Waste Dept
Location: #9 : Main Building - Chlorine Tonner Room
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Area (sqft): 2200
Last Re-Assessment: 2023-06-19

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |

KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM.

Client: City of Winnipeg Water and Waste Dept
Location: #10 : Main Building - Pump Room
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Basement-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Area (sqft): 7700
Last Re-Assessment: 2023-06-19

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|--------------------|-------------------|----------------|---------------|----|----|-----|------|------|------|------|----------|---------------|--------|------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | | | | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Floor | | Metal | No Information | NI | | | | | | | | 00000 | Non-Asbestos | | None | |
| Floor ¹ | All | Adhesive/mastic | Surface | Ceramic Tiles | A | Y | | 1200 | | | SF | S0015ABC | None Detected | N.D. | None | |
| Mechanical Equipment | Generator Exhaust | Magnesia block | System | | C | Y | | 30 | | | LF | S0003 | [Asbestos] | N.D. | [Asbestos] | F |
| Mechanical Equipment | Generator Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Generator Unit | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Heating Water Tank | Fibreglass | Surface | Foil Face | B | Y | | 100 | | | % | V0000 | Non-Asbestos | | None | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-----------------------------|----------------|---------------|----|----|-----|------|------|------|------|----------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Other | | Ceiling tiles (glue-on) | Surface | N/A | B | Y | | 70 | | | SF | S0002 | None Detected | N.D. | None | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Metal | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | Surface | Cork | B | Y | | | | | | | | | | |
| Wall | | Cement Product | Surface | | B | Y | | 16 | | | SF | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | NF |
| Wall ² | | Adhesive/mastic, South wall | Surface | Ceramic Tiles | A | Y | | 400 | | | % | S0016ABC | Chrysotile | 1-5% | Confirmed Asbestos | NF |

Magnesia Block on generator exhaust duct is presumed asbestos containing KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was also sampled and determined to be non ACM.

- 1 - Setting compound - 6"brown tiles
- 2 - 6" tan tiles

Client: City of Winnipeg Water and Waste Dept
Location: #11 : Main Building - Custodian Closet
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Basement-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 32

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | | | | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Floor ¹ | All | Mortar | Surface | Ceramic Tiles | A | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (poured) | Surface | Cork | C | Y | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |

Ceramic tile setting compound is presumed asbestos containing. KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM.

1 - Setting compound

Client: City of Winnipeg Water and Waste Dept
Location: #12 : Main Building - Washroom
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Basement-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 32

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-------------------|----------------|---------------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | | | | | | | | | | | | | | | |
| Duct | Supply Air | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |
| Floor ¹ | All | Mortar | Surface | Ceramic Tiles | A | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (poured) | Surface | Cork | C | Y | | | | | | | | | | |
| Wall | | Ceramic Tiles | No Information | NI | | | | | | | | | | | | |

KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM.

1 - Setting compound

Client: City of Winnipeg Water and Waste Dept
Location: #13 : Main Building - Crawlspace
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Basement-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 2200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Dirt | No Information | NI | | | | | | | | | | | [None] | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Client: City of Winnipeg Water and Waste Dept
Location: #14 : Main Building - Sub Basement
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Sub Basement-Main Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 7700

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Beam, Deck | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Wall | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |

Client: City of Winnipeg Water and Waste Dept
Location: #15 : Northwest Building - Northwest Building
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Northwest Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|--------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | Surface | Wood | B | Y | | | | | | | | | | |

KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM. Roof sections needs to be tested prior to any renovation or demolition activities.

Client: City of Winnipeg Water and Waste Dept
Location: #16 : Drain Pump Building
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-Drain Pump Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 225

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------------|-------------------|----------------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Wood | No Information | NI | | | | | | | | | | | | |
| Duct | Fresh Air Intake | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Pump | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | N/a | NI | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | Surface | Wood | B | Y | | | | | | | | | | |

KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar was sampled and determined to be non ACM. Roof sections needs to be tested prior to any renovation or demolition activities.

Client: City of Winnipeg Water and Waste Dept
Location: #17 : North Reservoir Building
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-North Reservoir Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|------------------|--------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Electrical Panel | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | No Information | NI | | | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Roof sections needs to be tested prior to any renovation or demolition activities. Vermiculite suspect to be present.

Client: City of Winnipeg Water and Waste Dept
Location: #18 : B Pit Building
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: Main-B Pit Building

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 150

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------------------|-----------|--------------------|----------------|----------|----|----|-----|------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Duct | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Floor | | Concrete (poured) | No Information | NI | | | | | | | | | | | | |
| Mechanical Equipment | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Other | Not Found | NI | No Information | NI | | | | | | | | | | | | |
| Piping | | Not Insulated | No Information | NI | | | | | | | | | | | | |
| Structure | Deck | Concrete (precast) | No Information | NI | | | | | | | | | | | | |
| Wall | | Masonry | Surface | Wood | B | Y | | | | | | | | | | |
| Wall | | Vermiculite | Insulation | Masonry | B | N | | 100 | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Masonry walls suspect to contain asbestos containing vermiculite insulation Roof sections needs to be tested prior to any renovation or demolition activities.

Client: City of Winnipeg Water and Waste Dept
Location: #19 : Hurst Pump Station Main Building
Exterior
Survey Date: 2006-05-03

Site: W.D. Hurst Pumping Station
Floor: NA

Building Name: W.D. Hurst Pumping Station
Room #:
Last Re-Assessment: 2023-06-19

Area (sqft): 0

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|---------------------|----------|----------|----------|----|----|-----|------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | Exterior | Plaster | | N/A | A | Y | | 100 | | | SF | S0011 | None Detected | N.D. | None | |
| Wall | Exterior | Plaster | Base | N/A | A | Y | | 16 | | 8 | SF | S0012 | None Detected | N.D. | None | |
| Wall | Exterior | Masonry | | Plaster | B | N | | 100 | | | % | | | | | |
| Wall | Description Pending | Plaster | Exterior | N/A | A | Y | | 242 | | 2 | SF | S0013 | None Detected | N.D. | None | |
| Wall | Window Liner | Caulking | Exterior | | A | Y | | 100 | | | % | S0010 | Chrysotile | 0.1-1% | Confirmed Asbestos | NF |

KGS Group determined the walls do not contain vermiculite as per their report dated October 29, 2019. Brick mortar and roofing materials were replaced in 2021.

Legend:

| Sample number | | Units | | Other | |
|---------------|--|-------|-------------|-------|------------------------------|
| S#### | Asbestos sample collected | SF | Square feet | A | Access |
| V#### | Material visually similar to numbered sample collected | LF | Linear feet | V | Visible |
| V0000 | Known non-asbestos material | EA | Each | AP | Air Plenum |
| V9000 | Visually identified as an asbestos material | % | Percentage | F | Friable material |
| V9500 | Material is presumed to be an asbestos material | | | NF | Non Friable material |
| | | | | PF | Potentially Friable material |

| Access | |
|--------|---|
| A | Accessible to all building occupants |
| B | Accessible to maintenance and operations staff without a ladder |
| C | Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas |
| D | Not normally accessible |

| Condition | |
|-----------|---|
| Good | No visible damage or deterioration |
| Fair | Minor, repairable damage, cracking, delamination or deterioration |
| Poor | Irreparable damage or deterioration with exposed and missing material |

| Visible | |
|---------|---|
| Y | The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels). |
| N | The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. |

| Air Plenum | |
|------------|---|
| Yes or No | The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation. |

| Colour Coding | |
|--|---|
|  | The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code). |
|  | The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling. |