
UPS-1 INSTRUCTIONS

Startup Procedure

- 1. Turn MTS-1 (Manual Transfer Switch) to the *Line* position.
- 2. Ensure that breaker BKR-10 is closed and supplying power.
- 3. Close the disconnect switch, DS-UPS-1 to supply power to the UPS.
- 4. Turn on the UPS battery circuit breaker, located at the rear of the UPS.
- 5. Wait for the -⊙→ indicator to illuminate on the UPS.
- 6. Turn MTS-1 to the *UPS* position.
- 7. Verify that the -⊙→ indicator is off.

Shutdown Procedure

- 1. Turn MTS-1 (Manual Transfer Switch) from the UPS position to the Line position.
- 2. Press the \uparrow button on the front panel display and then press the \rightarrow button to select the *TURN UPS ON/OFF* menu.
- 3. Press the \downarrow button to select the *TURN UPS OFF* option; press the \leftarrow button.
- 4. Confirm the selection. Press and hold the ← button for three seconds, until the UPS stops beeping.
- 5. Turn off the UPS battery circuit breaker, located at the rear of the UPS.
- 6. Turn off the disconnect switch DS-UPS-1.



		B.M. ELE\	I.	FIELD BOOK #:			•))	SNC-LAVALIN INC. 148 Nature Park Way	ENGINEER'S SEAL	@	THE CITY OF	= \A/ININ	WIDEG
		POSTED TO LBIS						Winnipeg, MB, Canada R3P 0X7 204-786-8080	 PRELIMINARY	Winnipeg WATER AND WASTE DEPA			
							DESIGNED C. REIMER	CHECKED C. REIMER	NOT TO BE	TACHE BOOSTER PUMPING STATION			
	Z APEGIN	#\ 2=CD					DRAWN E. BOHNCKE	APPROVED C. REIMER	USED FOR CONSTRUCTION	UPS UPGRADES OPERATING INSTRUCTIONS UPS-1			
	Certificate of Authorization						HOR. SCALE NTS VERTICAL NTS	RELEASED FOR CONSTRUCTION					
	SNC-Lavalin Inc. (MB) No. 4489 Expiry: April 30, 2008	0	ISSUED FOR TENDER		2008/01/08	AEO	DATE 2007/10/11	DATE		CITY DRAWING NUMBER			REV. SIZ
		NO.	REVISIONS		DATE BY FILENAME: 1-0660M-E0004-001-00.dwg		04-001-00.dwg		<u> 1-0660N</u>	<u>И-Е0004</u>	001	0 A	

.: 2008/01/09 — 10:2/am |113063\4ENG\47ELE\DD — General DWG\1—0660M—E0004—001—00.