

ASBESTOS INVENTORY CONTROL

BUILDING SERVICES DIVISION

BUILDING NAME: Assiniboine West CC (Buchanan)	INSPECTION DATE: May 15, 2007
BUILDING CODE: CC-002	INSPECTED BY: Karl Bauch & Jayson Cyncora
BUILDING ADDRESS: 861 Buchanan Boulevard	Construction date:

LEGEND-	Application T Condition: Inspection Fr	PW-Pipe Wrap SO-Spray On HB-Hardboard EN-Encapsulated R-Removed PL-Plaster TI-Tank Insulation C-Ceiling F-Flooring D- Ducting G-Good NR-Need Repair ency: B-Per 6 Months Y-Yearly 2Y-Two Years 5Y-Five Years							
		Description	Application Type	Estimated %	General Condition	Inspection Frequency	Area Tested		
Asbestos Lo	cation						Yes	No	
Main Building									
West (old) End		12" x 12" Floor Tile may contain asbestos	F		G	2Y		No	
		Building visually inspected and does not appear to contain vermiculite insulation							
Skate Change	Building								
		Block walls randomly inspected and appear to be empty (do not contain vermiculite insulation)							

Note:

- · All vinyl floor tile installed before 1990 may contain asbestos and therefore must be treated as an asbestos containing material
- Vermiculite insulation may contain pockets of asbestos and therefore all vermiculite must be treated as an asbestos containing material
- There may be asbestos containing materials present that were not located during building inspections
- Any asbestos related concerns should be directed to Bruce Kazun 794-4409 (alternate Robert Haglund 986-6047)

Deleted: J:\CMS_Branch\Asbes tos Inventory (saved)\Community Centres\Assiniboine West CC (Morgan Site)CC-003.doc

V:\CMS_Branch\Asbestos Inventory (saved)\Community Centres\Assiniboine West CC (Buchanan Site) CC-002.docV:\CMS_Branch\Asbestos Inventory (saved)\CMS_Branch\Asbestos Inventory (saved)\CMS_Bra