

## ASBESTOS INVENTORY CONTROL

## **BUILDING SERVICES DIVISION**

BUILDING NAME: TRANSCONA CENTENNIAL POOL	INSPECTION DATE: April 1/2005
BUILDING CODE: PI-12	INSPECTED BY: Karl Bauch & Jayson Cyncora
BUILDING ADDRESS: 1101 WABASHA AVE.	Year Built: 1967

PW-Pipe Wrap SO-Spray On HB-Hardboard EN-Encapsulated R-Removed PL-Plaster Application Type: TI-Tank Insulation C-Ceiling F-Flooring DW-Ductwork LEGEND-Condition: G-Good NR-Need Repair Inspection Frequency: B-Per 6 Months Y-Yearly 2Y-Two Years 5Y-Five Years Application Type Area Inspection Frequency Estimated General Condition **Tested Asbestos Location Description** Yes No MAIN FLOOR LEVEL PW Men's Locker Room Pipe Elbows @ Heating Unit G 2 Y no Women's Public Washroom Pipe Elbows PW G 2 Y no PW Women's Locker Room Pipe Elbows G 2 Y no Pool Storage Room Pipe Elbows PW G 2 Y no Pool Staff Room Pipe Elbows PW G 2 Y no G Front Lobby Pipe Elbows PW 2 Y no Pipe Elbows PW G Pool Deck Entrance Above 2 Y no Washroom Doors BASEMENT LEVEL 2 Y **Boiler Room** Pipe Elbows PW G no G 2 Y Workshop Area Tank Insulation on Storage Container ΤI no Pipe Elbows PW G 2 Y Crawlspace no