



ASBESTOS INVENTORY CONTROL

Building Name:	City Hall (Administration Building)
Building Code:	CB-01
Building Address:	510 Main
Inspection Date:	March 26 2008
Inspected By:	Jayson Cyncora & Karl Bauch
Construction Date:	

Legend	Application Type: PW - Pipe Wrap SO - Spray On HB - Hardboard EN - Encapsulated PL - Plaster
	TI - Tank Insulation C - Celing F - Flooring D - Ducting LF - Lose Fill
	Condition: G - Good NR - Needs Repair R - Removed

Asbestos Location	Description	Application Type	Estimated %	Condition	Area Tested	
					Yes	No
-Sub Basement	Pipes	PW		G		X
	Pipe Elbows	PW		G		X
	HWT's	TI		G		X
-Basement	Pipes	PW		G		X
	Pipe Elbows	PW		G		X
-Computer Storage Room	12x12 Floor Tile	F		G		X
-Hallway & V Rooms	9x9 Floor Tile	F		G		X
-Garage Storage Room	9x9 Floor Tile	F		G		X
	Pipe Elbows	PW		G		X
-Fire Doors	Pipe Elbows	R				
-Back Hallway	Pipe Elbows	R				
-Café prep.room	Pipe Elbows	R				
-Garage	Pipe Elbows	PW		G		X
-Central Control Office	Pipe Elbows	PW		G		X
-Staff Luch Room	12x12 Floor Tile	F		G		X
-Elevator Lobby & East Hallway	Ceiling	PL	20-30%	G	X	
-Southeast Crawlspace	Pipe Elbows	PW		G		X
-Main Floor						
	Ceiling Space & asbestos covered beams	SO		G		X
	Possible asbestos floor tile throughout(Covered)	F		G		X
	Return Air Shaft	EN		G		X
	Ceiling Area Above Courtyard Doors	R				
	Ceiling Area Above North Exit Doors-West	R				
	Ceiling Area Above North Exit Doors-East	R				
-West Wing -Restaurant	Ceiling Space & asbestos covered beams	R				

cont.

-Second Floor	Ceiling Space & asbestos covered beams	R				
	Return Air Shaft	EN		G		X
-Third Floor	Ceiling Space & asbestos covered beams	SO		G		X
-Bathroom	9x9 Floor Tile	F		G		X
-Lunch Room	9x9 Floor Tile	F		G		X
Fourth Floor	Central Ceiling Space & Asbestos Covered Beams	SO		G		X
-Hallway	9x9 Floor Tile	F		G		X
	Return Air Shaft	EN		G		X
Fifth Floor	Central Ceiling Space & Asbestos Covered Beams					
-Hallway	9x9 Floor Tile	F		G		X
	Return Air Shaft	EN		G		X
Sixth Floor	Central Ceiling Space & Asbestos Covered Beams	SO		G		X
-Hallway	9x9 Floor Tile	F		G		X
	Return Air Shaft	EN		G		X
Seventh Floor	Pipes	PW		G		X
	Pipe Elbows	PW		G		X
	Duct Insulation	TI		G		X
	Return Air Shaft	EN		G		X
	Perimeter Wall Boards	HB		G		X
	Fan Room at Top of Duct Shafts	HB		G		X
-Hallway	12x12 Floor Tile	F		G		X

Notes: All vinyl floor tile installed before 1990 may contain asbestos and therefore must be treated as an asbestos containing material
Vermiculite insulation may contain pockets of asbestos and therefore all vermiculite must be treated as an asbestos containing material
There may be asbestos containing materials present that were not located during building inspections
Any asbestos related concerns should be directed to Bruce Kazun 794-4409 (alternate Robert Haglund 986-6047)