


COLUMN REPAIR DETAIL

S5.1 N.T.S.




3 JOIST PRESSURE GROUTING REPAIR

S5.1 N.T.S.

1 TYPICAL BEAM PRESSURE GROUTING REPAIR


\$5.1 N.T.S.

INSTALL TEMPORARY BEAM SHORING. SHORING REQUIREMENTS AND SETUP TO BE COORDINATED WITH CONTRACT ADMINISTRATOR




A THRU SLAB REPAIR - SINGLE SPAN

S5.1 | 1" = 1'-0"



MULTIPLE SPAN
THRU SLAB AND JOIST REPLACEMENT


S5.1 | 1" = 1'-0"



MULTIPLE SPAN THRU SLAB REPLACEMENT

WITH OR WITHOUT JOIST REPLACEMENT

S5.1 1" = 1'-0"



D TYPICAL JOIST REPAIR DETAIL

S5.1 1" = 1'-0"

		ntractor shall check & verify all dimensions and ny errors or omissions to the designers.	
			T
			1
			7
		and the second s	\top
		,	\dashv
0	2017-08-15	ISSUED FOR CONSTRUCTION	+
No.	Date	Issue/Revision	+

Certificate of Authorization
Crosier Kilgour & Partners Ltd.
No. 235 Date: 2017-08-15



Consultant

300-275 Carlton Street Winnipeg, Manitoba R3C 5R6 T 204. 943. 7501 F 204. 943. 7507

Crosier Kilgour & Partners Ltd.

CONSULTING STRUCTURAL ENGINEERS

WINNIPEG TRANSIT
NORTH GARAGE
2017 STRUCTURAL REPAIRS
1520 MAIN STREET
WINNIPEG, MANITOBA

heet Title
TYPICAL SECTIONS AND DETAILS

S5.1