

APPENDIX D

2782 ASSINIBOINE AVENUE OUTFALL – INTERNAL INSPECTION PHOTOS



Photo 1: Looking North at Pipe Outlet



Photo 2: Looking D/S at Sta. 2+00 (Upstream Manhole)



Photo 3: Looking U/S from Approx. Sta. 1+90



Photo 4: Looking D/S from Approx. Sta. 1+85



Photo 5: Looking D/S from Approx. Sta. 1+75



Photo 6: Looking D/S from Approx. Sta. 1+40



**Photo 7: Looking D/S from Approx. Sta. 1+35
(Intermediate Manhole)**



**Photo 8: Looking D/S from Approx. Sta. 1+30.7
(Existing Clay Pipe to be Lined)**