

APPENDIX A

SITE PHOTOGRAPHS



Photo 1: Pipe outlet, looking south along lower bank



Photo 2: Pipe outlet, looking southeast



Photo 3: Existing concrete piles (to be removed), looking west towards Red River



Photo 4: Pipe outlet, looking north



Photo 5: Looking upslope (east) from pipe outlet




Photo 6: Looking north along mid-bank at existing deadfall (deadfall to be removed)



Photo 7: Looking south along mid-bank at existing trees and deadfall (deadfall to be removed)



Photo 8: Looking south along mid-bank



Photo 9: Looking north along mid-bank



Photo 10: Looking downslope (west) at mid-bank along pipe alignment



Photo 11: Looking east from mid-bank along pipe alignment



Photo 12: Looking northeast from mid-bank



Photo 13: Looking southeast from mid-bank



Photo 14: Looking south from upper bank



Photo 15: Upstream chamber (looking south)



Photo 16: Looking east towards St. Mary's Road from chamber (site access route)



Photo 17: Looking west from chamber/upper bank towards the Red River



Photo 18: Looking north from chamber at upper bank