


GENERAL NOTES:

1. REPAIR DECK CONCRETE DELAMINATIONS THAT EXTEND BEYOND THE TYPICAL DECK CONCRETE REMOVAL DEPTH WITH TYPE 1 CONCRETE REPAIR METHOD SHOWN ON SHEET 92.
2. INSTALL ANODES TO EXPOSED EXISTING REINFORCING STEEL IN ACCORDANCE WITH TYPE 1 REPAIR DETAIL ON SHEET 92.
3. * INDICATES DIMENSION TAKEN ALONG SKEW, PARALLEL TO EXPANSION JOINT.
4. FIELD CUT D162SSS AND D1623SS TO FIT AT OVERHANG.

SUPR. U/G STRUCTURES

NOTE:
LOCATION OF UNDERGROUND STRUCTURES AS SHOWN ARE BASED ON THE BEST INFORMATION AVAILABLE BUT NO GUARANTEE IS GIVEN THAT ALL EXISTING UTILITIES ARE SHOWN OR THAT THE GIVEN LOCATIONS ARE EXACT. CONFIRMATION OF EXISTENCE AND EXACT LOCATION OF ALL SERVICES MUST BE OBTAINED FROM THE INDIVIDUAL UTILITIES BEFORE PROCEEDING WITH CONSTRUCTION.

B.M.	76-006	Tblt. in W. wall of Conc. parking garage of No. 77 University Cres. E. of Pembina Hwy., 0.5 m N. of S.W. cor. of garage, & 2.8 m below recreation deck.		
ELEV	234.128 m			
1	ISSUED FOR ADDENDUM 2	25/03/24	BE	
0	ISSUED FOR TENDER	25/02/28	BE	
No.	REVISIONS	YY/MM/DD	BY	



PROFESSIONAL'S SEAL

ORIGINAL DRAWING
REV No. 0

SEALED BY:
A.G. GILARSKI
2025-02-28

CONSULTANT FILE NAME
132500075-STR-DECK04.d

