



Corporate Finance Department  
Materials Management Division

## **ADDENDUM NO. 1 to TENDER NO. 646-2003**

### **2003 OUTFALL MAINTENANCE PROGRAM OUTFALL REPAIRS AND RIVERBANK STABILITY IMPROVEMENTS**

ISSUED: January 15, 2003  
BY: Roy Houston, P.Eng.  
TELEPHONE NO. (204) 896-1209

#### **URGENT**

**PLEASE FORWARD THIS DOCUMENT TO WHOEVER  
IS IN POSSESSION OF THE TENDER PACKAGE**

**THIS ADDENDUM SHALL BE INCORPORATED  
INTO THE TENDER PACKAGE AND SHALL  
FORM A PART OF THE CONTRACT  
DOCUMENTS**

---

**Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Tender Package, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 10 of Form A: Tender may render your Tender Submission non-responsive.**

#### **PART A – TENDER SUBMISSION**

Replace Form B: Prices with Form B(R1):Prices

#### **PART E – SPECIFICATIONS**

Replace E1.2 with:

E1.2 The following Drawings are applicable to the Work:

Drawing No.	Drawing
LD-2983	Site Plan Showing Location of Riverbank Improvements
LD-2984	Sections A, B and C
LD-2985	Rue Dumoulin Outfall (RR-58)
LD-2986	Radcliffe Road Outfall (RR-10)
LD-2987	Shenfield Road Outfall (AS-25)
LD-2988	Debris Grate Details
LD-2989	Hand Rail Details

Revise the heading in E8.7.1 to read:

E8.7.1 Rockfill Riprap

#### **PART E – DRAWINGS**

Replace complete drawing set with revised Rev.1 drawings and new cover sheet.

**FORM B (R1): PRICES**  
(See B9) Addendum 1  
**2003 OUTFALL MAINTENANCE PROGRAM**  
**OUTFALL REPAIRS AND RIVERBANK STABILITY IMPROVEMENTS**

## UNIT PRICES

ITEM NO.	DESCRIPTION	SPEC. REF.	UNIT	APPROX. QUANTITY	UNIT PRICE	AMOUNT
<b>Radcliffe Road Outfall (RR-10)</b>						
1	Site Development and Restoration	E6	lump sum	1		
2	Supply and Install Hand Rails	E11	lump sum	1		
3	Supply and Install 1219mm Dia. Debris Grate	E11	each	1		
4	Supply and Install Rockfill Riprap	E8	tonnes	400		
5	Sodding Using Imported Topsoil	CW3510-R6	sq. metre	150		
<b>Shenfield Road Outfall (AS-25)</b>						
<b>(Pipe Installed by Open Cut Methods)</b>						
1	Site Development and Restoration	E6	lump sum	1		
2	Clearing and Grubbing	E10	lump sum	1		
3	Supply and install 450mm CMP pipe	E11	linear meter	10		
4	Supply and Install Rockfill Riprap	E8	tonnes	160		
5	Sodding Using Imported Topsoil	CW3510-R6	sq. metre	100		
<b>Rue Dumoulin Outfall (RR-58)</b>						
<b>(Rockfill Shear Key and Outfall Pipe Relacement)</b>						
1	Site Development and Restoration	E6	lump sum	1		
2	Remove Existing 1050mm Dia. CMP and Replace with new 2.8mm 1050 CMP pipe	E11	linear meter	38		
3	Supply and Install 1050mm Dia. Debris Grate	E11	each	1		
4	Supply and Install Hand Rails	E11	lump sum	1		
5	Geotextile	E7	sq. metre	600		
6	Rockfill trench Shear Key					
	a) Excavation	E9	cu. metre	1900		
	b) Rockfill	E9	tonnes	4200		
7	Supply and Install Rockfill Riprap	E8	tonnes	820		
8	Sodding Using Imported Topsoil	CW3510-R6	sq. metre	300		
<b>TOTAL BID PRICE (GST extra) (in figures):</b> _____						
(in words) _____						