NOTES:

- 1. CONTRACTOR TO VERIFY LIMITS OF SEWER REPAIRS PRIOR TO EXCAVATION BY MEANS OF VIDEO INSPECTION.
- 2. CONTRACTOR TO PROVIDE VIDEO INSPECTION OF SEWER SERVICES WITHIN LIMITS OF REPAIR OR RENEWAL IN PRESENCE OF CONTRACT ADMINISTRATOR TO DETERMINE IF SERVICE RENEWAL IS REQUIRED.

SEWER JUNCTION INFORMATION WITHIN PROPOSED SEWER REPAIR

DISTANCE FROM MH (ID #22306) AT KINGSWAY

7 . 1	11110	O 117	\ I		
88.7	S	_	WEST	UNKNOWN LOCATION	_
89.3	S	-	EAST	UNKNOWN LOCATION	
93.1	S	_	EAST	UNKNOWN LOCATION	
938	S	_	WFST	LINKNOWN LOCATION	Ξ

SEWER JUNCTION INFORMATION WITHIN PROPOSED SEWER REPAIR

DISTANCE FROM 2nd MH (ID #576)
N OF KINGSWAY

0.8	S	_	WEST	UNKNOWN	LOCATION
48.0	S	_	WEST	UNKNOWN	LOCATION
48.7	S	_	EAST	UNKNOWN	LOCATION

INFORMATION FROM SEWER VIDEO INSPECTION

