

ASBESTOS INVENTORY CONTROL

BUILDING SERVICES DIVISION

BUILDING NAME: NORTH END CENTENNIAL POOL	INSPECTION DATE: April 26/2005
BUILDING CODE: PI-11	INSPECTED BY: Karl Bauch & Jayson Cyncora
BUILDING ADDRESS: 90 SINCLAIR ST	Year Built: 1969

PW-Pipe Wrap SO-Spray On HB-Hardboard EN-Encapsulated R-Removed PL-Plaster Application Type: TI-Tank Insulation C-Ceiling F-Flooring DW-Ductwork LEGEND-Condition: G-Good NR-Need Repair Inspection Frequency: B-Per 6 Months Y-Yearly 2Y-Two Years 5Y-Five Years Application Type Area Inspection Frequency Estimated General Condition Tested **Asbestos Location Description** Yes No MEZZ, FLOOR LEVEL PW Spectator Seating Area / West 2 Y Pipe Elbows, Spray On Ceiling R no Balcony SO 0 % R 2 Y yes MAIN FLOOR LEVEL Family Change Room Pipe Elbows PW G 2 Y no Deck Storage Room Pipe Elbows (No elbows this location.) PW G 2 Y no Staff Room Reception Pipe Elbows PW G 2 Y no Janitors Room off Men's and PW Pipe Elbows G 2 Y no Women's change rooms Pipe Elbows PW Women's Locker Room G 2 Y no SO 0 % R 2 Y **Pool Ceiling** Spray On yes Pool Supervisors Office Pipe Elbows SO G 2 Y no Roof Drain PW G 2 Y Men's Public washroom no Roof Drain PW G 2 Y Entrance into senior centre no BASEMENT LEVEL Pipe Elbows **PW** G 2 Y Crawlspace no Workshop / Utility Room Pipe Elbows PW G 2 Y no Main Circulation Pump Room Pipe Elbows PW G 2 Y no Chemical Storage Room Pipe Elbows PW G 2 Y no Pipe Elbows **Boiler Room** PW < 50% G 2 Y yes Pipe Elbows West Mechanical Room PW G 2 Y no PW G 2 Y South Side Tunnel Room Pipe Elbows no