

## Water and Waste Department • Service des eaux et des déchets

Environmental Standards Division • Division des Normes Environnementales

August 30, 2017

Our File No: 040-17-08-29-00 040-17-08-15-00 040-17-08-35-00

Manitoba Sustainable Development Environmental Compliance and Enforcement Branch 1007 Century Street Winnipeg, MB R3H 04W

Attention: Mr. Don Labossiere, Regional Director

## RE: JULY 2017 MONITORING REPORTS FOR THE WEST END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2669 E RR, THE NORTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 RRR AND THE SOUTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2716 RR

The July 2017 Monitoring Reports for Licence No. 2669 E RR issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC), Licence No. 2684 RRR issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC) and Licence No. 2716 RR issued for the City of Winnipeg South End Water Pollution Control Centre (SEWPCC) are attached. This information is provided under compulsion of law in accordance with the requirements under the Environment Act Licences #2669 E RR, #2684 RRR and #2716 RR.

Please note the following respecting the report for Licence #2669 E RR:

- 1. The TSS results met the licence limit in July.
- 2. There was no cBOD5 result on July 27 due to a QC failure; the cBOD5 results met the licence limit in July.
- 3. The ammonia results met the licence limit in July.
- 4. The total phosphorus and total nitrogen thirty-day rolling averages met the licence limits in July.
- 5. There were no fecal coliform and *E. coli* results on July 11 due to contract lab error; the monthly geometric means for fecal coliform and *E. coli* met the licence limits in July.

Please note the following respecting the report for Licence #2684 RRR:

- 1. There was no 24-hour composite sample on July 11 due to sampler malfunction.
- 2. The TSS result exceeded the licence limit on three days in July due to intermittent high flows and by-pass events. The total daily flow exceeded 380 MLD on July 12, therefore in accordance with the licence, the TSS value for this day is not considered to be an exceedence.
- 3. There were no BOD5 and cBOD5 results on July 27 due to a QC failure; the BOD5 results met the licence limit in July.
- 4. The monthly geometric means for fecal coliform and *E. coli* met the licence limits in July.



2230 Main Street • 2230, Rue Main • Winnipeg • Manitoba R2V 4T8 tel/tél. (204) 986-4684 • fax/téléc. (204) 339-2147 • www.winnipeg.ca

Please note the following respecting the report for Licence #2716 RR:

- 1. The TSS results met the licence limit in July.
- 2. There were no BOD5 and cBOD5 results on July 27 due to a QC failure; the cBOD5 results met the licence limit in July.
- 3. The monthly geometric mean for *E. coli* met the licence limit in July.

Please let me know of any concerns or questions respecting this submission. I can be reached by telephone at 204-986-8359 or by email at <u>rgrosselle@winnipeg.ca</u>.

Yours sincerely,

Original signed by R. Grosselle:

R. Grosselle Manager of Environmental Standards

NC

Enclosures

cc: M. L. Geer CPA, CA (e-mail) C. Carroll, P. Eng (e-mail)