

PIER 3 SIDE ELEVATION
SCALE 1:50



PIER 3 END ELEVATION
SCALE 1:50



SOUTH ABUTMENT PLAN VIEW
SCALE 1:50



SECTION A 7 7
SCALE 1:50
SOUTH ABUTMENT CROSS-SECTIONAL VIEW

PHOTO OF ABUTMENT BETWEEN GIRDERS TO BE JACKED
(LOOKING SOUTH)

METRIC
ALL MEASUREMENTS IN MILLIMETRES
UNLESS OTHERWISE STATED

NOTE:
These design documents are prepared solely for the use by the party with whom the design professional has entered into a contract and there are no representations of any kind made by the design professional to any party with whom the design professional has not entered into a contract.

ENGINEERS GEOSCIENTISTS MANITOBA
Certificate of Authorization
WSP Canada Inc.
No. 5750

LOCATIONS APPROVED
UNDERGROUND STRUCTURES

SIGNED BY: _____ DATE _____
SUPV U/G STRUCTURES

LOCATION OF UNDERGROUND STRUCTURES AS SHOWN ARE BASED ON THE BEST INFORMATION AVAILABLE BUT NO GUARANTEE IS GIVEN THAT ALL EXISTING UTILITIES ARE SHOWN OR THAT THE GIVEN LOCATIONS ARE EXACT CONFIRMATION OF EXISTANCE AND EXACT LOCATION OF ALL SERVICES MUST BE OBTAINED FROM THE INDIVIDUAL UTILITIES BEFORE PROCEEDING

G.B.M.
ELEV.

No.	REVISIONS	DATE	BY
0	ISSUED FOR TENDER	25.05.13	MLW

WSP Canada Inc.
1600 Buffalo Place
Winnipeg MB R3T 6B8
T+ 1 204-943-3178
www.wsp.com

DESIGNED BY	GN	CHECKED BY	EH
DRAWN BY	CP	APPROVED BY	MLW
HOR. SCALE	AS NOTED	RELEASED FOR CONSTRUCTION	M. MADY, Ph.D., P.ENG. CITY OF WINNIPEG
VERTICAL	AS NOTED		
DATE	25.05.13	DATE	

ENGINEER'S SEAL
PROVINCE OF MANITOBA
MADEU
Member
35354
REGISTERED PROFESSIONAL ENGINEER
2025-05-14

CONSULTANT PROJECT No.
CA0047563.3090

Winnipeg
THE CITY OF WINNIPEG
PUBLIC WORKS DEPARTMENT
ENGINEERING DIVISION

MIDTOWN BRIDGE MAINTENANCE
REPAIRS AND RELATED WORKS

PIER 3 AND SOUTH ABUTMENT
JACKING LOCATIONS

CITY DRAWING NUMBER
B114-25-07
BID OPPORTUNITY NUMBER
329-2025
SHEET 7 OF 9
REV 0

A1 SIZE (594 mm x 841 mm)

Plotted: May 12, 2025 at 5:23:52 PM | Last saved by: paterson
File: C:\Users\paterson\DC\ACCDocs\WSP Canada projects (AMER)\CA0047563.3090 - Midtown Bridge - C2A\Project Files\01-Bridges\03-Working Drawings\CA0047563-3090 Midtown Bridge Repairs - south abutment.dwg | Layout: 7 Pier 3 and South Abutment Jacking Locations