



139-2005 ADDENDUM 1

2005 BRIDGE MAINTENANCE - MISCELLANEOUS EMBANKMENT SLOPE FAILURE REPAIRS

URGENT

**PLEASE FORWARD THIS DOCUMENT TO
WHOEVER IS IN POSSESSION OF THE BID
OPPORTUNITY**

ISSUED: September 7, 2005
BY: Bob Wiebe, P. Eng.
TELEPHONE NO. (204) 453-2301

**THIS ADDENDUM SHALL BE INCORPORATED
INTO THE BID OPPORTUNITY AND SHALL
FORM A PART OF THE CONTRACT
DOCUMENTS**

Template Version: A20050506

Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid Opportunity, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 10 of Form A: Bid may render your Bid non-responsive.

PART D – SUPPLEMENTAL CONDITIONS

- Add:
- D15. LAYOUT OF THE WORK**
 - D15.1 The Contract Administrator will provide the basic centrelines and limits of the Works.
 - D15.2 The Contractor shall be responsible for the true and proper laying out of the Work and for the correctness of the location, levels, dimensions, and alignment of all aspects of the Work. He shall provide all required instruments and competent personnel for performing all layouts.
 - D15.3 The Contract Administrator shall be notified at least one (1) Working Day prior to any Work being commenced in order to have the option to check and review all elevations and layouts at his discretion.
 - D15.4 The Contractor shall carefully protect and preserve all benchmarks, stakes, and other items of the basic data supplied by the Contract Administrator. Any such benchmarks or stakes removed or destroyed by the Contractor, without the consent of the Contract Administrator, shall be replaced by the Contract Administrator at the expense of the Contractor.