NOTES:

1. CONTRACTOR TO VERIFY LIMITS OF SEWER REPAIRS PRIOR TO EXCAVATION BY MEANS OF VIDEO INSPECTION.

2. CONTRACTOR TO PROVIDE VIDEO INSPECTION OF SEWER SERVICES WITHIN LIMITS OF REPAIR OR RENEWAL IN PRESENCE OF CONTRACT ADMINISTRATOR TO DETERMINE IF SERVICE RENEWAL IS REQUIRED.

MEASUREMENT TO REPAIR FROM REFERENCE MH SHOWN THUS... $\frac{1}{100}$

SEWER SERVICE INFORMATION

ADDRESS P DIST JUNCTION TIE SIZE

129 LINDSAY ST

11.0 S 1ST MH N ACADEMY RD RESIDENTIAL 130/132 LINDSAY ST

RESIDENTIAL DOUBLE 4.0 S 1ST MH N ACADEMY RD



SEWER JUNCTION INFORMATION WITHIN PROPOSED SEWER REPAIR

DISTANCE FROM 1st MH (ID #22554) N OF ACADEMY ROAD

WEST S -UNKNOWN LOCATION

SHEET 9 OF 15

05661

CITY DRAWING NUMBER

INFORMATION FROM SEWER VIDEO INSPECTION

AND SEWER REPAIRS

LINDSAY STREET


2ND MH S OF WELLINGTON CRESENT TO MH AT ACADEMY ROAD

APPROVED

RELEASED FOR CONSTRUCTION

1:500

2005 10 14 DATE



METRIC

WHOLE NUMBERS INDICATE MILLIMETRES

DECIMALIZED NUMBERS INDICATE METRES