Template Version: eC2022 03 23 - C BCivil

APPENDIX B - TABLE E11.2 : SITE SPECIFIC MANHOLE CONDITIONS AND REPAIR REQUIREMENTS

STREET_NAME LOCATION_DETAILS MANHOLE_ID REPAIRS REQUIRED

1	Cornish Avenue	MH at East Gate	MH20012417	Grout under manhole frame. Replace manhole cover
2	Walnut Street	MH at Preston Avenue	MH20013884	Repace top 0.3m of brick risers below frame (750 diameter)
3	Walnut Street	MH at Purcell Avenue	MH20013863	Replace top 0.9m of precast concrete risers below frame (750 diameter)
4	Cornish Avenue	MH at Sherbrook Street	MH20012366	Replace 0.8m of precast concrete risers below frame (750 diameter). Replace manhole cover
5	St Marys Road	MH at Coniston Street	MH50003543	Grout under manhole frame. Replace manhole cover
6	St Marys Road	1st MH S of Coniston Street	MH50003560	Replace top 1.9m of precast concrete risers below frame (750 diameter)
7	St Marys Road	2nd MH S of Coniston Street	MH50003561	Replace top 0.35m of precast concrete risers below frame (750 diameter)
8	Lyndale Drive	MH at Lloyd Street	MH50003548	Replace manhole frame and cover
9	St Marys Road	MH at Lyndale Drive	MH50003549	Replace top 1.3m of precast concrete risers below frame