

May 27, 2019

REVISION INFORMATION DIVISION 4 – SURFACE WORKS STANDARD CONSTRUCTION SPECIFICATIONS

REVISION SUMMARY

Approved Products for Surface Works

The following are the revisions to the approved products for surface works that was updated on May 2, 2019:

Section 1: Bonding Agents/Dowel Adhesive

The section was revised to separate dowel adhesives from bonding agents.

The following products are no longer approved:

Duralcrete Gel

Duralcrete Resin

Duralith Gel

Duralpatch Gel

Acrl-Stix

Chemroc 800

The following products are approved for use as dowel adhesives:

Dural 452 Gel

Dural Fast Set Gel

Sikadur-31

Anchorfix 3001

Latex R is approved for use as a bonding agent.

Section 2: Hot Poured Joint Sealer

The following products are no longer approved:

Crafco Roadsaver 231

Bemac Beram 195 LM

Asphalt Rubber Plus Type 2 is approved.

ENGINEERING DIVISION



Section 6: Separation/Filtration Geotextile Fabric

The section title was changed from Drainage/Separation Fabric to Separation/Filtration Geotextile Fabric.

The following products are no longer approved:

Skaps GT 180

BW 180

Propex 861

Armtec 250W

Carthange Mills FX-86HS

Propex Geotex 801

GSE NW8

Thrace-Linq 180EX

The following products are approved:

Mirafi 180N

Nilex Nonwoven 4553

Section 7: Separation Geotextile Fabric

The section title was changed from Separation/Reinforcement Fabric to Separation Geotextile Fabric.

The following products are no longer approved:

Armtec 855

Layfield LP315

BW 315

Propex 315ST

CC315

Thrace-Linq GTF300

FX-66

Winfab 315W

The following products are approved:

Mirafi 600X

Nilex Woven 2006

SX130T

TE-W315



Section 8: Geogrid

The following products are no longer approved:

Tenax LBO 302 SAMP
Checkmate 2525PP
Griffen GBX2000
Checkmate 2020PP
Layfield E'Grid RX 1200
Maccaferri Macgrid EG25S
Titan TE-BX2

The following products are approved:

Mirafi BXG120 Tensar BX SQ2020 Tensar BX SQ3030 Tensar BX TYPE 2F Terrafix BX2500 SX2020 SX3030

Section 9: Pavement Repair Fabric / Fiberglass Geogrid

This is a new section for asphalt pavement reinforcement using fiberglass geogrid.

The following products are approved:

GlasGrid 8501 GlasGrid 8502 Titan TE-FGP10

Section 10: Drainage Pipe

The following products are no longer approved:

Boss 2000 Solflomax

The following products are approved:

ADS - N12 ST IB Pipe - 320 kPa ADS - N12 WT IB Pipe - 320 kPa



Section 11: Culvert Pipe

The following products are no longer approved:
Challenger 2000
Armtec Boss 2000

Section 12: Detectable Warning Surface Tile

ADA Solutions Cast in Place 24"x48" 2448IDPAV2 is no longer approved.

Armor-Tile Wayfinding Tile (6"x48") is approved for use as a wayfinding tile to indicate primary travel routes.

Section 13: Repair Materials

This is a new section for partial-depth repairs or patching wide cracks and joints.

Mastic One™ is approved for use as a hot-poured repair product for filling wide cracks and joints more than 37.5 mm wide.

Planitop 18 is approved for use as a concrete partial-depth repair product for high early strength patching and generally can be used during the summer when temperatures are in the range of 8°C to 30°C and traffic must be quickly reinstated.

SikaTop 122 Plus is approved for use as a concrete partial-depth repair product for normal strength patching and generally can be used during the summer when temperatures are above 10°C and traffic must be reinstated within three days.

SikaSet 45 is approved for use as a concrete partial-depth repair product for high early strength patching and generally can be used during spring and late fall when temperatures are in the range of 2°C to 8°C and traffic must be quickly reinstated.