

## Water and Waste Department • Service des eaux et des déchets

October 31, 2005

Our Files: 040-17-08-27-00

040-17-08-15-00

Mr. Mike Van Den Bosch, P.Eng. Environmental Assessment and Licensing Branch Manitoba Conservation Suite 160 – 123 Main Street Winnipeg, Manitoba R3C 1A5

Dear Mr. Van Den Bosch:

RE: SEPTEMBER 2005 MONITORING REPORTS FOR THE WEST END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2669 E R AND THE NORTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 R

Attached please find the September 2005 Monitoring Reports for Licence No. 2669 E R issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC) and Licence No. 2684 R issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC).

Please note the following respecting the report for Licence #2669 E R:

 On September 10 there were no results for temperature because the result was not recorded.

Please note the following respecting the report for Licence #2684 R:

- 1. On September 4, 5 and 6 the sample pump failed and a sample was not taken for analysis. The problem was corrected by September 7.
- 2. On September 8, 9, 11 and 12 there was a failure in the TKN analysis related to sample digestion. The total nitrogen results were therefore not reported.
- 3. On September 15, 16 and 18 you will note that the raw sewage flow values on the attached monitoring report are bolded. This is as explained in the note with detail having been provided in the August report.

Please let me know of any concerns or questions respecting this submission. I may be reached at the below address, by telephone at 986-4807 or by email at kkjartanson@winnipeg.ca.

Thanks for your ongoing cooperation and understanding in this matter.

Yours sincerely,

Original signed by:

K.J.T. Kjartanson, P.Eng. Manager of Environmental Standards

KJTK:kk:pr Attachments

c: Cliff Lee, P.Eng., Assistant Director of Red River Region B.D. MacBride, P.Eng. W.J. Borlase, P.Eng.

M.A. Shkolny, P.Eng.