



GLULAM BEAM REPAIRS
FROM GL "2" to GL "10"
AT END BEARING CONDITIONS
(ALONG GL "A" & GL "B")
(18 GLULAM END REPAIRS)



ARENA ROOF FRAMING

Scale: 1/32" = 1'-0"

SK-2

Gulam Beam Repairs
St Vital Arena
580 St. Annes Road
Winnipeg, MB R2M 3G4



GC ENGINEERING LTD.
675 ELM ST.
WINNIPEG MB R3M 3N8
PH 793-3948 FAX 487-4616
EMAIL CALGRAY@MTS.NET