The City of Winnipeg	ASBESTOS INVENTORY CONTROL	Appendix A
Bid Opportunity No. 339-20	10	
Addition & Renovation of Winakwa Community Centre		2010-05-13

Appendix A

Contents: Asbestos Inventory Control sheet

By: City of Winnipeg, dated January 26, 2009 1 page attached



Planning, Property and Development Department Building Services Division 100 Main Street • Winnipeg • MB R3C 1A4

ASBESTOS INVENTORY CONTROL

Building Name:	Winakwa CC	
Building Code:	CC-106	
Building Address:	980 Winakwa Rd	
Inspection Date:	January 26,2009	
Inspected By:	karl Bauch & Nick DeMelo	
Construction Date:	1960, Garage 1999	

Application Type: Legend Condition:	PW - Pipe Wrap SO - Spray On HB - Hardboard EN - Encapsulated PL - Plaster TI - Tank Insulation C - Ceiling F - Flooring D - Ducting LF - Loose Fill G - Good NR - Needs Repair R - Removed					
Asbestos Location	Description Description	Application Type	Estimated %	Condition	Area Tested	
					Yes	No
Boardroom	9x9 Floor Tile	F		G		X
Block Wall Insulation In Original Portion Of Bldg	Walls Contain Vermiculite Insulation	LF		G		X

Notes: All vinyl floor tile installed before 1990 may contain asbestos and therefore must be treated as an asbestos containing material

Vermiculite insulation may contain pockets of asbestos and therefore all vermiculite must be treated as an asbestos containing material

There may be asbestos containing materials present that were not located during building inspections

Any asbestos related concerns should be directed to Bruce Kazun 794-4409 (alternate Robert Haglund 986-6047)