

APPENDIX B

SITE PHOTOS



Photo 1 – Lower Bank – Looking West



Photo 2 – Lower Bank – Looking East



Photo 3 – Lower Bank Riprap at Outfall



Photo 4 – Mid bank – TH10-06 shown



Photo 5 – Lower Bank – Looking East




Photo 6 – Upper Bank – Looking East



Photo 7 – Lower Bank – Looking West



Photo 8 – Lower Bank – Looking East



Photo 9 – Test holes TH10-03 (front) and TH10-05 (back)



Photo 10 – Lower Bank – Looking West



Photo 11 – Upper Bank – Looking East



Photo 12 – Upper Bank – Looking West



Photo 13 – Top of Bank – Looking East



Photo 14 – Lower Bank – Looking West



Photo 15 – Lower Bank – Looking East



Photo 16 – Upper Bank – Looking East