

APPENDIX — PHOTOS



FIGURE — 1 — Existing Dover Machine



FIGURE — 2 — Existing cable terminations



FIGURE — 3 — Existing Car Top Station



FIGURE — 4 — Existing Car Station



FIGURE — 5 — Location and width of existing Car Station



FIGURE — 6 — Height of Existing Car Station



FIGURE — 7 — Fire Alarm Annunciator Panel in North Entrance Lobby



FIGURE — 8 — Existing Car Position Indicator



FIGURE — 9 — Typical Existing Hall Push Button fixture



FIGURE — 10 — Existing Hall Push Button fixture at Main floor