

APPENDIX B
2018 INTERNAL INSPECTION PHOTOS



Archibald Outfall – Outlet at Seine River (February 2018)



Approx. Sta. 0+86 (Looking Upstream)



Approx. Sta. 0+88 (Looking Upstream)



Approx. Sta. 1+00 (Looking Upstream from intermediate manhole location)



Approx. Sta. 1+07 (Looking Upstream)



Approx. Sta. 1+45 (Looking Upstream)



Approx. Sta. 1+45 (Looking Downstream)



Approx. Sta. 1+58 (Looking Downstream towards bend location)



Approx. Sta. 1+64 (Looking Downstream towards bend location)



Approx. Sta. 1+63.5 (Looking Upstream towards Mission chamber)



Approx. Sta. 1+66 (Looking up at inside of Mission Chamber)