

APPENDIX 'B'

SITE PHOTOS

**Charleswood-Assiniboine Feeder Main River Crossing Rehabilitation,
Tender 310-2025 - Appendix B – Site Photos**



Figure 1: South Side of Assiniboine River Facing North



Figure 2: Access Path on South Side of Assiniboine River

**Charleswood-Assiniboine Feeder Main River Crossing Rehabilitation,
Tender 310-2025 - Appendix B – Site Photos**



Figure 3: West End of Access Path on South Side of Assiniboine River



Figure 4: View of Access Road Looking North at Intersection of Berkley St and Southboine Dr

**Charleswood-Assiniboine Feeder Main River Crossing Rehabilitation,
Tender 310-2025 - Appendix B – Site Photos**



Figure 5: South Valve Chamber Internal View



Figure 6: South Valve Chamber Internal View

**Charleswood-Assiniboine Feeder Main River Crossing Rehabilitation,
Tender 310-2025 - Appendix B – Site Photos**



Figure 7: South Valve Chamber Internal View



Figure 8: South Valve Chamber Internal View

**Charleswood-Assiniboine Feeder Main River Crossing Rehabilitation,
Tender 310-2025 - Appendix B – Site Photos**



Figure 9: View of Easement on North Side of Assiniboine River Looking South



Figure 10: View of Easement on North Side of Assiniboine River Looking South at River

**Charleswood-Assiniboine Feeder Main River Crossing Rehabilitation,
Tender 310-2025 - Appendix B – Site Photos**



Figure 11: View of Easement on North Side of Assiniboine River Looking North



Figure 12: View of Easement on North Side of Assiniboine River Looking North at Assiniboine Av

**Charleswood-Assiniboine Feeder Main River Crossing Rehabilitation,
Tender 310-2025 - Appendix B – Site Photos**



Figure 13: North Valve Chamber Internal View



Figure 14: North Valve Chamber Internal View

**Charleswood-Assiniboine Feeder Main River Crossing Rehabilitation,
Tender 310-2025 - Appendix B – Site Photos**



Figure 15: North Valve Chamber Internal View



Figure 16: North Valve Chamber Internal View

**Charleswood-Assiniboine Feeder Main River Crossing Rehabilitation,
Tender 310-2025 - Appendix B – Site Photos**



Figure 17: North Valve Chamber Internal View



Figure 18: Existing Victaulic Coupler Style (typ.)

**Charleswood-Assiniboine Feeder Main River Crossing Rehabilitation,
Tender 310-2025 - Appendix B – Site Photos**




Figure 19: North Valve Chamber Existing Valve with Broken Operator



Figure 20: Existing valve Condition (typ.)